AECOM
250 Apollo Drive
Chelmsford, MA 01824
www.aecom.com

978 905 2100 tel
978 905 2101 fax

Technical Memorandum

To	Ridgefield WPCA	Page	1 of 9
CC	C. Fisher, J. O'Brien, M. Burke, J. Pennell		
Subject	Town of Ridgefield, CT Phase 2 Wastewater Facilities Plan Technical Memorandum No. 4 – House to House Inspections		
From	Jon Pearson/Alberto Angles		
Date	December 21, 2016		

INTRODUCTION

This Technical Memorandum summarizes the results of the house to house inspections conducted under the Phase 2 Wastewater Facilities Plan. The inspection program goal was to conduct internal inspections of buildings in Sewer District 1 to identify sources of inflow such as sump pumps connected to the sewer system.

BACKGROUND

There have been previous discussions and speculation that some of the observed inflow in the collection system during periods of wet weather may be the result of sump pumps connected to the sanitary sewer system. During the smoke testing conducted in 2013, 5 sump pumps connected to the sanitary sewer system were identified. This provided evidence of the presence of sump pumps in Sewer District 1. As a result, the Town undertook a program of house to house inspections of the buildings within Sewer District 1 to locate sump pumps connected to the sanitary sewer system.

DATA COLLECTION

Description of House to House Inspections

House to house inspections were performed to investigate and identify inflow sources and potential inflow sources in buildings within Sewer District 1. House to house inspections were conducted by EST Associates, Inc. between April 2016 and July 2016 generally between the hours of 8:00 AM and 8:00 PM. During each inspection, both the basement and exterior of the building were inspected for possible sources in inflow. Buildings with sump pumps connected to the sanitary sewer were the primary concern while conducting inspections.

House to House Inspection Procedures

House to house inspections were performed to identify sump pumps connected to the sanitary sewer system and other sources of inflow. Other sources of inflow include rain leaders and basement,

driveway, or yard drains, etc. that are connected directly to the sewer system. All connections observed during the house to house inspections are considered private connections as they include yard, floor, window well, and/or driveway drains, downspouts and flat roof drains, and sump pumps which are all located on private property.

Prior to the house to house inspections, press releases regarding the planned inspection program were issued, and information was posted on the Town's website to increase awareness of the program and garner support. Mailings were sent to all sewer users in Sewer District 1 announcing the program, and then each property received a door hanger 24 to 72 hours prior to conducting a building inspection. House to house inspections were attempted in all buildings within Sewer District 1, totaling 1,206 buildings, including 1,057 residential buildings and 149 commercial, industrial, or municipal buildings. If the first attempt to conduct an internal inspection was unsuccessful, two additional attempts were subsequently made to conduct the inspection. If a building could not be accessed, an external visual inspection, from public property, was conducted and the observations were recorded on the inspection form.

ANALYSIS

Buildings Inspected

There are a total of 1,206 buildings including 1,057 residential buildings and 149 commercial/industrial/municipal buildings in Sewer District 1. Internal inspections were completed in 996 of the 1,206 buildings in Sewer District 1. The success rate of accessing buildings was approximately 82.6%, with approximately 0.3% of property owners refusing EST Associates entry to perform an internal inspection and approximately 0.3% of buildings were found to be vacant. The remaining, 203 buildings, did not respond to repeated attempts to make contact and gain entry. It should be noted that some of the 203 buildings where contact/access was not gained may have intentionally avoided responding due to a known sump pump connected to the sewer system. A breakdown of the house to house inspection information is presented in Tables 1, 2, and 3. See Attachment A for the individual inspection reports prepared by EST Associates.

TABLE 1. SUMMARY OF BUILDING TYPE

Total Buildings	Residential	Commercial
1,206	1,057	149

TABLE 2. BUILDING INSPECTIONS ATTEMPTED AND COMPLETED

Internal Building Inspections Completed	No Access After 3rd Attempt	Refused	Vacant
996	203	3	4

TABLE 3. PERCENTAGE OF BUILDING INSPECTIONS ATTEMPTED AND COMPLETED

Buildings Inspected	No Access after 3rd Attempt	Refused	Vacant
82.6%	16.8%	0.3%	0.3%

A list of properties which did not respond after a third attempt to conduct an inspection is included as Attachment B. A list of properties which refused house to house inspections is included as Attachment C.

Interior Observations

Inside the buildings, inspectors looked for and made note of any sump pumps, floor drains, downspouts or foundation drain pipes coming in from outside, and loose or missing cleanout caps. It was noted if any of these potential sources could be confirmed to connect directly to the building's sanitary sewer system.

Sump Pumps. A total of 348 sump pumps were observed during the house to house inspections. 254 of the 996 buildings internally inspected (approximately 25.5%) had a sump pump. A breakdown of the sump pump information obtained during the house to house inspections is presented in Tables 4 and 5. It should be noted that some buildings have more than one sump pump discharging to more than one location.

TABLE 4. OBSERVED SUMP PUMP CONNECTIONS

Sump Pump to Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
102	187	18	41

TABLE 5. OBSERVED SUMP PUMP CONNECTIONS PERCENT OF INSPECTED BUILDINGS

Sump Pump to Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
10.2%	18.8%	1.8%	4.1%

As noted above, 102 sump pumps were observed to discharge to the sanitary sewer and 187 to the ground surface. 18 sump pumps were observed to discharge other locations, like downspouts or driveway drains. The discharge location of 41 sump pumps could not be determined in 38 of the 996 buildings internally inspected, due to finished basements or other obstructions which obscured the discharge piping.

Figure 1 presents the approximate locations of properties with sump pumps connected to the sanitary sewer system in Sewer District 1, identified through house to house inspections. A list of the properties with sump pumps identified during the house to house inspections is presented in Attachment D.

House to house inspections of properties within Sewer District 1

SUBAREA 5

OUTPOST INN POND

SOUTH STREET WWTF

SUBAREA 6

GREAT SWAMP

SUBAREA 3

SUBAREA 4

SUBAREA 2

SUBAREA 1

Drawn:	BC	11/28/2016
Approved:	AA	11/28/2016

Map Location



Legend

- WWTF
- Pump Station
- Manholes
- Municipal Sewer
- Private Sewer
- Roads
- Force Main
- Streams
- Parcel
- Sewer District 1 Boundary
- Sump Pumps Connected to Sanitary Sewer
- Swamps
- Waterbodies

N

0 500 1,000 Feet

FIGURE 1: HOUSE TO HOUSE INSPECTIONS
SUMP PUMPS CONNECTED TO SANITARY SEWER
TECHNICAL MEMORANDUM NO. 4
DECEMBER 2016

RIDGEFIELD, CT

PHASE II WASTEWATER FACILITIES PLAN

G:\Projects\MUNI\60299267RID\Maps\Figure 1 - HomeInspectionsDec2016.mxd

Sump pumps can have a wide range of pumping capacities depending on the size of the unit installed. There are various size pumps available, with the size selected depending on the size of the basement area and the extent of leakage present. In addition to the capacity of the unit, the flow from a sump pump discharged into the collection system is also a function of the number of hours each day that the sump pump is in operation. Typically, a sump pump is installed in a pump chamber (sump) recessed into the basement floor, with piping under the basement floor collecting groundwater and conveying it to the sump. The operation of the pump is controlled by a float in the sump basin which turns the pump on when the water depth exceeds the float setting. Each pump will run for a period sufficient to drain the sump and collection piping. This operating period is highly variable depending on the amount of water present, which typically varies with the groundwater level and precipitation. To illustrate this variation, Table 6 presents the calculated flow in gallons per day for several pump capacities and daily operating periods. As indicated in the table, a 10 gallon per minute (gpm) pump running for 4 hours per day will contribute 2,400 gallons per day (gpd) to the sewer system, while a 60 gpm pump running continuously will contribute 86,400 gpd to the sewer system.

TABLE 6. FLOW IN GALLONS PER DAY PER SUMP PUMP FOR VARIOUS OPERATING HOURS AND PUMP CAPACITIES

Pump Capacity (gpm)	Operating Hours per Day			
	4	8	16	24
10	2,400	4,800	9,600	14,400
20	4,800	9,600	19,200	28,800
30	7,200	14,400	28,800	43,200
40	9,600	19,200	38,400	57,600
50	12,000	24,000	48,000	72,000
60	14,400	28,800	57,600	86,400

Table 7 presents the same analysis as presented in Table 6, except that instead of the flow from one sump pump as shown in Table 6, the flows in Table 7 are what could be discharged from the 102 sump pumps identified to be connected to the sewer system in Sewer District 1. The estimated flows discharged by the 102 sump pumps connected to the sewer system in Sewer District 1 could range from a low of 244,800 gpd to a high of 8,812,800 gpd. Studies of sump pumps conducted in other communities have concluded that while sump pumps can contribute a large instantaneous peak flow rate, as indicated in Tables 6 and 7, the volume discharged over extended periods are lower due to intermittent pump operation as groundwater levels decline. Assuming an average flow per pump of 20 gpm that runs for 8 hours during a storm event to estimate the total contribution of 102 sump pumps discharging to the sanitary sewer system, the potential inflow to Sewer District 1 is estimated at approximately 980,000 gpd during peak flow conditions.

TABLE 7. FLOW IN GALLONS PER DAY FOR 102 SUMP PUMPS FOR VARIOUS OPERATING HOURS AND PUMP CAPACITIES

Pump Capacity (gpm)	Operating Hours per Day			
	4	8	16	24
10	244,800	489,600	979,200	1,468,800
20	489,600	979,200	1,958,400	2,937,600
30	734,400	1,468,800	2,937,600	4,406,400
40	979,200	1,958,400	3,916,800	5,875,200
50	1,224,000	2,448,000	4,896,000	7,344,000
60	1,468,800	2,937,600	5,875,200	8,812,800

Private Interior Drains and Other Structures. Table 9 presents a breakdown of private interior drains and other structures observed during the house to house inspections.

TABLE 9. SUMMARY OF PRIVATE INTERIOR DRAINS AND OTHER STRUCTURES

Loose/Open Cleanout	Floor Drain	Sump Pit Present
3	153	349

Loose or open cleanouts and floor drains can be a source of inflow if they are used to drain groundwater or stormwater into the sanitary sewer system. None of the responses from the 3 properties with loose or open cleanouts reported basement flooding. Therefore, none of the loose or open cleanouts are believed to be a source of significant inflow to the sanitary sewer system.

Of the 153 floor drains observed, the discharge location of 97 floor drains could not be confirmed. 10 of the 97 properties that have floor drains whose discharge location could not be confirmed, noted that they experience flooding or backups. A list of the 10 properties with floor drains, whose discharge locations could not be confirmed, and who noted that they experience flooding or backups identified during house to house inspections is presented in Attachment E.

The presence of a sump pit in a building basement would imply that there is a sump pump. As noted previously, 348 sump pumps were observed during the house to house inspections. One additional sump pit is located at the Casagmo Condominium complex, Building 10, Olcott Way, and is hard piped to the sanitary sewer system. Additionally, this property has 2 sump pumps connected to the sanitary sewer system, and is noted in Appendix D.

Exterior Observations

Outside of the buildings, the inspector looked for and made note of any flat roofs, yard drains, patio drains, driveway, sidewalk or stairwell drains, roof downspouts leading underground, and window well drains. It was noted if any of these potential sources connect directly to the building's sanitary sewer system.

Downspouts. 888 of the 1,206 total buildings externally inspected (approximately 73.6%) were found to have downspouts which enter the ground. Downspouts, also sometimes referred to as roof leaders, rain leaders, or roof drains, which enter the ground are potential sources of inflow as they may be connected to the sanitary sewer system. Unconfirmed, potential sources of inflow are called suspect sources.

These and other suspect sources of inflow to the sewer system were also identified during smoke testing conducted under the Phase 1 Wastewater Facilities Plan in 2013. Subsequently, under the Phase 2 Wastewater Facilities Plan, dyed water testing and tracing of suspect sources was conducted to determine if these and other suspect sources are connected to the sanitary sewer system. The dyed water testing confirmed that 2 of the properties (21 King Lane and 353 Main Street) identified as having downspouts which enter the ground had 17 downspouts connected to the sanitary sewer system. The Town is working with the property owners to implement the design and construction of capping and redirection of these sources. None of the remaining buildings with downspouts which enter the ground are believed to be connected to the sanitary sewer system. The results of the smoke testing, and dyed water testing and tracing were presented in separate Technical Memoranda.

Private Exterior Drains and Flat Roofs . Similar to downspouts, exterior drainage structures observed on private property during inspections were recorded. Exterior drainage structures observed include flat roofs, yard, driveway, stairwell, or window well drains which may have an internal drainage system connected to the sanitary sewer system. The private drainage structures that were identified during house to house inspections are summarized in Table 8.

TABLE 8. SUMMARY OF PRIVATE EXTERIOR DRAINS AND FLAT ROOFS

Flat Roof	Yard Drain	Driveway Drain	Stairwell Drain	Window Well Drain
66	194	165	32	34

3 of the 194 yard drains noted above (located at 35 Copps Hill Road, 353 Main Street, and 21 King Lane) were confirmed to be connected to the sanitary sewer during the smoke testing conducted in 2013. The Town worked with the property owners of 35 Copps Hill Road and 353 Main Street, and those inflow sources have been corrected. Like downspouts, flat roofs and exterior drains were also noted as suspect sources during the smoke testing conducted. Dyed water testing and tracing follow up field work was conducted to determine if the suspect sources identified are connected to the sanitary sewer system. Dyed water tracing confirmed an indirect cross connection between the yard drain and at 21 King Lane and the service connection at 207 Main Street. None of the remaining private exterior drains and flat roofs identified during the house to house inspections are believed to be connected to the sanitary sewer system. As noted above, the results of the smoke testing, and dyed water testing and tracing were presented in separate Technical Memoranda.

Other Private Exterior Structures. An unsealed exterior holding tank and a defective exterior cleanout, which are susceptible to inflow, were observed during house to house inspections. The estimated inflow from these other private exterior structures is 5,000 gpd and 2,000 gpd respectively. A list of the other private exterior structures is included in Attachment F.

REHABILITATION ALTERNATIVES

There are three typical options for redirecting the flow from sump pumps:

- Redirect flow to a drywell.
- Redirect flow to an outlet at existing ground level (overland flow).
- Redirect flow to connect to an existing drainage system.

For general guidance, typical details showing various sump pump redirection alternatives are included in Attachment G.

Each sump pump redirection requires an individual evaluation to identify a recommended redirection method. Some sump pumps may be easily disconnected from the sewer and the discharge of the clean water redirected onto the ground surface in the yard. When determining if this is a viable option, it is important that there is adequate surface area in the yard to permit discharge without creating drainage problems on the Owner's property or adjacent properties. Similarly, when determining if connection to an existing drainage system is a viable option, it is important that the drainage system has adequate capacity.

SUMMARY

Based on the results of the house to house inspections in Sewer District 1, 102 sump pumps, an unsealed exterior holding tank, and a defective exterior cleanout have been identified as contributing an estimated 987,000 gpd of inflow to the sewer system during peak flow conditions. To eliminate or reduce inflow to the sanitary sewer from these sources, the following actions would be required:

- Continue with the ongoing program requiring private property owners to redirect flow from sump pumps connected to the sanitary sewer (Attachment D).
- Initiate a program requiring private property owners to repair or replace leaking or damaged cleanouts and other structures connected to the sanitary sewer system to prevent inflow from entering (Attachment F).

In addition to the above, the Town should consider inspection of the following buildings to verify that there are no sources of inflow at these locations:

- The 203 buildings where contact/access was not gained (Attachment B)
- The 3 buildings where property owners refused access (Attachment C)
- The 38 buildings with 41 sump pumps whose discharge location cannot be determined (Attachment D)
- The 10 buildings which have floor drains whose discharge location cannot be determined, and have reported experiencing flooding or backups (Attachment E)

The Town should also consider inspection of the 10 buildings with floor drains whose discharge could not be confirmed that experience flooding or backups. Building inspections could be accomplished by Town staff prior to a real estate transaction. Or, building inspections may be performed by the building inspector whenever he or she needs to visit a building for issuance of a building permit. The

Town's Sewer Ordinance provides the authority to conduct these inspections. With this approach, building inspections may be performed on an ongoing basis without a formal house to house inspection program. To implement this approach, the WPCA and the Building Department will need to collaborate to implement and administer this inspection program.

All sources identified during the house to house building inspections are located on private property. The WPCA has determined that costs to rehabilitate private inflow sources will be borne by the owner of the private property as these are illegal connections to the sanitary sewer system. Therefore, no rehabilitation costs for sump pump or other private inflow source remediation have been estimated.

As previously noted, the house to house inspections have been conducted under the Phase 2 Wastewater Facilities Plan to further locate sources of inflow from sources such as sump pumps connected to the sewer system. Other activities to locate sources inflow and infiltration (I/I) conducted under the Facilities Plan include television inspection of selected mainline sewers and lateral service connections, manhole inspections, and dyed water testing and tracing. The rehabilitation alternatives presented herein along with those arising from the other activities to locate I/I will be incorporated into an Inflow Reduction Plan in the Phase 2 Wastewater Facilities Plan Report that will present an approach for the Town to reduce collection system I/I.

ATTACHMENT A

EST Associates, 2016 Ridgefield Building Inspection Report

ATTACHMENT B

Properties Which Did Not Respond After Third Attempt to Conduct Inspection

Attachment B
Properties Which Did Not Respond After Third Attempt to Conduct Inspection

Subarea	No.	Address
1	19	Ascot Way
1	9	Branchville Rd
1	19	Creamery Ln
1	29	East Ridge Rd
1	56	East Ridge Rd
1	2	Main St
1	8	Main St
1	55	Main St
1	156	Main St
1	200	Main St
1	236	Main St
1	250	Main St
1	43	Rockwell Rd
1	59	Rockwell Rd
1	61	Rockwell Rd
1	16	Rowland Ln
1	19	Rowland Ln
1	25	Rowland Ln
1	26	Rowland Ln
1	349	Wilton Rd East
2	22	Catoonah Street
2	25	Catoonah Street
2	47	Catoonah Street
2	51	Catoonah Street
2	33B	Catoonah Street
2	34B	Catoonah Street
2	37R	Catoonah Street
2	39A	Catoonah Street
2	44B	Catoonah Street
2	36	Catoonah Street Unit 16
2	36	Catoonah Street Unit B10
2	36	Catoonah Street Unit B7
2	8	Griffith Ln
2	16	Griffith Ln
2	30	Griffith Ln
2	36	Griffith Ln
2	37	Griffith Ln
2	111	High Ridge Ave
2	123	High Ridge Ave
2	125	High Ridge Ave
2	143	High Ridge Ave
2	146	High Ridge Ave
2	148	High Ridge Ave
2	154	High Ridge Ave
2	159	High Ridge Ave
2	63	High Ridge Avenue

Attachment B
Properties Which Did Not Respond After Third Attempt to Conduct Inspection

Subarea	No.	Address
2	44	King Lane
2	21	King Ln
2	139	Main St
2	145	Main St
2	267	Main St
2	305	Main St
2	321	Main St
2	323	Main St
2	325	Main St
2	2	Peaceable St
2	38	Peaceable St
2	42	Peaceable St
2	56	Shadow Ln
2	61	Shadow Ln
3	2	Abbott Ave
3	3	Abbott Ave
3	13	Abbott Ave
3	21	Abbott Ave
3	27	Abbott Ave
3	31	Abbott Ave
3	29 A	Abbott Ave
3	29B	Abbott Ave
3	8	Barry Ave
3	14	Barry Ave
3	23	Barry Ave
3	25	Barry Ave
3	32	Barry Ave
3	33	Barry Ave
3	34	Barry Ave
3	41	Barry Ave
3	46	Barry Ave
3	6	Berry Ave
3	21	Bryon Ave
3	22	Bryon Ave
3	26	Bryon Ave
3	30	Bryon Ave
3	7	Fairview Ave
3	32	Fairview Ave
3	36	Fairview Ave
3	27	Gilbert Street
3	32	Gilbert Street
3	43	Gilbert Street
3	55	Gilbert Street
3	14	Greenfield Ave
3	15	Greenfield Ave
3	190	High Ridge Ave

Attachment B
Properties Which Did Not Respond After Third Attempt to Conduct Inspection

Subarea	No.	Address
3	192	High Ridge Ave
3	201	High Ridge Ave
3	218	High Ridge Ave
3	25	Kellogg Street
3	5	Mulberry Street
3	7	Mulberry Street
3	14	Mulberry Street
3	28	Mulberry Street
3	8	Nutmeg Court
3	16	Nutmeg Court
3	19	Nutmeg Court
3	20	Overlook Drive
3	7	Ramapoo Hill Road
3	6	Ramapoo Road
3	21	Ramapoo Road
3	34	Ramapoo Road
3	91	Ramapoo Road
3	99	Ramapoo Road
3	7	Victor Drive
4	33	Bailey Ave
4	107	East Ridge St
4	109	East Ridge St
4	500	Main St
4	520	Main St Unit 18
4	520	Main Street Unit 12
4	520	Main Street Unit 6
4	12	Prospect Ridge Unit 12
4	19	Prospect Ridge Unit 2
4	19	Prospect Ridge Unit 20
4	19	Prospect Ridge Unit 23
4	19	Prospect Ridge Unit 3
4	19	Prospect Ridge Unit 32
4	19	Prospect Ridge Unit 4
4	19	Prospect Ridge Unit 43
4	19	Prospect Ridge Unit 45
4	19	Prospect Ridge Unit 51
4	19	Prospect Ridge Unit 52
4	19	Prospect Ridge Unit 6
4	19	Prospect Ridge Unit 63
4	19	Prospect Ridge Unit 7
4	28	Prospect St
4	58	Prospect St
4	120	Prospect St Unit 15
4	120	Prospect St Unit 21
4	120	Prospect St Unit 22
4	120	Prospect St Unit 36

Attachment B
Properties Which Did Not Respond After Third Attempt to Conduct Inspection

Subarea	No.	Address
4	120	Prospect St Unit 4
4	120	Prospect St Unit 5
4	120	Prospect St Unit 50
4	120	Prospect St Unit 51
4	120	Prospect St Unit 53
4	120	Prospect St Unit 54
4	120	Prospect St Unit 58
4	120	Prospect St Unit 6
4	120	Prospect St Unit 60
4	120	Prospect St Unit 61
4	85	Prospect St Unit B
4	59	Prospect St Unit C
4	85	Prospect St Unit C
4	85	Prospect St Unit D
4	85	Prospect St Unit E
4	59	Prospect St Unit J
4	120	Prospect St Until 30
4	13	Sunset Ln
4	17	Sunset Ln
4	19	Sunset Ln
4	23	Sunset Ln
4	47	Sunset Ln
5	2	Cops Hill Rd
5	159	Danbury Road
5	Building 14	Fox Hill - Blackberry Lane 1-4, 6-8 Cottonwood Lane
5	4	Island Hill Ave
5	4	Lafayette Ave
5	6	Lafayette Ave
5	7	Lafayette Ave
5	14	Lafayette Ave
5	16	Lafayette Ave
5	8	Mountain Ave
5	12	Mountain View Ave
5	16	Mountain View Ave
5	5	North Salem Rd
5	17	North Salem Rd
5	24	North St
5	32	North St
5	40	North St
5	42	North St
5	48	North St
5	59	North St
5	10	Roberts Lane
5	16	Roberts Lane
5	3	Rochambeau Ave
5	14	Rochambeau Ave

Attachment B

Properties Which Did Not Respond After Third Attempt to Conduct Inspection

Subarea	No.	Address
5	18	Rochambeau Ave
6	55	Danbury Rd
6	75	Danbury Rd Building A
6	75	Danbury Rd Building B
6	57	Danbury Rd Building C
6	6	Danbury Road
6	66	Grove St Unit 3
6	66	Grove St Unit 4
6	66	Grove St Unit 9
6	66	Grove St Until 11
6	66	Grove St Until 20
6	6	Island Hill Ave
6	13	Lawson Lane
6	14	Lawson Lane
6	19	Lawson Lane
6	607	Main St
6	616	Main St
6	115	Olcott Way
6	2	Silver Birch Lane

ATTACHMENT C

House to House Inspection Refusal Table

Attachment C
House to House Inspection Refusals

Subarea	No.	Address
2	87	High Ridge Road
4	120	Prospect St Unit 11
6	1	Island Hill Avenue

ATTACHMENT D

Sump Pump Table

Attachment D
Sump Pump Table

Subarea	No.	Address	Discharge Location			
			Sump Pump To Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
1	5	Ascot Way			1	
1	15	Ascot Way		1		
1	9	Branchville Rd		1		
1	95	Branchville Rd		1		
1	21	Branchville Road		1		
1	24	Branchville Road		1		
1	50	Branchville Road	1	1		
1	52	Branchville road		1		
1	5	East Ridge Road		1		
1	62	East Ridge Road		1		
1	17	East Ridge Street		1		
1	48	East Ridge Street		1		
1	10	Governor St Veterans park school	1	1		
1	28	High Ridge Ave			1	
1	23	High Ridge Avenue				1
1	7	Ivy hill		1		
1	9	Ivy Hill Road		1		
1	59	Main St	1	1		
1	310	Main St		1		
1	32	Main Street				1
1	49	Main Street		1		
1	57	Main Street		1		
1	85	Main Street				1
1	120	prospect Ridge Rd				1
1	39	Rockwell Rd		1		
1	41	Rockwell Road		1		

Attachment D
Sump Pump Table

Subarea	No.	Address	Discharge Location			
			Sump Pump To Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
1	49	Rockwell Road		1		
1	20	Rowland Lane		1		
1	23	Rowland Lane		1		
1	25	Rowland Ln		1		
1	16	Shadow Lane		1		
1	21	West Lane		1		
1	31	West Lane			1	
1	43	West Lane		1		
1	45	West Lane		1		
1	51	West Lane		1		
1	380	Wilton Rd West		1		
1	381	Wilton Rd West		1		
1	388	Wilton Rd West		1		
1	371	Wilton Road East		1		
1	371	Wilton Road West				1
1	378	Wilton Road West				1
2	35	Catoonah St	2	1		
2	23	Catoonah St Unit 1		1		
2	23	Catoonah St Unit 2		1		
2	6	Catoonah Street	1			
2	27	Catoonah Street	2			1
2	29	Catoonah Street	1	1		
2	33	Catoonah Street				1
2	41	Catoonah Street				1
2	42	Catoonah Street		1		
2	47	Catoonah Street		1		

Attachment D
Sump Pump Table

Subarea	No.	Address	Discharge Location			
			Sump Pump To Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
2	31A	Catoonah Street	1	1		
2	36	Catoonah Street Unit 12				1
2	36	Catoonah Street Unit 13		1		
2	31	Griffith		1		
2	15	Griffith Lane				1
2	27	Griffith Lane		2		
2	34	Griffith Ln				2
2	62	High Ridge Ave		1		
2	108	High Ridge Ave	1	1		
2	112	High Ridge Ave		1		
2	42	High Ridge Avenue		1	1	
2	74	High Ridge Avenue	1			1
2	121	High Ridge Avenue		1		
2	141	High Ridge Avenue		1		
2	55	High Ridge Avenue Guest house				1
2	55	High Ridge Rd		1		
2	110	High Ridge Rd		1		
2	77	High Ridge Road	2		1	1
2	106	High Ridge Road				2
2	139	High Ridge Road				2
2	77	High Ridge Road Pool House				1
2	162	Highridge Ave		1		
2	1	Jackson Court		1		
2	7	Jackson Court		1		
2	8	Jackson Court		2		
2	455	Main				1

Attachment D
Sump Pump Table

Subarea	No.	Address	Discharge Location			
			Sump Pump To Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
2	145	Main St		1		
2	293	Main St			1	
2	127	Main Street	1	1		
2	149	Main Street		1		
2	275	Main Street		1		
2	385	Main Street		1		
2	409	Main Street	1			
2	451	Main Street	1	1		
2	453	Main Street				1
2	467	Main Street	1	1		
2	509	Main Street	1			
2	127	Main Street Cottage		1		
2	207	Main Street main Church building				1
2	19	Peacable Street	1	1		
2	20	Peacable Street		1		
2	46	Peacable Street	1	1		
2	49	Shadow Lane		1		
2	57	Shadow Lane		1		
2	10	West Lane		1		
2	20	West Lane		1		
2	22	West Lane (Main house)		1		
2	22	West Lane Cottage Units 401 to 406	3			
3	4	Abbott Ave		1		
3	17	Abbott Ave	1	1		
3	23	Abbott Avenue		1		
3	25	Abbott Avenue	1			

Attachment D
Sump Pump Table

Subarea	No.	Address	Discharge Location			
			Sump Pump To Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
3	30	Barry Ave				1
3	4	Barry Avenue		1		
3	24	Barry Avenue		2		
3	52	Barry Avenue		1		
3	53	Barry Avenue		2		
3	36	Bryon Ave		1		
3	42	Bryon Ave		1		
3	6	Bryon Avenue		1		
3	7	Bryon Avenue	1	1		
3	12	Bryon Avenue	2			
3	18	Bryon Avenue		1		
3	20	Bryon Avenue	1			
3	31	Bryon Avenue		1		
3	34	Bryon Avenue		1		
3	14	Fairview Ave		1		
3	32	Fairview Ave			1	
3	18	Fairview Avenue		1		
3	16	Farm Hill Road		1		
3	26	Farm Hill Road	1	1		
3	40	Gilbert Street	1	1		
3	7	Greenfield Ave		1		
3	6	Greenfield Avenue		1		
3	10	Greenfield Avenue		1		
3	11	Greenfield Avenue		1		
3	17	Greenfield Avenue		1		
3	19	Greenfield Avenue		1		

Attachment D
Sump Pump Table

Subarea	No.	Address	Discharge Location			
			Sump Pump To Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
3	191	High Ridge Ave		1		
3	183	High Ridge Avenue		1	2	
3	196	High Ridge Avenue		1		
3	197	Highridge Ave		1		
3	32	Overlook Dr				1
3	90	Overlook Dr		1		
3	31	Overlook Drive		1		
3	19	Ramapoo Hill Road		1		
3	40	Ramapoo Rd				1
3	162	Ramapoo Rd		1		
3	15	Ramapoo Road				1
3	55	Ramapoo Road		1		
3	80	Ramapoo Road		2		
3	86	Ramapoo Road	1			
3	126	Ramapoo Road		1		
3	2	Victor Drive		1		
3	3	Victor Drive		1		
3	9	Victor Drive		1		
3	15	Victor Drive		1		
4	16	Bailey Ave				1
4	30	Bailey Ave	1	1		
4	107	East Ridge St		1		
4	106	East Ridge Street	1	1		
4	111	East Ridge Street		1		
4	115	East Ridge Street		1		
4	90	East Ridge Street (RF Playhouse, Chef's Warehouse)		1		

Attachment D
Sump Pump Table

Subarea	No.	Address	Discharge Location			
			Sump Pump To Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
4	12	Grove St apartment front				1
4	14	Grove Street				1
4	30	Grove Street	1	1		
4	95	Ivy Hill Road		1		
4	374	Main St	1			
4	400	Main Street				1
4	488	Main Street		1		
4	490	Main Street		1		
4	51	Prospect Ridge Road	1	1		
4	19	Prospect Ridge Road #34		1		
4	19	Prospect Ridge Road #35		1		
4	55	Prospect St	1	1		
4	57	Prospect St	1	1		
4	16	Prospect Street	1			
4	54	Prospect Street				1
4	60	Prospect Street				1
4	120	Prospect Street Unit 66		1		
4	59	Prospect Street Unit E		1		
4	43	Prospect Street Units 1-4		1		
4	43	Prospect Street Units 5-9		1		
4	27	Sunset		1		
4	4	Sunset Lane				1
4	5	Sunset Lane		1		
4	15	Sunset Lane	1			
4	18	Sunset lane	2	1		
5	15	Danbury Rd		1		

Attachment D
Sump Pump Table

Subarea	No.	Address	Discharge Location			
			Sump Pump To Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
5	23	Danbury Rd	1	1		
5	98	Danbury Road		1		
5	Building 22	Fox Hill - 1,2,3 Orange Lane, 1,2,6,7,11 Quince Court				1
5	Building 1	Fox Hill - 1,2,3,4 Nettle Lane, Units 1,2,3,4,5 Meadow Lane	2			
5	Building 21	Fox Hill - Orange Lane Units 4-8, Quince Court Units 8-10	3			
5	Building 36	Fox Hill - Units 1,3,5,7 Edelweiss Lane, Units 1,2,3,4 Forest Lane Ridgefield CT	4			
5	Building 34	Fox Hill - Units 1,4 Honeysuckle Lane, Units 2,3,6 Juniper Lane		3		
5	Building 37	Fox Hill - Units 1-4 Daisy Lane, Units 2,4,6,8 Edelweiss Lane	1			
5	Building 6	Fox Hill - Units 1-4 Frog Hollow, Units 2,3,6,7 Grape Lane	1	1		
5	Building 35	Fox Hill - Units 1-4 Greenbrier, Units 3,5 Honeysuckle Lane	2			
5	Building 19	Fox Hill - Units 1-4 Sandlewood La, Units 1,4,5,7 Outpost Lane	3			
5	Building 12	Fox Hill - Units 1-5 Apple Lane, Units 4,6,7 Blueberry Lane			4	
5	Building 33	Fox Hill - Units 1-5 Lime Lane, Units 1,4,5,7 Juniper Lane		3		
5	Building 20	Fox Hill - Units 1-5 Raspberry Lane, Units 3-5 Quince Court	2			
5	Building 18	Fox Hill - Units 2,3,6,8 Outpost Lane, Units 1-4 Vine Lane		2	2	
5	Building 5	Fox Hill - Units 2,4,5,8 Grape Lane, Units 1,3,5,7 Hollyberry Lane	1	1		
5	Building 7	Fox Hill - Units 5-8 Island Path, Units 9-12 Elderberry Lane Ridgefield CT				1
5	Building 24	Fox Hill - Units 8,10,12 Sandlewood Lane, Units 11,13,16,17 Outpost Lane			3	
5	Building 17	Fox Hill - Units 9,10 Outpost Lane, Units 1-3 Teaberry Lane, Units 1-3 Winterberry Lane	3			
5	Building 11	Fox Hill- 2,5,7,8 Cypress Lane, 1-5 Blueberry Lane Ridgefield CT		2		
5	10	Hillsdale Avenue	2			
5	11	Hillsdale Avenue		1		
5	6	Juneberry Lane	1			
5	12	Lafayette Ave		1		
5	2	Lafayette Avenue		2		
5	11	Lafayette Avenue				1

Attachment D
Sump Pump Table

Subarea	No.	Address	Discharge Location			
			Sump Pump To Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
5	10	Mountain Ave		1		
5	28	North Street		1		
5	44	North Street		1		
5	57	North Street		1		
5	65	North Street		1		
5	21	Roberts Lane		1		
5	24	Roberts Lane		1		
5	27	Roberts Lane				1
5	5	Rochambeau Ave		1		
5	6	Rochambeau Ave		1		
5	15	Rochambeau Ave		1		
5	Building 10	Units 1,3,4,6 Cypress Avenue, 5,6,7,8 Dogberry Lane		1		
6	Building 1	Casagmo - Carpenter Close		1		
6	Building 2	Casagmo - Cook Close	1			
6	Building 3	Casagmo - Cook Close	1	1		
6	Building 6	Casagmo - Keeler Close	1			
6	Building 14	Casagmo - Lawson Lane		1		
6	Building 15	Casagmo - Lawson Lane	2	1		
6	Building 16	Casagmo - Lawson Lane		3		
6	Building 17	Casagmo - Lawson Lane	3			
6	Building 18	Casagmo - Lawson Lane	1	1		
6	Building 10	Casagmo - Olcott Way	2			
6	Building 22	Casagmo - Olcott Way	2			
6	Building 23	Casagmo - Olcott Way	1	1		
6	Building 24	Casagmo - Olcott Way	2			1
6	Building 25	Casagmo - Olcott Way	1			

Attachment D
Sump Pump Table

Subarea	No.	Address	Discharge Location			
			Sump Pump To Sanitary Sewer	Sump Pump to Ground Surface	Sump Pump to Other	Sump Pump to Unknown
6	Building 7	Casagmo - Olcott Way		1		
6	Building 8	Casagmo - Olcott Way	1			
6	Building 11	Casagmo - Olcott Way	2	1		
6	Building 9	Casagmo - Olcott Way	1			
6	Building 19	Casagmo - Quincy Close	1			
6	Building 20	Casagmo - Quincy Close	3			
6	Building 13	Casagmo - Unit 11 Lawson Lane	1			
6	Building 5	Casagmo - Unit 12 Keeler Close	1			
6	5	Danbury Road		1		
6	12	Danbury Road - Ridgefield Power Equipment	1	1		
6	10	Lawson Lane	1			
6	22	Lawson Lane		1		
6	23	Lawson Lane		1		
6	24	Lawson Lane	1			
6	543	Main St		1		
6	547	Main St	1	1		
6	549	Main Street		1		
6	613	Main Street				1
6	621	Main Street	1			
6	381-383	Main Street		1		
Totals			**102**	**187**	**18**	**41**

ATTACHMENT E

Buildings with Floor Drains That Experience Flooding or Backups
Whose Discharge Locations Could Not Be Determined

Attachment E
Buildings with Floor Drains That Experience Flooding or Backups
Whose Discharge Locations Could Not Be Determined

Subarea	No.	Address
1	30	Main Street
2	127	Main Street
4	38	Prospect St
4	490	Main Street
4	120	Prospect St Unit 67
5	13	Rochambeau Ave
6	86	Danbury Rd
N/A	700	North Salem Road
5	125	Danbury Road unit 6
5	130	Danbury Road

ATTACHMENT F

Other Private Exterior Structures Table

Attachment F
Other Private Exterior Structures

Subarea	No.	Address	Comment
4	9	Grove Street	Cleanout in drive on right side of building at ground level has a hole that is exposed to stormwater runoff.
5	6	Farmingville Road	Many openings in holding tank where clean water appears to enter and is pumped to sewer.

ATTACHMENT G

Typical Details of Sump Pump Redirection Alternatives



NOTES:

1. DETAIL SHOWS TYPICAL OPTIONS FOR REDIRECTION OF SUMP PUMP AFTER DISCONNECTING FROM SANITARY SEWER. OTHER OPTIONS, NOT SHOWN, MAY ALSO BE CONSIDERED.
2. ENSURE REDIRECTION IS PERFORMED WITHOUT CREATING DRAINAGE PROBLEMS ON OWNER'S PROPERTY OR ADJACENT PROPERTIES.

TOWN OF RIDGEFIELD, CONNECTICUT

PHASE 2 WASTEWATER FACILITIES PLAN
TYPICAL DETAILS FOR
SUMP PUMP REMOVAL

TYPICAL PLAN OF SUMP PUMP REDIRECTION OPTIONS

SCALE: NTS | DATE: 11/28/16 | AECOM



SECTION

NOTE:

PIPE DIMENSIONS SHOWN MAY VARY.

TOWN OF RIDGEFIELD, CONNECTICUT

PHASE 2 WASTEWATER FACILITIES PLAN
TYPICAL DETAILS FOR
SUMP PUMP REMOVAL

TYPICAL SECTION OF SUMP PUMP REDIRECTION OPTIONS

SCALE: NTS | DATE: 11/28/16 | AECOM

2016 RIDGEFIELD

BUILDING INSPECTION REPORT

Prepared for:

AECOM
250 Apollo Drive
Chelmsford, MA 01824

Prepared by:

EST Associates, Inc.
51 Fremont Street
Needham, MA 02494

Subarea 1

TABLE OF CONTENTS

Subarea	No.	Street
1	17	Ascot Way
1	5	Ascot Way
1	6	Ascot Way
1	15	Ascot Way
1	18	Ascot Way
1	19	Ascot Way
1	9	Branchville Rd
1	58	Branchville Rd
1	95	Branchville Rd
1	21	Branchville Road
1	24	Branchville Road
1	25	Branchville Road
1	28	Branchville Road
1	33	Branchville Road
1	48	Branchville Road
1	50	Branchville Road
1	52	Branchville road
1	54	Branchville Road
1	56	Branchville Road
1	60	Branchville Road
1	64	Branchville Road
1	29	Branchville Road Ridgefield CT
1	19	Creamery Ln
1	21	Creamery Ln
1	10	East Ridge Rd
1	29	East Ridge Rd
1	35	East Ridge Rd
1	56	East Ridge Rd
1	5	East Ridge Road
1	7	East Ridge Road
1	15	East Ridge Road
1	17	East Ridge Road
1	27	East Ridge Road
1	44	East Ridge Road
1	48	East Ridge Road
1	62	East Ridge Road
1	43	East Ridge Street
1	76	East Ridge Street
1	86	Govenor St
1	76	governor St
1	84	Governor Street
1	28	High Ridge Ave
1	32	High Ridge Ave
1	23	High Ridge Avenue
1	5	High Ridge Road

Subarea	No.	Street
1	15	Highridge Ave
1	7	Ivy hill
1	9	Ivy Hill Road
1	6	Juneberry Lane
1	2	Main St
1	8	Main St
1	17	Main St
1	19	Main St
1	54	Main St
1	55	Main St
1	59	Main St
1	94	Main St
1	156	Main St
1	200	Main St
1	236	Main St
1	250	Main St
1	304	main st
1	310	Main St
1	378	Main St
1	1	Main Street
1	7	Main Street
1	12	Main Street
1	30	Main Street
1	32	Main Street
1	34	Main Street
1	35	Main Street
1	49	Main Street
1	51	Main Street
1	53	Main Street
1	57	Main Street
1	85	Main Street
1	88	Main Street
1	99	Main Street
1	103	Main Street
1	104	Main Street
1	114	Main Street
1	152	Main Street
1	154	Main Street
1	155	Main Street
1	158	Main Street
1	160	Main Street
1	164	Main Street
1	188	Main Street
1	212	Main Street
1	260	Main Street
1	316	Main Street
1	258	Main Street - Administrative Offi
1	258	Main Street - Museum

Subarea	No.	Street
1	152	Main Street Barn/ Garage
1	152	Main Street Carriage House
1	132	Main Street Garden House
1	132	Main Street Main House
1	34	Market
1	14	Market Street
1	19	Market Street
1	24	Market Street
1	1	Parley Lane
1	3	Parley Lane
1	78	Prospect Ridge
1	120	prospect Ridge Rd
1	74	Prospect Ridge Road
1	132	R Main Street Cottage
1	15	Rockwell Rd
1	39	Rockwell Rd
1	43	Rockwell Rd
1	59	Rockwell Rd
1	61	Rockwell Rd
1	63	Rockwell Rd
1	5	Rockwell Road
1	27	Rockwell Road
1	30	Rockwell Road
1	41	Rockwell Road
1	45	Rockwell Road
1	47	Rockwell Road
1	49	Rockwell Road
1	57	Rockwell Road
1	13	Rowland Lane
1	14	Rowland Lane
1	20	Rowland Lane
1	23	Rowland Lane
1	16	Rowland Ln
1	19	Rowland Ln
1	25	Rowland Ln
1	26	Rowland Ln
1	16	Shadow Lane
1	21	West Lane
1	27	West Lane
1	29	West Lane
1	31	West Lane
1	39	West Lane
1	43	West Lane
1	45	West Lane
1	48	West Lane
1	51	West Lane
1	55	West Lane
1	57	West Lane

Subarea	No.	Street
1	58	West Lane
1	63	West Lane
1	27R	West Lane
1	39A	West Lane
1	349	Wilton Rd East
1	378	Wilton Rd East
1	410	Wilton Rd W
1	367	Wilton Rd West
1	380	Wilton Rd West
1	381	Wilton Rd West
1	388	Wilton Rd West
1	398	Wilton Rd West
1	356	Wilton Road East
1	371	Wilton Road East
1	371	Wilton Road West
1	378	Wilton Road West
1	387	Wilton Road West

LEGEND

DWD	Driveway Drain
SWD	Stairwell Drain
YD	Yard Drain
WWD	Window Well Drain
SP	Sump Pump
FD	Floor Drain
SW	Sewer Cleanout
X	Downspout goes to surface
O	Downspout goes to ground
⊗	Downspout goes into foundation

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	**Permitted**	**Deffered**	**Refused**
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Andy kelemen	Subarea	1
Address:	17 Ascot Way	Phone Number	2034386537
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/NC	Date/Time	5/2/2016 9:36 AM

NAME OF PERSON ALLOWING ENTRY: Andy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES: NA

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	300
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2. Project 17 Ascot Way. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Varilla Joan	Subarea	1
Address:	5 Ascot Way	Phone Number	2034380538
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/NC/JH	Date/Time	5/2/2016 11:19 AM

NAME OF PERSON ALLOWING ENTRY: Joan — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Roof leader	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	600	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES: NA

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2. Project 5 Ascot Way Initial MC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner: Sonia Small
Address: 6 Ascot Way
Ridgefield, CT
FM:
Technicians TP/jh

Subarea 1
Phone Number 2034385965
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 4/29/2016 11:47 AM

NAME OF PERSON ALLOWING ENTRY Sonia Small
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 6
OTHER INFLOW SOURCES NA

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4/29/16 Project 6 Ascot Way Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Sara Kiernan	Subarea	1
Address:	15 Ascot Way	Phone Number	2034389333
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/JH	Date/Time	4/29/2016 11:04 AM

NAME OF PERSON ALLOWING ENTRY: Sara — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	7200	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)	7200	ELEVATION (ft)	4

OTHER INFLOW SOURCES: NA

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

PHOTO LOG

NOTES:



NOTES:

PHOTOS 1 & 2

PHOTO LOG



NOTES:

NOTES:

PHOTOS 3 & 4

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4/29/16 Project 15 ASCOT WAY Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Joseph Trench	Subarea	1
Address:	18 Ascot Way	Phone Number	2034389324
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/jh	Date/Time	4/29/2016 8:51 AM

NAME OF PERSON ALLOWING ENTRY: Joseph Trench — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)	400	ELEVATION (ft)	7
OTHER INFLOW SOURCES	No		

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4/29/16 Project 18 Ascot Way Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Steve Foundoukis
Address: 19 Ascot Way
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/21/2016 9:20 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/21/16 Project 19 ascot way Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Michael Weiss
Address: 9 Branchville Rd
Ridgefield, CT
FM:
Technicians CD/Sp

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 9:11 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION Left side yard
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)

HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1800
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

3rd attempt. Only did external house inspection. Saw sump pump drain pipes existing the left side of the

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 7 Branchville Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Michael Weiss
Address: 9 Branchville Rd
Ridgefield, CT
FM:
Technicians CD/Sp

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 9:11 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION Left side yard
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)

HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1800
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

3rd attempt. Only did external house inspection. Saw sump pump drain pipes existing the left side of the

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 7 Branchville Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Janet Jones	Subarea	1
Address:	58 Branchville Rd	Phone Number	203-894-8016
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TH/SP	Date/Time	6/28/2016 2:03 PM

NAME OF PERSON ALLOWING ENTRY: Janet — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	15000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 58 Branchville Rd Initial TH/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Juliet carter	Subarea	1
Address:	95 Branchville Rd	Phone Number	927 603 5413
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TH	Date/Time	6/23/2016 9:02 AM

NAME OF PERSON ALLOWING ENTRY: Juliet — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Backyard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	400	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6/23/16 Project 95 Branchville Initial OD/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Ann Harper	Subarea	1
Address:	21 Branchville Road	Phone Number	203-894-5289
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TH/SP	Date/Time	6/28/2016 3:26 PM

NAME OF PERSON ALLOWING ENTRY: Ann — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Ink
DISCHARGE LOCATION	Outside	PUMP CAPACITY(gpm)	0
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Rare
DRAINAGE AREA (sf)	900	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Ink — DRAINAGE AREA (sf): 500

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	15000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 21 Branchville Rd Initial SP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sarah Champion	Subarea	1
Address:	24 Branchville Road	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/9/2016 8:36 AM

NAME OF PERSON ALLOWING ENTRY: Sarah — CONFIRM OVER 18 YRS: No

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	NA
DISCHARGE LOCATION	Yard	PUMP CAPACITY(gpm)	NA
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	NA
DRAINAGE AREA (sf)	800	IS PUMP ALWAYS ADEQUATE	NA

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 425

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Owner states downspouts exit to yard and sump exits to yard. One floor drain connected to dehumidifier

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/9 Project 24 Branch ville rd. Initial MC



* Note: A Humidifier was connected with a tube leading to Floor Drain

Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Kim Rector	Subarea	1
Address:	25 Branchville Road	Phone Number	203 438 5156
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/12/2016 8:47 AM

NAME OF PERSON ALLOWING ENTRY: Kim — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 25 Branchville Rd. Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Andy Blieden	Subarea	1
Address:	28 Branchville Road	Phone Number	561-213-3314
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TH/SP	Date/Time	6/28/2016 1:59 PM

NAME OF PERSON ALLOWING ENTRY: Andy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	10000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 28 Branchville Rd Initial TH/SP



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Joanne DeSpirito	Subarea	1
Address:	33 Branchville Road	Phone Number	203-438-9289
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TH/SP	Date/Time	6/28/2016 2:48 PM

NAME OF PERSON ALLOWING ENTRY: Joanne — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 33 Branchville Rd Initial SP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X Permitted | Deffered | Refused

GENERAL INFORMATION | 1st Attempt | 2nd Attempt | 3rd Attempt

Owner: Geraldine Price
Address: 48 Branchville Road
Ridgefield, CT
FM:
Technicians TP SS

Subarea 1
Phone Number 2034035098
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/13/2016 8:10 AM

NAME OF PERSON ALLOWING ENTRY Geraldine
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 7
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/13/16 Project 48 Branchville Rd. Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner: Michelle Quindlen
Address: 50 Branchville Road
Ridgefield, CT
FM:
Technicians TP SS

Subarea 1
Phone Number 2034380084
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/5/2016 8:43 AM

NAME OF PERSON ALLOWING ENTRY Michelle
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION Sewer
SUMP PIPE HARD PIPED Yes
DRAINAGE AREA (sf) 3000
HORSEPOWER OF PUMP NA
PUMP CAPACITY(gpm) NA
FREQUENCY OF CYCLING NA
IS PUMP ALWAYS ADEQUATE Yes
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
OTHER INFLOW SOURCES No
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 1

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Positive connection sump pump to sewer

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/5/16 Project 50 Branchville Rd. Initial S.S



Positive sump pump to sewer.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Veronica Isley	Subarea	1
Address:	52 Branchville road	Phone Number	203 4313035
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 10:40 AM

NAME OF PERSON ALLOWING ENTRY: Veronica — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	To ground side yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	400	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 52 Branchville Rd Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Charles Knoche	Subarea	1
Address:	54 Branchville Road	Phone Number	203-403-3963
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TH/SP	Date/Time	6/28/2016 2:27 PM

NAME OF PERSON ALLOWING ENTRY: Elaine Krehley — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project J4 Branchville Initial TH/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sarah Sullivan	Subarea	1
Address:	56 Branchville Road	Phone Number	203 438 2868
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/19/2016 8:27 AM

NAME OF PERSON ALLOWING ENTRY: Sarah — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	500

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Downspouts to dry well per owner

Garage drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 56 Branchville Rd Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Christina Calabro	Subarea	1
Address:	60 Branchville Road	Phone Number	203-438-7309
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TH/SP	Date/Time	6/28/2016 1:35 PM

NAME OF PERSON ALLOWING ENTRY: Christina — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 60 Branchville Initial TH/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Richard Forfson	Subarea	1
Address:	64 Branchville Road	Phone Number	203-438-9393
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TH/SP	Date/Time	6/28/2016 1:52 PM

NAME OF PERSON ALLOWING ENTRY: Mary Dionne — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	10000
YARD DRAIN	No	DRAINAGE AREA (sf)	4000
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6/28-16 Project 64 Branchville Rd Initial TH/SP



DD

DD

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Greg Murtaugh	Subarea	1
Address:	29 Branchville Road Ridgefield CT	Phone Number	203-438-7108
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TH/SP	Date/Time	6/28/2016 3:16 PM

NAME OF PERSON ALLOWING ENTRY: Greg — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	25000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 29 Branchville Initial TH/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Sage 29 LLC
Address: 19 Creamery Ln
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 3
Building Type: Reds
Flat Roof: No
Date/Time 7/21/2016 9:27 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1400

YARD DRAIN No DRAINAGE AREA (sf)

DRIVEWAY DRAIN No DRAINAGE AREA (sf)

WINDOW WELL DRAIN No DRAINAGE AREA (sf)

OTHER DRAINS No DRAINAGE AREA (sf)

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/21/16 Project 29 Creamery Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner: Elizabeth Side
Address: 21 Creamery Ln
Ridgefield, CT
FM:
Technicians TP JH

Subarea 1
Phone Number 2034389310
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/4/2016 9:43 AM

NAME OF PERSON ALLOWING ENTRY Elizabeth
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)

HORSEPOWER OF PUMP NA
PUMP CAPACITY(gpm) NA
FREQUENCY OF CYCLING NA
IS PUMP ALWAYS ADEQUATE NA

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
IS THE CLEANOUT SEALED?
DRAINAGE AREA (sf)

ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION
ELEVATION (ft)

OTHER INFLOW SOURCES NA

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1400
YARD DRAIN Yes DRAINAGE AREA (sf) 800
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 3200
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Finished basement clean out not located

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/4/16 Project 21 Creamery Ln Initial JAH.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Town of Ridgefield	Subarea	1
Address:	10 East Ridge Rd	Phone Number	203 438 3744
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	School
		Flat Roof:	Yes
Technicians	CD/TH	Date/Time	6/23/2016 10:30 AM

NAME OF PERSON ALLOWING ENTRY: Mike killcar — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?: Yes

TYPE OF BASEMENT FLOOR:

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 12 — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf): 1200

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Below Baseme

DRAINAGE AREA (sf): 500 — ELEVATION (ft): 0

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	10000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	200
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?: Yes

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Date 6/23/16 Project 10 Ridgefield Rd E Ridge Middle School Initial CD/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Jody Mallory
Address: 29 East Ridge Rd
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 1
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 9:23 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1600
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 24 East Ridge Rd Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Claire Bradburn	Subarea	1
Address:	35 East Ridge Rd	Phone Number	203-300-8203
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TH/SP	Date/Time	6/28/2016 1:00 PM

NAME OF PERSON ALLOWING ENTRY: Mrs Hollingworth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	15000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 35 east ridge Initial TH/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Sue manning trustee
Address: 56 East Ridge Rd
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 1
Phone Number
# of floors: 3
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 9:34 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2000
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 56 EastRidge Rd Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Fred Caruso	Subarea	1
Address:	5 East Ridge Road	Phone Number	203- 438-3013
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TH/SP	Date/Time	6/28/2016 1:22 PM

NAME OF PERSON ALLOWING ENTRY: Fred — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Unk
DISCHARGE LOCATION	Rear	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Unk
DRAINAGE AREA (sf)	2000	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	8000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 5 east ridge Initial TH/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Russell Gasdia	Subarea	1
Address:	7 East Ridge Road	Phone Number	203 4312280
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/NC	Date/Time	5/3/2016 10:34 AM

NAME OF PERSON ALLOWING ENTRY: Russell — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 7 East Ridge St Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Ronald Hill	Subarea	1
Address:	15 East Ridge Road	Phone Number	2034310442
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 5:00 PM

NAME OF PERSON ALLOWING ENTRY: Ronald — CONFIRM OVER 18 YRS:

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Crawl space

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Sewer goes to a 1000 gallon waste water tank. And gets pumped up to the road

PHOTO LOG

NOTES: 1000 gallon waste water tank

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Date 5-9-16 Project 15 East Ridge Road Initial TP.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jill Chase	Subarea	1
Address:	17 East Ridge Road	Phone Number	20389493216
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/3/2016 10:25 AM

NAME OF PERSON ALLOWING ENTRY: Jill — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Unknown
DISCHARGE LOCATION	Yard	PUMP CAPACITY(gpm)	Unknown
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Unknown
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	Unknown

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? Yes

ADDITIONAL COMMENTS:

Pond and wet areas on property. Owner states gutters and sump pump drain to pond or wetlands nearb

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 17 East Ridge St. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X	Permitted	Deffered	Refused
GENERAL INFORMATION	X	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner: Michael Beck
Address: 27 East Ridge Road
Ridgefield, CT
FM:
Technicians TP. NC

Subarea 1
Phone Number 203 438 6306
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/3/2016 11:19 AM

NAME OF PERSON ALLOWING ENTRY Ralph
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 6
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 900
YARD DRAIN Yes DRAINAGE AREA (sf) 1200
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 600
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 27 East Ridge St. Initial NC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	David Beeman	Subarea	1
Address:	44 East Ridge Road	Phone Number	908 285 0971
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/15/2016 8:11 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT No

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/15/14 Project 44 East Ridge Initial JC/JP



East Ridge

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Beth Simon	Subarea	1
Address:	48 East Ridge Road	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/3/2016 11:16 AM

NAME OF PERSON ALLOWING ENTRY: Beth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Unknown
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	Unknown
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Unknown
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES: NA

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 48 East Ridge st Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Peter Montanari	Subarea	1
Address:	62 East Ridge Road	Phone Number	203 733 2950
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/4/2016 11:28 AM

NAME OF PERSON ALLOWING ENTRY: Peter — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	NA
DISCHARGE LOCATION	Ground	PUMP CAPACITY(gpm)	NA
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	NA
DRAINAGE AREA (sf)	1200	IS PUMP ALWAYS ADEQUATE	NA

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: _____ FREQUENCY OF USE: _____

DISCHARGE LOCATION: _____ DRAINAGE AREA (sf): _____

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE: _____

DISCHARGE LOCATION: _____ DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: _____ (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): _____ — ELEVATION (ft): 5

OTHER INFLOW SOURCES: NA

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2300
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Owner said sump pump goes into the yard, could not confirm

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/4/16 Project 62 East Ridge St. Initial JAH.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner: RandallBaldwin
Address: 43 East Ridge Street
Ridgefield, CT
FM:
Technicians TP. SS

Subarea 1
Phone Number 2037334160
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/5/2016 11:35 AM

NAME OF PERSON ALLOWING ENTRY Randall
CONFIRM OVER 18 YRS Yes
BASEMENT No
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED?
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 3000
YARD DRAIN DRAINAGE AREA (sf)
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 200
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Owner states clean out is there but covered by wall

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/5/14 Project 43 E. Ridge ST Initial SS



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Town of Ridgefield	Subarea	1
Address:	76 East Ridge Street	Phone Number	2034386531
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Municipal Police
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/10/2016 11:31 AM

NAME OF PERSON ALLOWING ENTRY: Dan Gjodesen CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes NUMBER OF DRAINS: 2 FREQUENCY OF USE:

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: FREQUENCY OF USE:

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes LOCATION: Above Basem

DRAINAGE AREA (sf): ELEVATION (ft): 6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1800
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-10-16 Project 76 East Ridge Street (Police St.) Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	86 Govenor St LLC	Subarea	1
Address:	86 Govenor St	Phone Number	203 470 3478
	Ridgefield, CT	# of floors:	4
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/8/2016 1:40 PM

NAME OF PERSON ALLOWING ENTRY: Phil — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet / tile — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Below Baseme
DRAINAGE AREA (sf)	250	ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-8-16 Project 86 Governor St. Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	76 governor St LLC	Subarea	1
Address:	76 governor St	Phone Number	203 470 3478
	Ridgefield, CT	# of floors:	4
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/8/2016 1:17 PM

NAME OF PERSON ALLOWING ENTRY: Phil haitsch — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet/tile — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2600
YARD DRAIN	Yes	DRAINAGE AREA (sf)	450
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Could not locate sewer clean out, finished bottom floor could not see any sewer pipes

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-8-16 Project 76 Governor Street Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	George Dinise	Subarea	1
Address:	84 Governor Street	Phone Number	9143296622
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/10/2016 8:25 AM

NAME OF PERSON ALLOWING ENTRY: George — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	6000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Sewer clean out is under a finished stair case

EST
Associates, Inc.

Date 5-10-16 Project 8H Governor Street Initial T.P.



EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Nella Sementilli	Subarea	1
Address:	28 High Ridge Ave	Phone Number	9144384060
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/10/2016 12:59 PM

NAME OF PERSON ALLOWING ENTRY: Nella — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	To sewer pipe	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Has a sump pump the is hard piped to the sewer line. However she she states that the house has a Septic Tank And she has the tank pumped out every year.

PHOTO LOG

NOTES:

NOTES:

PHOTOS 1 & 2

PHOTO LOG



NOTES:

NOTES:

PHOTOS 3 & 4

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-10-16 Project 28 High Ridge Avenue Initial T.P.



* Positive connection to sewer pipe

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Chris Brown	Subarea	1
Address:	32 High Ridge Ave	Phone Number	2032445822
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/3/2016 2:07 PM

NAME OF PERSON ALLOWING ENTRY: Chris — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2600
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 32 High Ridge Ave Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Christine Brown	Subarea	1
Address:	23 High Ridge Avenue	Phone Number	2032445546
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP / NC	Date/Time	5/3/2016 2:02 PM

NAME OF PERSON ALLOWING ENTRY: Christine — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	UK
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	UK
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	UK
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	Unknown

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES: No

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

One sewer clean out submerged under water in basement

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 23 High Ridge Ave Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Carrie McManus	Subarea	1
Address:	5 High Ridge Ave	Phone Number	203 438 7958
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/27/2016 12:28 PM

NAME OF PERSON ALLOWING ENTRY: Carrie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3200
YARD DRAIN	Yes	DRAINAGE AREA (sf)	800
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	30

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

PHOTO LOG

NOTES: Downspout going into house to unknown location

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-27-16 Project 5 High Ridge Ave. Initial N.C.

* Found one Down spout leading to the inside of house.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Fred Ernst	Subarea	1
Address:	15 Highridge Ave	Phone Number	2034319437
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/Jh	Date/Time	4/29/2016 9:27 AM

NAME OF PERSON ALLOWING ENTRY: Fred Ernst — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Below Baseme
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES: No

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4/29/16 Project 15 HIGHRIDGE Rd. Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Webber Bill	Subarea	1
Address:	7 ivy hill	Phone Number	2034171140
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 11:30 AM

NAME OF PERSON ALLOWING ENTRY: Bill — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	To ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	300	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 300

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2400
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Exterior clean out under ground in the yard. Not visible

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 7 Ivy Hill Rd. Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Steven Meyers	Subarea	1
Address:	9 Ivy Hill Road	Phone Number	2034382408
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/10/2016 9:22 AM

NAME OF PERSON ALLOWING ENTRY: Steven — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	To ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

PHOTO LOG

NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-10-16 Project 9 Ivy Hill Road Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner: | Subarea: 5

Address: 6 Juneberry Lane | Phone Number:

Ridgefield, CT | # of floors: 2

FM: | Building Type: Commercial

Flat Roof: Yes

Technicians SS/TP | Date/Time 4/28/2016 2:18 PM

NAME OF PERSON ALLOWING ENTRY Jerry | CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No | EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Dirt | No

SUMP PUMP

SUMP PUMP Yes | HORSEPOWER OF PUMP Unknown

DISCHARGE LOCATION Sewer | PUMP CAPACITY(gpm) Unknown

SUMP PIPE HARD PIPED Yes | FREQUENCY OF CYCLING Unknown

DRAINAGE AREA (sf) 8000 | IS PUMP ALWAYS ADEQUATE Unknown

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No | NUMBER OF DRAINS | FREQUENCY OF USE

DISCHARGE LOCATION | DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No | FREQUENCY OF USE

DISCHARGE LOCATION | DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes | ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? Yes | LOCATION Above Basem

DRAINAGE AREA (sf) | ELEVATION (ft) 1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes | DRAINAGE AREA (sf) 8000

YARD DRAIN Yes | DRAINAGE AREA (sf)

DRIVEWAY DRAIN No | DRAINAGE AREA (sf)

WINDOW WELL DRAIN No | DRAINAGE AREA (sf)

OTHER DRAINS No | DRAINAGE AREA (sf)

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Crawl space with sump pump connected to sewer.to muddy to crawl under to get picture.covers all of th

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4-28-16 Project 6 Juneberry Ln Initial T. Purcell



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Robert Caruso
Address: 2 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 12:05 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1800

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date _____ Project 2 main St Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Lawrence Kalkstein
Address: 8 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 12:06 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 8 main St Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Frank Connard
Address: 17 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 12:01 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 17 main St Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Regina Christel	Subarea	1
Address:	19 Main St	Phone Number	917 494 8470
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Reds
		Flat Roof:	No
Technicians	CD /SP	Date/Time	7/18/2016 11:57 AM

NAME OF PERSON ALLOWING ENTRY: Ragina Christel — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 19 main St Initial co/sp



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** X **3rd Attempt**

Owner:	Susan Kissel	Subarea	1
Address:	54 Main St	Phone Number	203 438 8099
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Reds
		Flat Roof:	No
Technicians	CD/ SP	Date/Time	7/18/2016 12:31 PM

NAME OF PERSON ALLOWING ENTRY: Susan Kissel — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3500
YARD DRAIN	Yes	DRAINAGE AREA (sf)	250
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	250
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 54 main St Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Rudolph Chang	Subarea	1
Address:	55 Main St	Phone Number	
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Reds
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/18/2016 11:48 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 55 main St Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	David Doyle	Subarea	1
Address:	59 Main St	Phone Number	203 894 9210
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Reds
		Flat Roof:	No
Technicians	CD/ SP	Date/Time	7/18/2016 11:32 AM

NAME OF PERSON ALLOWING ENTRY: Pam Custove — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

PHOTO LOG



NOTES: Positive connection to the sewer

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 59 Main St Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | X **3rd Attempt**

Owner:	Robert Loughran	Subarea	1
Address:	94 Main St	Phone Number	203 431 8979
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/18/2016 2:13 AM

NAME OF PERSON ALLOWING ENTRY: Katy Loren — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 50

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	50
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 94 main Street Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Thomas Cowan
Address: 156 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/21/2016 10:37 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 250
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/21/16 Project 156 main St Initial CD/SP





51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Richard Cacciapaglia
Address: 200 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 2:46 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 3500
YARD DRAIN Yes DRAINAGE AREA (sf) 500
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 250
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 200 main Street Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Main st LLC
Address: 236 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 3:00 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 236 main St Initial CD/SP



front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Valero Jensen Trustee
Address: 250 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 3:06 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1800
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 250 main Street Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Emit Ackerlund	Subarea	1
Address:	304 main st	Phone Number	9144717288
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 11:02 AM

NAME OF PERSON ALLOWING ENTRY: Emit — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 304 Main Street Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | X **3rd Attempt**

Owner:	Town of Ridgefield	Subarea	1
Address:	310 Main St	Phone Number	917 216 2004
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/19/2016 9:37 AM

NAME OF PERSON ALLOWING ENTRY: Alycia dadd — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Back yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 2/19/16 Project 310 main st Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Ridgefiel LLC	Subarea	1
Address:	378 Main St	Phone Number	203 431 4440
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Business
		Flat Roof:	No
Technicians	CD/TH	Date/Time	6/23/2016 10:04 AM

NAME OF PERSON ALLOWING ENTRY: Lesa — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	300

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Other drain is stairway drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6/23/16 Project 378 Main St Initial CD/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Jack Borbely	Subarea	1
Address:	1 Main Street	Phone Number	203-431-0159
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Residential
		Flat Roof:	No
Technicians	SS/TP	Date/Time	4/28/2016 1:21 PM

NAME OF PERSON ALLOWING ENTRY: Jack — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	50

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Stairwell drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4-28-16 Project 1 Main St, Ridgefield Initial T. Purcell



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Hilary Oskam	Subarea	1
Address:	7 Main Street	Phone Number	2034033077
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/SS	Date/Time	5/5/2016 1:18 PM

NAME OF PERSON ALLOWING ENTRY: Hilary — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/5/16 Project 7 Main St Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner: Scott Darling
Address: 12 Main Street
Ridgefield, CT
FM:
Technicians TP / SS

Subarea 1
Phone Number 2034326574
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/5/2016 1:05 PM

NAME OF PERSON ALLOWING ENTRY Scott
CONFIRM OVER 18 YRS Yes
BASEMENT No
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 6
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/5/16 Project 12 Main St. Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Karen Corcoran	Subarea	1
Address:	30 Main Street	Phone Number	2034311344
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/10/2016 10:32 AM

NAME OF PERSON ALLOWING ENTRY: Karen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	To ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 3 — FREQUENCY OF USE: Not much

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 900

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Owner states that the driveway drain backs up several times in the spring

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-10-16 Project 30 Main St. Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Erica Smock	Subarea	1
Address:	32 Main Street	Phone Number	203 648 8737
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/30/2016 9:44 AM

NAME OF PERSON ALLOWING ENTRY: Erica — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Into ground outside hou	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-30-16 Project 32 Main St Initial CD



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Ralph Serpico	Subarea	1
Address:	34 Main Street	Phone Number	2034389892
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians		Date/Time	5/2/2016 10:14 AM

NAME OF PERSON ALLOWING ENTRY: Ralph — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2 Project 34 Main St Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Gary Singer	Subarea	1
Address:	35 Main Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/NC	Date/Time	5/2/2016 11:24 AM

NAME OF PERSON ALLOWING ENTRY: Gary — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Below Baseme

DRAINAGE AREA (sf): — ELEVATION (ft):

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	800
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2 Project 35 Main St Initial



No Gutters.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Laurie Kenagy	Subarea	1
Address:	49 Main Street	Phone Number	203 438 7776
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/8/2016 9:51 AM

NAME OF PERSON ALLOWING ENTRY: Laurie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/8/16 Project 49 Main St. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X	Permitted	Deffered	Refused
GENERAL INFORMATION	X	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Kevin Corcoran	Subarea	1
Address:	51 Main Street	Phone Number	Refused
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. JH	Date/Time	5/4/2016 3:41 PM

NAME OF PERSON ALLOWING ENTRY: Kevin — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES: NA

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/4/16 Project 51 Main St. Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner: Cerbonne Nick
Address: 53 Main Street
Ridgefield, CT
FM:
Technicians TP NC

Subarea 1
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/4/2016 3:54 PM

NAME OF PERSON ALLOWING ENTRY Nick
CONFIRM OVER 18 YRS Yes
BASEMENT No
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR NA
No

SUMP PUMP

SUMP PUMP No
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED? Yes
LOCATION Above Basem
DRAINAGE AREA (sf) 1400
ELEVATION (ft) 1
OTHER INFLOW SOURCES NA

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes
DRAINAGE AREA (sf) 5000
YARD DRAIN No
DRAINAGE AREA (sf)
DRIVEWAY DRAIN No
DRAINAGE AREA (sf)
WINDOW WELL DRAIN No
DRAINAGE AREA (sf)
OTHER DRAINS No
DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/4/16 Project 53 MAIN ST Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jane Hyde	Subarea	1
Address:	57 Main Street	Phone Number	2038941410
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JH	Date/Time	5/4/2016 3:04 PM

NAME OF PERSON ALLOWING ENTRY: Jane — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Unknown
DISCHARGE LOCATION	Yard or ground	PUMP CAPACITY(gpm)	Unknown
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Unknown
DRAINAGE AREA (sf)	1,000	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES: No

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	350
YARD DRAIN	Yes	DRAINAGE AREA (sf)	1600
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

57A, rear office, not inspected. Said he would call to schedule appointment. Jane's husband.

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/4/16 Project 57 Main St Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Dorothy Doty	Subarea	1
Address:	85 Main Street	Phone Number	2034310557
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/NC	Date/Time	5/2/2016 10:45 AM

NAME OF PERSON ALLOWING ENTRY: Dorothy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Under yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	900	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2
OTHER INFLOW SOURCES	NA		

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sump pump pipe comes out under yard, sewer manhole nearby

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2 Project 85 Main Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Epstein	Subarea	1
Address:	88 Main Street	Phone Number	2034033340
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/jh	Date/Time	4/29/2016 10:00 AM

NAME OF PERSON ALLOWING ENTRY: Bridget Maloney — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)	800	ELEVATION (ft)	1

OTHER INFLOW SOURCES: No

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	7200
YARD DRAIN	Yes	DRAINAGE AREA (sf)	2000
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	5000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4/29/16 Project 88 Main St Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Andy Pagano	Subarea	1
Address:	99 Main Street	Phone Number	203 438 8077 ex 19
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/11/2016 8:58 AM

NAME OF PERSON ALLOWING ENTRY: Andy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Crawl space

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/11/16 Project 99 Main St Initial SS



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Andy Pagano	Subarea	1
Address:	103 Main Street	Phone Number	2034388077 ext 19
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP SS	Date/Time	5/11/2016 8:50 AM

NAME OF PERSON ALLOWING ENTRY: Andy Pagano — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

103 Main St shares same property as 99 Main and 21 West Lane

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/11/16. Project 103 Main st. Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Cook Peter	Subarea	1
Address:	104 Main Street	Phone Number	203 4033783
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 10:06 AM

NAME OF PERSON ALLOWING ENTRY: Peter — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 5 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknow — DRAINAGE AREA (sf): Unknown

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

2 floor drains to old well inside the house

PHOTO LOG

NOTES: Old well inside house

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/9 Project 104 Main St Initial MC





51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Laurice Haynes	Subarea	1
Address:	114 Main Street	Phone Number	203 894 4641
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/11/2016 9:40 AM

NAME OF PERSON ALLOWING ENTRY: Laurice — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 330

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3250
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16 Project 114 Main St. Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Keeler Tavern	Subarea	1
Address:	152 Main Street	Phone Number	203 894 8393
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/11/2016 9:30 AM

NAME OF PERSON ALLOWING ENTRY: Roger Keller — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	8

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/11/16 Project 152 Main st. Initial S.S



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Christine Lecher	Subarea	1
Address:	154 Main Street	Phone Number	203 470 5155
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 3:55 PM

NAME OF PERSON ALLOWING ENTRY: Christine — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Owner states all drains go to stream in back

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 154 main st Initial OD



* Own states that drains around the pool drain to the back of the house and down embankment

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Christopher Pappas	Subarea	2
Address:	155 Main Street	Phone Number	
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/11/2016 10:10 AM

NAME OF PERSON ALLOWING ENTRY: Jennifer — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3400
YARD DRAIN	Yes	DRAINAGE AREA (sf)	240
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2300
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16 Project 155 Main St Initial JC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jim Lehy	Subarea	1
Address:	158 Main Street	Phone Number	2034381848
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. JH	Date/Time	5/6/2016 8:29 AM

NAME OF PERSON ALLOWING ENTRY: Jim — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES: NA

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Outlets to wetlands in back, confirmed that some downspouts connect, others unknown

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/6/16 Project 158 MAIN ST Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Maritza Johnson	Subarea	1
Address:	160 Main Street	Phone Number	203 942 5685
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	7/1/2016 8:48 AM

NAME OF PERSON ALLOWING ENTRY: Maritza — CONFIRM OVER 18 YRS: No

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-1-16 Project 160 Main St Initial CD



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sarah Blanford	Subarea	1
Address:	164 Main Street	Phone Number	203 894 8594
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/12/2016 9:19 AM

NAME OF PERSON ALLOWING ENTRY: Sarah — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	500
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 164 Main st. Initial SS.



EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Prusko James	Subarea	1
Address:	188 Main Street	Phone Number	9147630965
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/10/2016 2:54 PM

NAME OF PERSON ALLOWING ENTRY: Cesar — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Below Baseme
DRAINAGE AREA (sf)	2000	ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-10-16 Project 188 Main St. Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Alexandra Goodstabt	Subarea	1
Address:	212 Main Street	Phone Number	203 438 4716
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/12/2016 11:30 AM

NAME OF PERSON ALLOWING ENTRY: Alexandra — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 212 Main st Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Rob Orr	Subarea	1
Address:	260 Main Street	Phone Number	2037672373
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Church
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 4:04 PM

NAME OF PERSON ALLOWING ENTRY: Rob — CONFIRM OVER 18 YRS:

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No basement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE: Not much

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 300

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Church has no basement and the clean out was not visible

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 260 Main Street Initial T.P.



Downspouts to dry well per owner

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Town of Ridgefield	Subarea	1
Address:	316 Main Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/12/2016 8:50 AM

NAME OF PERSON ALLOWING ENTRY: Frank Madden — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Clean out not located

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 316 Main St. Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Aldrich Museum	Subarea	1
Address:	258 Main Street - Administrative Offices	Phone Number	203 458 4519
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/11/2016 10:50 AM

NAME OF PERSON ALLOWING ENTRY: Mary Kenealy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Could not locate clean out

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16 Project 258 Main st. (Administration Building) Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Aldrich Museum	Subarea	1
Address:	258 Main Street - Museum	Phone Number	203 438 4519
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	Yes
Technicians	TP NC	Date/Time	7/11/2016 10:54 AM

NAME OF PERSON ALLOWING ENTRY: Mary Kenealy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 8 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 1000

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: Yes — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	170
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16. Project 258 Main st. Initial NC

Aldrich Museum.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Keeler Tavern	Subarea	1
Address:	152 Main Street Barn/ Garage	Phone Number	
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP SS	Date/Time	5/4/2016 9:39 AM

NAME OF PERSON ALLOWING ENTRY: Pat and Roger Kelle — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/11/16 Project 152 Main St Garage Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Keeler Tavern	Subarea	1
Address:	152 Main Street Carriage House	Phone Number	
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/11/2016 9:45 AM

NAME OF PERSON ALLOWING ENTRY: Roger — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/11/16 Project 152 Main St Barn bldg Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Keeler Tavern	Subarea	1
Address:	132 Main Street Garden House	Phone Number	203 894 8393
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP SS	Date/Time	5/11/2016 9:53 AM

NAME OF PERSON ALLOWING ENTRY: Roger Keller — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	60

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump in basement

Stairwell drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/11/16. Project 132 Main St. Garden House Initial S.S



Building has Ejector Pump.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Roger Keller	Subarea	1
Address:	132 Main Street Main House	Phone Number	/203 894 8393
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/11/2016 9:16 AM

NAME OF PERSON ALLOWING ENTRY: Roger — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	60

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Stairwell Drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/11/16. Project 132 Main st. Tavern bldg Initial SS



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Doug Barile	Subarea	1
Address:	34 Market	Phone Number	2039484940
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 12:29 PM

NAME OF PERSON ALLOWING ENTRY: Doug — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 34 Market Street Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Eric Freidenrich	Subarea	1
Address:	14 Market Street	Phone Number	6504309538
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/5/2016 11:54 AM

NAME OF PERSON ALLOWING ENTRY: Eric — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/5/14 Project 14 Market St Initial S.S



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Melanie Mauldin	Subarea	1
Address:	19 Market Street	Phone Number	9172328793
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP SS	Date/Time	5/12/2016 8:59 AM

NAME OF PERSON ALLOWING ENTRY: Melanie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE: Unknown

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Floor drain below invert of sewer pipe

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 19 Market St. Initial S.S



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Larry Harder	Subarea	1
Address:	24 Market Street	Phone Number	203 438 7238
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/3/2016 11:42 AM

NAME OF PERSON ALLOWING ENTRY: Larry — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 160

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	4500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 24 Market St Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Scott Schneider	Subarea	1
Address:	1 Parley Lane	Phone Number	203 438 1444
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/8/2016 10:33 AM

NAME OF PERSON ALLOWING ENTRY: Scott — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/8/16 Project 1 Parley Ln Initial TJ TA



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner: Elaine Pflepsen
Address: 3 Parley Lane
Ridgefield, CT
FM:
Technicians TP NC

Subarea 1
Phone Number 203 994 2459
# of floors: 3
Building Type: Res
Flat Roof: No
Date/Time 7/12/2016 11:01 AM

NAME OF PERSON ALLOWING ENTRY Elaine
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 4
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 3000
YARD DRAIN Yes DRAINAGE AREA (sf) 500
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 1000
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Ejector pump to sewer
2nd EP for slop sink

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 3 Parley Lane. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Fujitani Paul	Subarea	1
Address:	78 Prospect Ridge	Phone Number	2039945115
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/10/2016 2:02 PM

NAME OF PERSON ALLOWING ENTRY: Chris Nadel — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	400

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-10-16 Project 78 Prospect Ridge Rd Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Ann Marie Galowski	Subarea	1
Address:	120 prospect Ridge Rd	Phone Number	203 5129064
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/10/2016 9:54 AM

NAME OF PERSON ALLOWING ENTRY AnnMarie CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2400
YARD DRAIN	Yes	DRAINAGE AREA (sf)	1200
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	800
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

PHOTO LOG

NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-10-16 Project 120 Prospect Ridge Rd Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Susan Ruehl	Subarea	1
Address:	74 Prospect Ridge Road	Phone Number	2034381786
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/11/2016 8:10 AM

NAME OF PERSON ALLOWING ENTRY: Susan — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4
OTHER INFLOW SOURCES			

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	300
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1300
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/11/16 Project 74 Prospect Ridge Initial S.S



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Keeler Tavern	Subarea	1
Address:	132R Main Street Cottage	Phone Number	203 894 8393
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/11/2016 9:27 AM

NAME OF PERSON ALLOWING ENTRY: Roger Keller — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	No	LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Caretaker's cottage, sewage pipe exposed but no clean out visible

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/11/16 Project 132 Main St Cottage Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Peter Montanari	Subarea	1
Address:	15 Rockwell Rd	Phone Number	2037332950
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. JH	Date/Time	5/4/2016 11:00 AM

NAME OF PERSON ALLOWING ENTRY: Peter — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES: No

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1800
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/4/16 Project 13 Rockwell. Rd. Initial JMH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	William wyman	Subarea	1
Address:	39 Rockwell Rd	Phone Number	2034386307
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/JH	Date/Time	4/29/2016 10:42 AM

NAME OF PERSON ALLOWING ENTRY: William — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Rug - finished — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1000	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Finished basement

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4/29/16 Project 39 Rockwell Rd. Initial JHH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Mark Harden
Address: 43 Rockwell Rd
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 12:59 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2000
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-16-16 Project 43 Rockwell Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Paul Pierre
Address: 59 Rockwell Rd
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 12:53 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 3500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 59 Rockwell Rd Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner: George Talisse
Address: 61 Rockwell Road
Ridgefield, CT
FM:
Technicians TP NC

Subarea 1
Phone Number 203 536 7732
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/30/2016 9:23 AM

NAME OF PERSON ALLOWING ENTRY George
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 8
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2700
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 1000
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:
All drains to outlet pipes per owner (pipes visible in back)

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-30-16. Project 61 Rockwell Road Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Michael Bradley	Subarea	1
Address:	63 Rockwell Rd	Phone Number	203 438 6245
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/29/2016 1:44 PM

NAME OF PERSON ALLOWING ENTRY Bradley CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Wood No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	8

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-29-16 Project 63 Rockwell Rd. Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Gavin Donnelly	Subarea	1
Address:	5 Rockwell Road	Phone Number	2034380521
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. JH	Date/Time	5/6/2016 7:42 AM

NAME OF PERSON ALLOWING ENTRY: Gavin — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES: NA

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

DWD goes to ground surface

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/6/16 Project 5 Rockwell RD Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	George Karaffa	Subarea	1
Address:	27 Rockwell Road	Phone Number	203-438-9625
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Residential
		Flat Roof:	No
Technicians	SS/TP	Date/Time	4/28/2016 2:45 PM

NAME OF PERSON ALLOWING ENTRY George CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4-28-16 Project 27 Rockwell Road Initial T. Purcell



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Robert Murphy	Subarea	1
Address:	30 Rockwell Road	Phone Number	2034386645
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. JH	Date/Time	5/6/2016 7:32 AM

NAME OF PERSON ALLOWING ENTRY: Robert — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/6/16 Project 30 Rockwell Rd Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner:	Edward Vandeventer	Subarea	1
Address:	41 Rockwell Road	Phone Number	2034387328
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/JH	Date/Time	5/2/2016 12:34 PM

NAME OF PERSON ALLOWING ENTRY: Edward V.
CONFIRM OVER 18 YRS: Yes
BASEMENT: Yes
WATER IN BASEMENT: No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR: Cement
No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?: Yes
LOCATION: Above Basem
DRAINAGE AREA (sf)
ELEVATION (ft): 7
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes
DOWNSPOUTS ENTER GROUND: No — DRAINAGE AREA (sf)
YARD DRAIN: No — DRAINAGE AREA (sf)
DRIVEWAY DRAIN: No — DRAINAGE AREA (sf)
WINDOW WELL DRAIN: No — DRAINAGE AREA (sf)
OTHER DRAINS: No — DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2 Project 41 Rockwell Rd Initial NL



EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Saqib Jamshed	Subarea	1
Address:	45 Rockwell Road	Phone Number	2038949608
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC JH	Date/Time	5/2/2016 10:40 AM

NAME OF PERSON ALLOWING ENTRY: Saqib — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2. Project 45 Rockwell Rd Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Justin Cahill	Subarea	1
Address:	47 Rockwell Road	Phone Number	2034380053
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/10/2016 1:35 PM

NAME OF PERSON ALLOWING ENTRY: Justin — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	750
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	750
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-10-16 Project 47 Rockwell Road Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Matthew Sharp	Subarea	1
Address:	49 Rockwell Road	Phone Number	203 438 3205
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/11/2016 8:36 AM

NAME OF PERSON ALLOWING ENTRY: Kathleen Sharp — CONFIRM OVER 18 YRS: No

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Wood/cement

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	400	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16 Project 49 Rockwell Road. Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Rosemary Morretta	Subarea	1
Address:	57 Rockwell Road	Phone Number	2034383731
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/5/2016 2:10 PM

NAME OF PERSON ALLOWING ENTRY: Rosemary — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1
OTHER INFLOW SOURCES	NA		

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	50
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/5/16 Project 57 Rockwall Rd. Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	John Mitchell	Subarea	1
Address:	13 Rowland Lane	Phone Number	845 304 99727
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 5:04 PM

NAME OF PERSON ALLOWING ENTRY: John — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? Yes

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-14-16 Project 13 Rowland Ln Initial CA



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sharon Hyatt	Subarea	1
Address:	14 Rowland Lane	Phone Number	2033124586
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/10/2016 11:02 AM

NAME OF PERSON ALLOWING ENTRY: Sharon — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Crawl Space — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-10-16 Project 14 Rowland Lane Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Karen Kazzi	Subarea	1
Address:	20 Rowland Lane	Phone Number	203 438 2234
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/17/2016 5:28 PM

NAME OF PERSON ALLOWING ENTRY: Karen — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Backyard per owner	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	15	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Crawl space with sump pump

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-17-16 Project #20 Bowland Ln Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Kate Mougey	Subarea	1
Address:	23 Rowland Lane	Phone Number	2034317884
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 4:40 PM

NAME OF PERSON ALLOWING ENTRY: Kate — CONFIRM OVER 18 YRS:

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR:

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	400	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Sewer clean out is in the far corner of a crawl space. Not able to get close to it and the are is under a pl

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 23 Rowland Lane Initial T.P



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Irma Roberti
Address: 16 Rowland Ln
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 1:05 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 11 Roland Ave. Initial CD/SF



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: KevinDavis
Address: 19 Rowland Ln
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 1:07 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1800
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 19 Roland lane Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Rodney Thorn
Address: 25 Rowland Ln
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 1:12 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION Right side yard
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)

HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection

Can see sump pump discharge pipe leave the right side of the house

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 25 Roland lane Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Patrick Egan	Subarea	1
Address:	26 Rowland Ln	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/18/2016 1:17 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/17 Project 25 Roland lane Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sharon	Subarea	1
Address:	16 Shadow Lane	Phone Number	203 438 6051
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC JH	Date/Time	5/3/2016 3:52 PM

NAME OF PERSON ALLOWING ENTRY: Sharon — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Unknown
DISCHARGE LOCATION	Yard/ground	PUMP CAPACITY(gpm)	Unknown
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Unknown
DRAINAGE AREA (sf)	1000	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	Yes	DRAINAGE AREA (sf)	350
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3/16 Project 16 Shaddock Ln Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Andy Pagano	Subarea	1
Address:	21 West Lane	Phone Number	203 438 8077 ex 19
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/11/2016 9:01 AM

NAME OF PERSON ALLOWING ENTRY: Andy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Shares property with 103 and 99 Main St

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/11/14 Project 21 West Ln Initial SS



EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	27 West Lane LLC	Subarea	1
Address:	27 West Lane	Phone Number	No Number tenant let us in
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 1:41 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

3 Sewer clean outs in basement

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Date 5-9-16 Project 27 West Ln Initial T.P.



↓ sewer cleanouts enter ground, cannot determine where they lead

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Richard Bdzzuto	Subarea	1
Address:	29 West Lane	Phone Number	
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 1:22 PM

NAME OF PERSON ALLOWING ENTRY: Richard — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION:

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sewer clean out was not visible

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 29 West Ln Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Kathleen Wolfel	Subarea	1
Address:	31 West Lane	Phone Number	203 438 7890
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/8/2016 10:54 AM

NAME OF PERSON ALLOWING ENTRY: Kathleen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Dirt — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Downspout	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	900	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1400
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1800
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

3 driveway drains take most of DW drainage

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/8/14 Project 31 West LN Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:		Subarea	1
Address:	39 West Lane	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 1:07 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT No

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

No Basement Sewer gets pumped

PHOTO LOG

NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 39 West Rd Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Kathy Flaherty	Subarea	1
Address:	43 West Lane	Phone Number	203-438-4309
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Residential
		Flat Roof:	No
Technicians	SS/TP	Date/Time	4/28/2016 3:27 PM

NAME OF PERSON ALLOWING ENTRY: Kathy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Na
DISCHARGE LOCATION	Yard	PUMP CAPACITY(gpm)	Na
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Unknown
DRAINAGE AREA (sf)	1500	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4-28-16 Project 43 West Ln Initial T. Purcell



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Amy Schmidt	Subarea	1
Address:	45 West Lane	Phone Number	2033130124
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 2:13 PM

NAME OF PERSON ALLOWING ENTRY: Amy — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	To ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	400	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE: Not much

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

PHOTO LOG

NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 45 West Ln Initial T.P.



* 2 mailboxes for 45 West Lane, house in back checked, no one home

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Neumann Real Estate	Subarea	1
Address:	48 West Lane	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/8/2016 10:47 AM

NAME OF PERSON ALLOWING ENTRY: Sheila Fox — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	120
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/8/16 Project 48 West Ln Initial TP/TH



EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Max Axler
Address: 51 West Lane
Ridgefield, CT
FM:
Technicians TP TH

Subarea 1
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 2:46 PM

NAME OF PERSON ALLOWING ENTRY Tara Axler
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION Ground surface
SUMP PIPE HARD PIPED Yes
DRAINAGE AREA (sf) 500
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 5
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 800
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/14 Project 51 West Ln Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sheila Sammur	Subarea	1
Address:	55 West Lane	Phone Number	2034383620
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 2:38 PM

NAME OF PERSON ALLOWING ENTRY: Sheila — CONFIRM OVER 18 YRS:

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR:

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE: Not much

DISCHARGE LOCATION: Ground — DRAINAGE AREA (sf): 400

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

No Basement. Sewer is in a tiny crawl space

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 55 West Ln Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner: Wendy White
Address: 57 West Lane
Ridgefield, CT
FM:
Technicians NC TP

Subarea 1
Phone Number 2035140004
# of floors: 3
Building Type: Res
Flat Roof: No
Date/Time 5/9/2016 3:03 PM

NAME OF PERSON ALLOWING ENTRY Wendy
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 4
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 900
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 57 West Lane Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner: Mark Trench
Address: 58 West Lane
Ridgefield, CT
FM:
Technicians TP/ NC

Subarea 1
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/3/2016 2:31 PM

NAME OF PERSON ALLOWING ENTRY Mark
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN Yes
NUMBER OF DRAINS 1
FREQUENCY OF USE
DISCHARGE LOCATION Unknown
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 4
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 400
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 1200
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Sewer clean outs outside house

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 58 West St. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Cidlete Holzthum	Subarea	1
Address:	63 West Lane	Phone Number	2034384985
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 2:54 PM

NAME OF PERSON ALLOWING ENTRY: Cidlete — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Owner stated that she was on a private septic

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 63 West Ln Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Hanna Deitsch	Subarea	1
Address:	27R West Lane	Phone Number	2034035372
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 1:50 PM

NAME OF PERSON ALLOWING ENTRY: Hanna — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-9-16 Project 27R West Ln Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Susan Stanley	Subarea	1
Address:	39A West Lane	Phone Number	2034317721
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/9/2016 1:03 PM

NAME OF PERSON ALLOWING ENTRY: Susan — CONFIRM OVER 18 YRS:

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	300
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

No basement. Sewer is pumped

PHOTO LOG

NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Date 5-9-16 Project 39A West Rd. Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Nancy Vilece
Address: 349 Wilton Rd East
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 1
Phone Number
# of floors: 2
Building Type: Reds
Flat Roof: No
Date/Time 7/18/2016 11:07 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1200
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 349 Milton East Rd Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner:	Michael Grenert	Subarea	1
Address:	378 Wilton Rd East	Phone Number	203 431 8033
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Reds
		Flat Roof:	No
Technicians	CD / SP	Date/Time	7/18/2016 11:09 AM

NAME OF PERSON ALLOWING ENTRY: Micheal grenert — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: Yes — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 398 Milton East Rd Initial SD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner: Alana Peck
Address: 410 Wilton Rd W
Ridgefield, CT
FM:
Technicians TP. JH

Subarea 1
Phone Number 8182989506
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/4/2016 10:44 AM

NAME OF PERSON ALLOWING ENTRY Alana
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 1
OTHER INFLOW SOURCES NA

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS Yes DRAINAGE AREA (sf) 60
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Stairwell drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/4/16 Project 410 Wilton Rd. West Initial JAH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Robert Lowell	Subarea	1
Address:	367 Wilton Rd West	Phone Number	413 427 7874
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Reds
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/18/2016 10:44 AM

NAME OF PERSON ALLOWING ENTRY: Dave Lowry — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 367 wilton west RD Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Geisinger Ethel	Subarea	1
Address:	380 Wilton Rd West	Phone Number	2&034386384
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/3/2016 10:39 AM

NAME OF PERSON ALLOWING ENTRY: Ethel — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	20
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 380 Wilton Rd West Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Karen Wright	Subarea	1
Address:	381 Wilton Rd West	Phone Number	2032445372
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. /. NC	Date/Time	5/3/2016 3:24 PM

NAME OF PERSON ALLOWING ENTRY: Karen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Unknown
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	Unknown
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Unknown
DRAINAGE AREA (sf)	1200	IS PUMP ALWAYS ADEQUATE	Unknown

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 381 Wilton Rd West. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** X **3rd Attempt**

Owner:	Carl Andresen	Subarea	1
Address:	388 Wilton Rd West	Phone Number	203 438 8909
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Reds
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/18/2016 10:30 AM

NAME OF PERSON ALLOWING ENTRY: Minde Andresen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Front yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 388 wilton west Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	David Wees	Subarea	1
Address:	398 Wilton Rd West	Phone Number	203 438 0150
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Reds
		Flat Roof:	No
Technicians	CD / SP	Date/Time	7/18/2016 10:24 AM

NAME OF PERSON ALLOWING ENTRY: Mimi vamwees — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	250
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 398 wilton west Rd Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner: Carol Benziger
Address: 356 Wilton Road East
Ridgefield, CT
FM:
Technicians TP. JH

Subarea 1
Phone Number 2034315841
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/4/2016 2:22 PM

NAME OF PERSON ALLOWING ENTRY Carol
CONFIRM OVER 18 YRS Yes
BASEMENT No
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT No
IS THE CLEANOUT SEALED?
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 4600
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Finished basement could not locate clean out

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/4/16 Project 356 Wilton Rd. East Initial JAH



5"x90

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner: Louis Lynn
Address: 371 Wilton Road East
Ridgefield, CT
FM:
Technicians TP. HJ

Subarea 1
Phone Number 2034033945
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/4/2016 1:31 PM

NAME OF PERSON ALLOWING ENTRY Louis
CONFIRM OVER 18 YRS Yes
BASEMENT No
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION Ground (creek)
SUMP PIPE HARD PIPED No
DRAINAGE AREA (sf) 1000
HORSEPOWER OF PUMP NA
PUMP CAPACITY(gpm) NA
FREQUENCY OF CYCLING NA
IS PUMP ALWAYS ADEQUATE NA
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 3
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 6000
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/4/16 Project 371 Wilton Rd. East Initial JHH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Ray Garst	Subarea	1
Address:	371 Wilton Road West	Phone Number	2039124169
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP / NC	Date/Time	5/2/2016 4:05 PM

NAME OF PERSON ALLOWING ENTRY: Bridie Barron — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?: No

ADDITIONAL COMMENTS:

Additional dwelling on property under same ownership not inspected

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2 Project 371 Wilton rd. West Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	William Weber	Subarea	1
Address:	378 Wilton Road West	Phone Number	2034385829
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/NC	Date/Time	5/2/2016 11:15 AM

NAME OF PERSON ALLOWING ENTRY: William — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown under yard an	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	2200	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Pool drain pipe going out back

2nd clean out in yard

Sump pump possibly leading to manhole in Main Street

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2 Project 378 ~~Main~~ Wilton Rd. W Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner: Mike Jenkins
Address: 387 Wilton Road West
Ridgefield, CT
FM:
Technicians TP / JH

Subarea 1
Phone Number 2034386604
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/4/2016 1:54 PM

NAME OF PERSON ALLOWING ENTRY Mike
CONFIRM OVER 18 YRS Yes
BASEMENT No
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN Yes
NUMBER OF DRAINS 1
FREQUENCY OF USE
DISCHARGE LOCATION Unknown
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 1
OTHER INFLOW SOURCES No

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes — DRAINAGE AREA (sf) 650
YARD DRAIN No — DRAINAGE AREA (sf)
DRIVEWAY DRAIN No — DRAINAGE AREA (sf)
WINDOW WELL DRAIN No — DRAINAGE AREA (sf)
OTHER DRAINS Yes — DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Curtain drain,pipe to ground according to owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/4/16 Project 387 Wilton Rd West Initial JAH.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

2016 RIDGEFIELD

BUILDING INSPECTION REPORT

Prepared for:

AECOM
250 Apollo Drive
Chelmsford, MA 01824

Prepared by:

EST Associates, Inc.
51 Fremont Street
Needham, MA 02494

Subarea 2

TABLE OF CONTENTS

Subarea	No.	Street
2	35	Catoonah St
2	37	Catoonah St
2	43	Catoonah St
2	31D	Catoonah St
2	41A	Catoonah St
2	44A	Catoonah St
2	23	Catoonah St Unit 1
2	23	Catoonah St Unit 2
2	36	Catoonah St Unit 8
2	36	Catoonah St Unit A4
2	36	Catoonah St Unit B07
2	6	Catoonah Street
2	10	Catoonah Street
2	19	Catoonah Street
2	22	Catoonah Street
2	25	Catoonah Street
2	26	Catoonah Street
2	27	Catoonah Street
2	28	Catoonah Street
2	33	Catoonah Street
2	39	Catoonah Street
2	41	Catoonah Street
2	42	Catoonah Street
2	47	Catoonah Street
2	48	Catoonah Street
2	49	Catoonah Street
2	50	Catoonah Street
2	51	Catoonah Street
2	52	Catoonah Street
2	55	Catoonah Street
2	27R	Catoonah Street
2	30 & 32	Catoonah Street
2	31A	Catoonah Street
2	31B	Catoonah Street
2	31C	Catoonah Street
2	33B	Catoonah Street
2	34A	Catoonah Street
2	34B	Catoonah Street
2	37R	Catoonah Street
2	39A	Catoonah Street
2	39B	Catoonah Street
2	43A	Catoonah Street
2	43B	Catoonah Street

Subarea	No.	Street
2	44B	Catoonah Street
2	36	Catoonah Street E18
2	36	Catoonah Street Unit 12
2	36	Catoonah Street Unit 13
2	36	Catoonah Street Unit 14
2	36	Catoonah Street Unit 16
2	36	Catoonah Street Unit 6
2	36	Catoonah Street Unit A
2	36	Catoonah Street Unit A2
2	36	Catoonah Street Unit A3
2	36	Catoonah Street Unit A5
2	36	Catoonah Street Unit B10
2	36	Catoonah Street Unit B11
2	36	Catoonah Street Unit B15
2	36	Catoonah Street Unit B7
2	28	Griffith
2	31	Griffith
2	13	Griffith Lane
2	15	Griffith Lane
2	20	Griffith Lane
2	25	Griffith Lane
2	27	Griffith Lane
2	29	Griffith Lane
2	30	Griffith Lane
2	8	Griffith Ln
2	16	Griffith Ln
2	30	Griffith Ln
2	34	Griffith Ln
2	36	Griffith Ln
2	37	Griffith Ln
2	27B	Griffith Ln
2	62	High Ridge Ave
2	72	High Ridge Ave
2	106	High Ridge Ave
2	108	High Ridge Ave
2	110	High Ridge Ave
2	111	High Ridge Ave
2	112	High Ridge Ave
2	113	High Ridge Ave
2	123	High Ridge Ave
2	125	High Ridge Ave
2	126	High Ridge Ave
2	129	High Ridge Ave
2	143	High Ridge Ave
2	144	High Ridge Ave
2	146	High Ridge Ave
2	148	High Ridge Ave
2	150	High Ridge Ave

Subarea	No.	Street
2	152	High Ridge Ave
2	154	High Ridge Ave
2	159	High Ridge Ave
2	42	High Ridge Avenue
2	50	High Ridge Avenue
2	63	High Ridge Avenue
2	74	High Ridge Avenue
2	82	High Ridge Avenue
2	115	High Ridge Avenue
2	121	High Ridge Avenue
2	128	High Ridge Avenue
2	139	High Ridge Avenue
2	141	High Ridge Avenue
2	145	High Ridge Avenue
2	153	High Ridge Avenue
2	160	High Ridge Avenue
2	161	High Ridge Avenue
2	163	High Ridge Avenue
2	55	High Ridge Avenue Guest house
2	55	High Ridge Avenue Main house
2	77	High Ridge Road
2	87	High Ridge Road
2	161	High Ridge Road
2	77	High Ridge Road Pool House
2	162	Highridge Ave
2	1	Jackson Court
2	7	Jackson Court
2	8	Jackson Court
2	11	Jackson Court
2	21	King Lane
2	27	King Lane
2	44	King Lane
2	455	Main
2	139	Main St
2	145	Main St
2	267	Main St
2	305	Main St
2	321	Main St
2	323	Main St
2	325	Main St
2	127	Main Street
2	149	Main Street
2	265	Main Street
2	275	Main Street
2	353	Main Street
2	385	Main Street

Subarea	No.	Street
2	401	Main Street
2	409	Main Street
2	451	Main Street
2	453	Main Street
2	457	Main Street
2	467	Main Street
2	509	Main Street
2	305B	Main Street
2	463	Main Street - Steve's Bagels
2	461	Main Street - Wild Ginger
2	411B	Main Street (Planet Pizza)
2	127	Main Street Cottage
2	181	Main Street Guest House
2	207	Main Street main Church building
2	181	Main Street main house Ridgefield CT
2	181	Main Street Office
2	351	Main Street South Hall
2	207	Main Street Wesley Hall
2	293	MainSt
2	19	Peacable Street
2	20	Peacable Street
2	30	Peacable Street
2	32	Peacable Street
2	46	Peacable Street
2	2	Peaceable St
2	38	Peaceable St
2	42	Peaceable St
2	44	Peaceable St
2	19	Prospect Ridge Unit 25
2	47	Shadow Lane
2	49	Shadow Lane
2	53	Shadow Lane
2	57	Shadow Lane
2	56	Shadow Ln
2	61	Shadow Ln
2	10	West Lane
2	20	West Lane
2	22	West Lane (Main house)
2	22	West Lane Cottage Units 401 to 406

LEGEND

DWD	Driveway Drain
SWD	Stairwell Drain
YD	Yard Drain
WWD	Window Well Drain
SP	Sump Pump
FD	Floor Drain
SW	Sewer Cleanout
X	Downspout goes to surface
O	Downspout goes to ground
⊗	Downspout goes into foundation

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Robert Fox	Subarea	2
Address:	35 Catoonah St	Phone Number	203 648 2799
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/17/2016 3:34 PM

NAME OF PERSON ALLOWING ENTRY: Robert — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	2 to sewer, one surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1200	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	0

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

3 sump pumps,2 connected to sewer; 3rd drains to surface, outlet pipe visible

Positive connections to sewer

Owner states sump pumps run frequently

PHOTO LOG

NOTES:



NOTES:

PHOTOS 1 & 2

PHOTO LOG

NOTES:

NOTES:

PHOTOS 3 & 4

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-17-16 Project 35 Catamah St. Initial MC





* Sump pump goes to SW

Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Caroline Molyneux	Subarea	2
Address:	37 Catoonah St	Phone Number	203 894 8437
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 2:15 PM

NAME OF PERSON ALLOWING ENTRY: Caroline — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 37 Catoonah St Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Joe Goetz	Subarea	2
Address:	43 Catoonah St	Phone Number	203 244 5350
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 2:15 PM

NAME OF PERSON ALLOWING ENTRY: John Goetz — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Below Baseme

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 43 Catoonah Initial SP/CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Paul Covill	Subarea	2
Address:	31 D Catoonah St	Phone Number	203 431 4907
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 2:54 PM

NAME OF PERSON ALLOWING ENTRY: Paul Covill — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? Yes

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 31D Catoonah St. Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Ray Pinielle	Subarea	2
Address:	41 A Catoonah St	Phone Number	203 240 9219
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 2:26 PM

NAME OF PERSON ALLOWING ENTRY: Ray Piniella — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Below Baseme

DRAINAGE AREA (sf): — ELEVATION (ft): 2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 41A Savannah Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Taft Coleman	Subarea	2
Address:	44A Catoonah St	Phone Number	203 241 3501
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 2:49 PM

NAME OF PERSON ALLOWING ENTRY: Taft Coleman — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	No		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	500
YARD DRAIN	Yes	DRAINAGE AREA (sf)	250
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Could not locate sewer clean. Finished basement most likely behind wall

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 44A Catoonah Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Tish Vredenburgh	Subarea	2
Address:	23 Catoonah St Unit 1	Phone Number	203 470 6071
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Business
		Flat Roof:	No
Technicians	CD/ TH	Date/Time	6/23/2016 9:25 AM

NAME OF PERSON ALLOWING ENTRY: Tish Vredenburgh — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Side yard stream	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6/23/16 Project 23 CATOOSAH Unit 1 Initial CD/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Joe Attonito	Subarea	2
Address:	23 Catoonah St Unit 2	Phone Number	203 438 0200
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 1:40 PM

NAME OF PERSON ALLOWING ENTRY: Joe — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Back yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1600	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: No — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 23 · Catoonah unit 2 Initial CO/SP



EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	James Roushe	Subarea	2
Address:	36 Catoonah St Unit 8	Phone Number	2035455227
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/16/2016 9:20 AM

NAME OF PERSON ALLOWING ENTRY: James — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sewer pipe goes behind wall, could not see clean out

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16 Project 36 #8 Catoonah. Initial NC



* Followed the Sewer line to behind a wall in the Garage.
SW clean out Not Visable.

Front.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	M Lores	Subarea	2
Address:	36 Catoonah St Unit A4	Phone Number	203 438 3083
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 3:03 PM

NAME OF PERSON ALLOWING ENTRY: Dolars York — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 7

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 36 Catoonah Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner:	Christopher Mattern	Subarea	2
Address:	36 Catoonah St Unit B07	Phone Number	719 268 0030
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 1:07 PM

NAME OF PERSON ALLOWING ENTRY: Linda demayo — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 7

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/12/16 Project 66 Catamount 9B Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Ridgefield Fire Dept.	Subarea	2
Address:	6 Catoonah Street	Phone Number	2034312724
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/16/2016 2:23 PM

NAME OF PERSON ALLOWING ENTRY: John Drake — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	800	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 8 — FREQUENCY OF USE:

DISCHARGE LOCATION: Stream outside? — DRAINAGE AREA (sf): 2500

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sump pump connected to sewer pipe

8 floor drains discharge to stream that runs under the building per Fire chief

Pipe on exterior side wall dripping water

PHOTO LOG

NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16 Project 6 Catawah St. Initial J/C.

Five house.



SP Goes to SW

← Catawah St →

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Southern New England Telephone	Subarea	2
Address:	10 Catoonah Street	Phone Number	203 438 0988
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Commercial
		Flat Roof:	Yes
Technicians	TP JC	Date/Time	7/14/2016 9:02 AM

NAME OF PERSON ALLOWING ENTRY: Walter Donovan — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Clean out not located

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/14/16 Project 10 Catoonah St Initial JC/TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Betsy Debany	Subarea	2
Address:	19 Catoonah Street	Phone Number	203 431 6397
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/20/2016 9:44 AM

NAME OF PERSON ALLOWING ENTRY: Betsy — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Downspouts to stream

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-20-16 Project 19 Catoonah St Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Ridgefield Holdings LLC	Subarea	2
Address:	22 Catoonah Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 11:35 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/14 Project 22 Catronah St 3rd Flr. Initial TP/TA



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner:	PRV Properties LLC	Subarea	2
Address:	25 Catoonah Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 11:40 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	6000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

External,inspection only

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/14 Project 25 Cottonwood ST 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	USPS	Subarea	2
Address:	26 Catoonah Street	Phone Number	2034386561
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Commercial
		Flat Roof:	Yes
Technicians	NC TP	Date/Time	5/24/2016 12:15 PM

NAME OF PERSON ALLOWING ENTRY: Walter — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

PHOTO LOG

NOTES: Clean out is most likely under ground

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-24-16 Project 26 Catoonah St. (Post Office) Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Tish Vredenburgh	Subarea	2
Address:	27 Catoonah Street	Phone Number	203 470 6071
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 10:19 AM

NAME OF PERSON ALLOWING ENTRY: Bruce — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	One to sewer, one to un	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	700	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Ejector pump

2 sump pumps, one connected to sewer pipe, one leading to unknown outlet

PHOTO LOG



NOTES:



NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 27 Catoonah Street Initial NC



☆ one sump pump goes to SW / possible 2nd

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Postal Holdings LLC
Address: 28 Catoonah Street
Ridgefield, CT
FM:
Technicians TP TH

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 11:48 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Vacant, external inspection only

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 28 Cottage ST 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Rudy Ruggles	Subarea	2
Address:	33 Catoonah Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/17/2016 9:59 AM

NAME OF PERSON ALLOWING ENTRY: Rudy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Rug — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/17 Project # 33 Catoonah St. Initial NC



Front.

Catoonah Rd.

Drive way

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Steve Zemo	Subarea	2
Address:	39 Catoonah Street	Phone Number	203 830 9235
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/15/2016 7:55 AM

NAME OF PERSON ALLOWING ENTRY: Mike Taylor — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Downspouts in front go to tank that feeds lawn sprinkler system, downspouts in back go to rain garden i

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/15/16 Project 39 Catoonah St. Initial VC/TP



Owner says down spouts are directed to a water reuse program (LEED certified)

Catoonah Rd

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Rosanna Friedman	Subarea	2
Address:	41 Catoonah Street	Phone Number	9178429835
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/17/2016 11:38 AM

NAME OF PERSON ALLOWING ENTRY: Rosanna — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	25	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

PHOTO LOG

NOTES: Pipe exiting home going into ground. Could not determine where it

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-17-16 Project 41 Cabana Ln Str. Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Tom Steiner	Subarea	2
Address:	42 Catoonah Street	Phone Number	914 522 8410
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/20/2016 10:15 AM

NAME OF PERSON ALLOWING ENTRY: Tom — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	850
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-20-16 Project 42 Catoonah St Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner:	Jane Tullo	Subarea	3
Address:	47 Catoonah Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 2:38 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP		HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/14 Project 47 Cottonwood St 3rd Flr. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner: Valerie Schneiderman
Address: 48 Catoonah Street
Ridgefield, CT
FM:
Technicians TP. NC

Subarea 2
Phone Number 203 240 5412
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/17/2016 5:14 PM

NAME OF PERSON ALLOWING ENTRY Valerie
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN Yes
NUMBER OF DRAINS 1
FREQUENCY OF USE
DISCHARGE LOCATION French drain per owne
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 4
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes — DRAINAGE AREA (sf) 900
YARD DRAIN No — DRAINAGE AREA (sf)
DRIVEWAY DRAIN No — DRAINAGE AREA (sf)
WINDOW WELL DRAIN No — DRAINAGE AREA (sf)
OTHER DRAINS No — DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Downspouts to French drains per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/17/16 Project 48 Catboroh St. Initial MC.



All DS Go to French Drains under Grand.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	David Staples	Subarea	2
Address:	49 Catoonah Street	Phone Number	894 5662
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/13/2016 2:01 PM

NAME OF PERSON ALLOWING ENTRY: David — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Dirt — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-13 Project 49 Catoonah Street. Initial VC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Randy Rodriguez	Subarea	2
Address:	50 Catoonah Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/21/2016 9:14 AM

NAME OF PERSON ALLOWING ENTRY: Randy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-21-16 Project 50 Catoonah St. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner:	Rachel Lieberman	Subarea	2
Address:	51 Catoonah Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 2:22 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 51 Catamount ST 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Dwayne Escola	Subarea	2
Address:	52 Catoonah Street	Phone Number	203 438 6818
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/20/2016 9:58 AM

NAME OF PERSON ALLOWING ENTRY: Suzanne — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	300
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-20-16 Project 52 catoonah st Initial ED



EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	St. Mary Catholic School	Subarea	2
Address:	55 Catoonah Street	Phone Number	203 948 8796
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 11:20 AM

NAME OF PERSON ALLOWING ENTRY: Seth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	No	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Plastic bag on clean out. Cracked?

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 55 Catoonah Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner: _____ Subarea 2

Address: 27R Catoonah Street Phone Number _____

Ridgefield, CT # of floors: 2

FM: _____ Building Type: Commercial

Flat Roof: No

Technicians TP. NC Date/Time 5/23/2016 9:52 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT No

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR No

SUMP PUMP

SUMP PUMP No HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN Yes NUMBER OF DRAINS 2 FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? Yes LOCATION Above Basem

DRAINAGE AREA (sf) _____ ELEVATION (ft) 1

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

3 storm sewer drains in lot

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 27 R. Catawba Street Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Pilar	Subarea	2
Address:	30 & 32 Catoonah Street	Phone Number	203 770 8887
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 12:00 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Dirt No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? Yes LOCATION Above Basem

DRAINAGE AREA (sf) ELEVATION (ft) 3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project SD Outfall 3rd Att. Initial TP/TL



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 32 Catoonah Street Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Kristen Bryson	Subarea	2
Address:	31A Catoonah Street	Phone Number	203 561 0355
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 10:06 AM

NAME OF PERSON ALLOWING ENTRY: Anne Carcaterra — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	600	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Positive connection sump pump to sewer

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

PHOTO LOG

NOTES:

NOTES:

PHOTOS 3 & 4

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23/16 Project 31 A Catawah Street Initial NC



X Sump pump Goes to SW

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Aline Lawrence	Subarea	2
Address:	31B Catoonah Street	Phone Number	203 438 8583
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 3:58 PM

NAME OF PERSON ALLOWING ENTRY: Aline — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Could not locate clean out

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 31B Cajoonah ST Initial JC/JD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Russell Sturges	Subarea	2
Address:	31C Catoonah Street	Phone Number	203 297 1227
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/30/2016 11:45 AM

NAME OF PERSON ALLOWING ENTRY: Russell — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-30-16 Project 31 App C Catoonah St Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner:	Lawrence McSwiggan	Subarea	2
Address:	33B Catoonah Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 1:09 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 33 Catoonah Unit 8 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Jim Grimley	Subarea	2
Address:	34A Catoonah Street	Phone Number	914 325 5883
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/17/2016 10:35 AM

NAME OF PERSON ALLOWING ENTRY: Jim — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/17 Project 34 Colonial St. Initial



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Arseni Radomyselski	Subarea	2
Address:	34B Catoonah Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 1:16 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 34-B Catamaran ST 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	William McGarry	Subarea	2
Address:	37R Catoonah Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 1:59 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/14 Project 37R CATOOMAH ST 3rd Att. Initial TP/JH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Emanuele Bergagnini
Address: 39A Catoonah Street
Ridgefield, CT
FM:
Technicians TP TH

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 2:03 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1600
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Possible sump pump - outlet pipe visible

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/14 Project 39A CATBONAH ST 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Melanie Lumellau	Subarea	2
Address:	39B Catoonah Street	Phone Number	914-649-5456
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 9:20 AM

NAME OF PERSON ALLOWING ENTRY: Melanie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	6000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 39B Catoonah St. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Melissa Torchia	Subarea	2
Address:	43A Catoonah Street	Phone Number	4142188648
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/SS	Date/Time	4/29/2016 8:32 AM

NAME OF PERSON ALLOWING ENTRY: Melissa — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Finished basement cannot locate sewer clean out

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4/29/16 Project 43 A Catawah Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jean Mooney and John Mooney	Subarea	2
Address:	43B Catoonah Street	Phone Number	9252237961
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/17/2016 11:24 AM

NAME OF PERSON ALLOWING ENTRY: Jean — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/17 Project 43 B Catawnah St. Initial NC



All DS Are to Ground No usable Direction

Front.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Steven Risbridger	Subarea	2
Address:	44B Catoonah Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 2:12 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP		HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 44 B CATAUMAH ST 3rd Flr. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Lora Guerrino	Subarea	2
Address:	36 Catoonah Street E18	Phone Number	9143100620
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/NC	Date/Time	5/2/2016 1:29 PM

NAME OF PERSON ALLOWING ENTRY: Lora — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2 Project 36 Colonial St #18 (E18) Initial AP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

81 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner: Per Holtman
Address: 36 Catoonah Street Unit 12
Ridgefield, CT
FM:
Technicians: TP NC

Subarea: 2
Phone Number: 203 244 5904
# of Floors: 2
Building Type: Res
Flat Roof: No
Date/Time: 5/23/2018 1:12 PM

NAME OF PERSON ALLOWING ENTRY: Per
CONFIRM OVER 18 YRS: Yes
BASEMENT: Yes
WATER IN BASEMENT: No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?: No
TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP: Yes
DISCHARGE LOCATION: Unknown
SUMP PIPE HARD PIPED: Yes
DRAINAGE AREA (sf): 350
HORSEPOWER OF PUMP:
PUMP CAPACITY(gpm):
FREQUENCY OF CYCLING:
IS PUMP ALWAYS ADEQUATE:
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No
NUMBER OF DRAINS:
FREQUENCY OF USE:
DISCHARGE LOCATION:
DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No
FREQUENCY OF USE:
DISCHARGE LOCATION:
DISTANCE FROM SJ (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes
IS THE CLEANOUT SEALED?: Yes
DRAINAGE AREA (sf):
OTHER INFLOW SOURCES:
ELEVATION OF SEWER CONNECTION CLEANOUT:
LOCATION: Above Basem
ELEVATION (ft): 3

EXTERNAL HOUSE INSPECTION: Yes
DOWNSPOUTS ENTER GROUND: Yes — DRAINAGE AREA (sf):
YARD DRAIN: Yes — DRAINAGE AREA (sf): 500
DRIVEWAY DRAIN: No — DRAINAGE AREA (sf):
WINDOW WELL DRAIN: No — DRAINAGE AREA (sf):
OTHER DRAINS: No — DRAINAGE AREA (sf):
EXPERIENCED PONDING ON PROPERTY DURING RAIN?: No

ADDITIONAL COMMENTS:

Black pipe connected to sewer, could not see where it goes
Sump pump pipe going in direction of sewer pipe but could not see where it went behind wall
Sump pump outlet pipe on outside of neighboring unit (13), could be shared outlet for units 12 and 13

PHOTO LOG



NOTES:



NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitorin
Pipeline Service
Operations & Maintenanc

Date 5/23 Project 36 Cotswold Street B17 Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner: Mary Ciarcia
Address: 36 Catoonah Street Unit 13
Ridgefield, CT
FM:
Technicians TP. NC

Subarea 2
Phone Number 203 733 2364
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/23/2016 1:06 PM

NAME OF PERSON ALLOWING ENTRY Mary
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 2
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf)
YARD DRAIN Yes DRAINAGE AREA (sf) 300
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN Yes DRAINAGE AREA (sf) 8
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 36 Catawnah # B13 Initial AC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Barbara Hillary	Subarea	2
Address:	36 Catoonah Street Unit 14	Phone Number	203 894 8154
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/13/2016 2:47 PM

NAME OF PERSON ALLOWING ENTRY: Barbara — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	300
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	8
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-13 Project 36 Catoonah St #14 Initial VC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	John Sfondrini	Subarea	2
Address:	36 Catoonah Street Unit 16	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 1:30 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

3rd Flr.

Date 7/19/16 Project 36 Cottonwood St Unit 16 Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Anita Baron	Subarea	2
Address:	36 Catoonah Street Unit 6	Phone Number	203 438 5593
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 11:33 AM

NAME OF PERSON ALLOWING ENTRY: Carine — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 36 Al Catoonah St Initial VC / TP



Catoonah St

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Charles Knoche	Subarea	2
Address:	36 Catoonah Street Unit A	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 1:22 PM

NAME OF PERSON ALLOWING ENTRY: Carol Gahagen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 36 Catron ST Unit 1 Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Anita Lindsey	Subarea	2
Address:	36 Catoonah Street Unit A2	Phone Number	203 244 5656
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 11:25 AM

NAME OF PERSON ALLOWING ENTRY: Anita Lindsey — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 36 Catoonah Street #12 Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	R Franziska	Subarea	2
Address:	36 Catoonah Street Unit A3	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 11:20 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT No

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 36 Cabonah #A3 Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Jim Cooper	Subarea	2
Address:	36 Catoonah Street Unit A5	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 11:14 AM

NAME OF PERSON ALLOWING ENTRY: Jim Cooper — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 36 Catoonah #A5 Initial N.C.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Suchi LLC	Subarea	2
Address:	36 Catoonah Street Unit B10	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 1:41 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP		HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 36 ~~Cottonwood~~ ST Unit 10 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Tom Maloney	Subarea	2
Address:	36 Catoonah Street Unit B11	Phone Number	203 894 1753
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 11:00 AM

NAME OF PERSON ALLOWING ENTRY: Tom — CONFIRM OVER 18 YRS: No

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Storm sewer in lot

Downspouts to wetlands in back per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 36 Catoonah Street #B11 Initial MC.



EP For a s/op sink goes to SW.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	John Baldaserini	Subarea	2
Address:	36 Catoonah Street Unit B15	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 10:48 AM

NAME OF PERSON ALLOWING ENTRY: Harry — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	8
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 36 Catoonah #B15 Street. Initial NC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner:	Christopher Mattern	Subarea	2
Address:	36 Catoonah St Unit B07	Phone Number	719 268 0030
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 1:07 PM

NAME OF PERSON ALLOWING ENTRY: Linda demayo — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/12/16 Project 66 Cedarwood 9B Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Mary Putnam	Subarea	2
Address:	28 Griffith	Phone Number	3
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/24/2016 5:07 PM

NAME OF PERSON ALLOWING ENTRY: Mary — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement / finished — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	4000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	1000
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-24-16 Project 28 Griffith Lane Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Paul Hanley	Subarea	2
Address:	31 Griffith	Phone Number	2035540828
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/24/2016 4:20 PM

NAME OF PERSON ALLOWING ENTRY: Paul — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	To ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-24-16 Project 31 Griffith Lane Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Gloria Sharkany	Subarea	2
Address:	13 Griffith Lane	Phone Number	2034385026
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/12/2016 9:38 AM

NAME OF PERSON ALLOWING ENTRY: Gloria — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 13 Griffith Lane. Initial SS



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Joan Rodriguez	Subarea	2
Address:	15 Griffith Lane	Phone Number	248 842 7345
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/17/2016 12:09 PM

NAME OF PERSON ALLOWING ENTRY: Joan — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground?	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	2200
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Gutters drain to yard drain per owner

PHOTO LOG

NOTES: Possible sump pump outlet

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/17/2016 Project 15 Griffith Lane Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	John gilchrist	Subarea	2
Address:	20 Griffith Lane	Phone Number	4384753
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/12/2016 9:25 AM

NAME OF PERSON ALLOWING ENTRY: John — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 20 Griffith Lane Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	David Trustee	Subarea	2
Address:	25 Griffith Lane	Phone Number	2033131551
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/24/2016 5:15 PM

NAME OF PERSON ALLOWING ENTRY: David — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	1500
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-24-16 Project 25 Griffith Lane Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Edwin Phelps	Subarea	2
Address:	27 Griffith Lane	Phone Number	203 403 3451
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP	Date/Time	5/16/2016 1:53 PM

NAME OF PERSON ALLOWING ENTRY: Edwin — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	480	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Sump pumps drain to outlet pipe and into yard drain in backyard per owner

2 sump pumps in basement

Gutters drain under yard to back per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16 Project 27 Griffith Initial NC



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Robert J Nossan	Subarea	2
Address:	29 Griffith Lane	Phone Number	203 438 0657
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/12/2016 9:51 AM

NAME OF PERSON ALLOWING ENTRY: Robert — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 29 Griffith Lane Initial S.S



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Lauri Hill	Subarea	2
Address:	30 Griffith Lane	Phone Number	203 438 7744
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 10:49 AM

NAME OF PERSON ALLOWING ENTRY: Lauri — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 30 Griffith Lane. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Joseph Lombardo
Address: 8 Griffith Ln
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 1
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 10:36 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1200
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project Griffith Lane Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: William McNamara
Address: 16 Griffith Ln
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 10:31 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1800

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project griffith Lane Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Lauri Hill	Subarea	2
Address:	30 Griffith Lane	Phone Number	203 438 7744
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 10:49 AM

NAME OF PERSON ALLOWING ENTRY: Lauri — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 30 Griffith Lane. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Meredith Mulhern	Subarea	2
Address:	34 Griffith Ln	Phone Number	201 981 0405
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/16/2016 4:25 PM

NAME OF PERSON ALLOWING ENTRY: Meredith — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Rug and cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

2 sump pumps, 2 separate discharge pipes exiting house, discharge to wetlands in back of property per

Clean out probably behind wall, could not see it

Mostly finished basement

PHOTO LOG

NOTES: One of 2 sump pump pipes on exterior

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16 Project #34 Griffith. Initial JC.



14 completed.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Michael Scally	Subarea	3
Address:	36 Griffith Lane	Phone Number	203 526 5454
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/30/2016 1:29 PM

NAME OF PERSON ALLOWING ENTRY: Michael — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement/carpet — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	Yes	DRAINAGE AREA (sf)	900
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Patio drains go to wetlands

Driveway drain goes to catch basin in neighbor's driveway which drains to back wetlands

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-30-16 Project 36 Griffith Lane Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Kishinev Ranade
Address: 37 Griffith Ln
Ridgefield, CT
FM:
Technicians CD / SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 10:22 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1800
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 36 griffith Lane Initial CD/SY



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY [X] Permitted [ ] Deffered [ ] Refused

GENERAL INFORMATION 1st Attempt 2nd Attempt 3rd Attempt

Owner:	Robert Thuss	Subarea	2
Address:	27B Griffith Ln	Phone Number	203 431 7994
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. JH	Date/Time	5/19/2016 8:01 AM

NAME OF PERSON ALLOWING ENTRY: Jean Anne — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Finished basement

EST
Associates, Inc.

Environmental Monito
Pipeline Servi
Operations & Maintena

Date 5/18/16 Project 27B Griffith Ln. Initial JAL



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Alex Wattles	Subarea	2
Address:	62 High Ridge Ave	Phone Number	914 486 1914
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/17/2016 12:50 PM

NAME OF PERSON ALLOWING ENTRY: Alex Wattles — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	15	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1600
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sump pump pipe to yard per owner - discharge pipe visible in yard

Gutters to pipes in yard per owner, pipes visible in yard

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/17/2016 Project # 62 High Ridge Ave. Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Dennis Janson	Subarea	2
Address:	72 High Ridge Road	Phone Number	203 438 9602
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/17/2016 1:08 PM

NAME OF PERSON ALLOWING ENTRY: Dennis — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Ground surface — DRAINAGE AREA (sf): 800

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES: Slop sink to sewer

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Floor drain to ground surface per owner

Downspouts to French drain per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/17/16 Project 72 High Ridge Ave. Initial NC



* slop sink to sewer.

Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Greg Pflaum	Subarea	2
Address:	106 High Ridge Ave	Phone Number	203 403 3363
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/16/2016 12:59 PM

NAME OF PERSON ALLOWING ENTRY: Linda — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown, yard per own	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

2 sump pumps,one in basement,one in garage. SP in garage connected to gutter, discharge location un

SP in basement : pipe exits to outside, discharge appeared to be nearby, could not confirm

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16. Project 106 High Ridge Initial AC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner:		Subarea	2
Address:	108 High Ridge Ave	Phone Number	203 403 5121
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/19/2016 10:55 AM

NAME OF PERSON ALLOWING ENTRY: Amanda — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Front yard / Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

PHOTO LOG



NOTES: Second Sump pump in house is connected to the sewer

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 108 high Ridge Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Allan Rowe	Subarea	2
Address:	110 High Ridge Ave	Phone Number	6176998526
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/16/2016 12:39 PM

NAME OF PERSON ALLOWING ENTRY: Allan — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES: Washer dryer pipe running into sewer line

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Driveway drains on common road for 106 108 and 110

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16 Project 110 High Ridge Road Initial VC.





DWD are in a Common Access Road

houses 106, 108, & 110 All use Access Road

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Karen Bollerman
Address: 111 High Ridge Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 3
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 11:09 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 3000
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 250
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 111 High Ridge cove Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | X **3rd Attempt**

Owner:	Mintak Joo	Subarea	2
Address:	112 High Ridge Ave	Phone Number	NA
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/19/2016 10:46 AM

NAME OF PERSON ALLOWING ENTRY: Jake Baldaserini — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Back yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	250
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	50

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Other drain is a stairwell drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 112 high Ridge ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Aileen Egan	Subarea	2
Address:	113 High Ridge Ave	Phone Number	203 438 6812
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/16/2016 12:19 PM

NAME OF PERSON ALLOWING ENTRY: Aileen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	1400
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16 Project 113 High Ridge Road Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Michael Modica
Address: 123 High Ridge Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: Yes
Date/Time 7/19/2016 11:15 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 123 High Ridge Rd Initial CD/SB



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Rebecca Ciota
Address: 125 High Ridge Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 11:21 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1400
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 125 High Ridge Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jeffrey Wetzel	Subarea	2
Address:	126 High Ridge Ave	Phone Number	203 403 3245
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/16/2016 11:57 AM

NAME OF PERSON ALLOWING ENTRY: Jeffrey — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16 Project 126 High Ridge Initial JC



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sue Lieberbach	Subarea	2
Address:	129 High Ridge Ave	Phone Number	203 444 5238
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/16/2016 11:17 AM

NAME OF PERSON ALLOWING ENTRY: Sue — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16. Project 129 High Ridge Road. Initial NC



All Ground Down Spark Unknown Direction

Front.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Steve Seagriff	Subarea	2
Address:	141 High Ridge Avenue	Phone Number	203 431 9040
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 10:06 AM

NAME OF PERSON ALLOWING ENTRY: Steve — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	600	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1800
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/11 Project 143 High Ridge Rd Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Lori Rahlfs	Subarea	2
Address:	144 High Ridge Ave	Phone Number	203 403 3970
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/16/2016 11:02 AM

NAME OF PERSON ALLOWING ENTRY: Lori — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16 Project 144 High Ridge Initial NC



All DS are to Ground. Direction unknown.

Front.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Margaret Powell
Address: 146 High Ridge Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 11:41 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1200
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 146 high Ridge Rd Initial CO/SR



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Kathleen Graham
Address: 148 High Ridge Ave
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 11:38 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/8/16 Project 148 high Ridge Rd Initial CG/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Elsie Craig	Subarea	2
Address:	150 High Ridge Ave	Phone Number	203 438 2278
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/12/2016 11:23 AM

NAME OF PERSON ALLOWING ENTRY: Elsie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Finished basement, pipe exposed but cannot locate clean out

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 150 High Ridge Ave Initial S.S.



No Cleanout found, Pipe is exposed
But Basement is finished.

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Kathleen Lang	Subarea	2
Address:	152 High Ridge Ave	Phone Number	203 438 3399
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/16/2016 2:54 PM

NAME OF PERSON ALLOWING ENTRY: Kathleen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	Yes	DRAINAGE AREA (sf)	900
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16 Project 152 High Ridge Road. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: John Maiorano
Address: 154 High Ridge Ave
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 11:52 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/10/16 Project 154 high Ridge ave Initial CD/SD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Julie Mayette	Subarea	
Address:	159 High Ridge Road	Phone Number	610 235 6417
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/30/2016 10:00 AM

NAME OF PERSON ALLOWING ENTRY: Jamie Grossman — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-30-16. Project 159 High Ridge Ave. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Eva Chan	Subarea	2
Address:	42 High Ridge Avenue	Phone Number	2034381933
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/3/2016 2:15 PM

NAME OF PERSON ALLOWING ENTRY: Eva — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Unknown
DISCHARGE LOCATION	Ground to surface	PUMP CAPACITY(gpm)	Unknown
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Unknown
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	Unknown

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	4500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1100
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

2 sump pumps, one leads to ground surface, other leads to driveway drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 42 High Ridge Ave Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Howard Turner	Subarea	2
Address:	50 High Ridge Avenue	Phone Number	203 438 9242
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/11/2016 3:16 PM

NAME OF PERSON ALLOWING ENTRY: Howard — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Clean out in back yard close to house

All downspouts to outlets in backyard (visible) per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16 Project 50 High Ridge Ave. Initial NC



No transit inside the house.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	William Diamond	Subarea	2
Address:	63 High Ridge Avenue	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/18/2016 3:14 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP		HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Exterior inspection only

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-16-18 Project 63 High Ridge Ave. Initial NE

3rd Attempt No interior



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner: Robert Bakish
Address: 74 High Ridge Avenue
Ridgefield, CT
FM:
Technicians TP NC

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/11/2016 3:46 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS Yes

BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR Cement
No

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION One unknown, one poss
SUMP PIPE HARD PIPED Yes
DRAINAGE AREA (sf) 350

HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN Yes NUMBER OF DRAINS 1 FREQUENCY OF USE
DISCHARGE LOCATION Unknown DRAINAGE AREA (sf) 150

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE
DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)

ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500
YARD DRAIN Yes DRAINAGE AREA (sf) 250
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 2600
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

One sump pump had no visible outlet but appeared to be exiting to ground or surface and not the sewer
One sump pump connected to sewer

PHOTO LOG

NOTES: Sump pump connected to sewer

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16 Project 74 High Ridge Ave. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Steve and Lorraine Kendall	Subarea	2
Address:	82 High Ridge Avenue	Phone Number	203 994 6784
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 11:53 AM

NAME OF PERSON ALLOWING ENTRY: Fred Whipple — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Downspouts drain to storm sewer on King Lane per property manager

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 82 High ridge Rd Initial CO



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Kim Daley	Subarea	2
Address:	115 High Ridge Avenue	Phone Number	203 431 6208
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 9:37 AM

NAME OF PERSON ALLOWING ENTRY: Kim — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 400

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	600
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 115 High Ridge Ave. Initial AC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Elizabeth Montanari	Subarea	2
Address:	121 High Ridge Avenue	Phone Number	203 313 9523;
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 9:59 AM

NAME OF PERSON ALLOWING ENTRY Elizabeth CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	200	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN Yes NUMBER OF DRAINS 1 FREQUENCY OF USE

DISCHARGE LOCATION Unknown DRAINAGE AREA (sf) 200

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 121 High Ridge Ave Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner: Bert Bowler
Address: 128 High Ridge Avenue
Ridgefield, CT
FM:
Technicians TP. SS

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/12/2016 10:19 AM

NAME OF PERSON ALLOWING ENTRY Adriana
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR Cement
No

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 6
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 1700
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
Ejector pump in basement

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/14 Project 128 High Ridge Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Dave Schupmann	Subarea	2
Address:	139 High Ridge Ave	Phone Number	2037317844
	Ridgefield, CT	# of floors:	2M
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP SS	Date/Time	5/12/2016 10:51 AM

NAME OF PERSON ALLOWING ENTRY: Dave — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished carpet — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 139 High Ridge Ave Initial S.S



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner:	Steve Seagriff	Subarea	2
Address:	141 High Ridge Avenue	Phone Number	203 431 9040
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 10:06 AM

NAME OF PERSON ALLOWING ENTRY: Steve — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	600	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT:

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1800
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitor
Pipeline Servic
Operations & Maintenan

Date 7-12-16 Project 141 High Ridge Ave Initial



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Brian Maltas	Subarea	2
Address:	145 High Ridge Avenue	Phone Number	203 438 6708
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 12:56 PM

NAME OF PERSON ALLOWING ENTRY: Brian — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	0.5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

PHOTO LOG

NOTES: "Room" in driveway - hole below ground

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 145 High Ridge Ave. Initial NC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Lorraine Trapani	Subarea	2
Address:	153 High Ridge Avenue	Phone Number	203 581 2540
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 4:15 PM

NAME OF PERSON ALLOWING ENTRY: Lorraine — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 153 Highridge Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Thomas Savundranayagam	Subarea	2
Address:	160 High Ridge Avenue	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 1:38 PM

NAME OF PERSON ALLOWING ENTRY Thomas CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN Yes FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 160 High Ridge Ave. Initial JC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Michael Elliott	Subarea	2
Address:	161 High Ridge Avenue	Phone Number	203 395 1847
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/25/2016 8:59 AM

NAME OF PERSON ALLOWING ENTRY: Michael — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	1000
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 161 Highridge Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Herbert Elliott	Subarea	2
Address:	163 High Ridge Avenue	Phone Number	203 438 7255
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 9:48 AM

NAME OF PERSON ALLOWING ENTRY: Herbert — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Downspouts to dry well per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-3-16 Project 163 Highridge Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Anita D'Onofrio	Subarea	2
Address:	55 High Ridge Avenue Guest house	Phone Number	203 431 0076
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/16/2016 3:51 PM

NAME OF PERSON ALLOWING ENTRY: Terry — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2700
YARD DRAIN	Yes	DRAINAGE AREA (sf)	3700
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

Sump pump into floor drain, unknown where it discharges

Per caretaker, downspouts drain to storm water outlet in back yard

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16. Project 55 High Ridge (Guest House) Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Anita D'Onofrio	Subarea	2
Address:	55 High Ridge Ave	Phone Number	203 431 0076
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/16/2016 3:18 PM

NAME OF PERSON ALLOWING ENTRY: Terry — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface per care	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1100	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2700
YARD DRAIN	Yes	DRAINAGE AREA (sf)	800
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	700
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

2 Ejector pumps, clean out not found, likely behind finished wall

Finished basement

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/16 Project 55 High Ridge (Main House) Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Andrei Ganea	Subarea	2
Address:	77 High Ridge Road	Phone Number	971 601 2131
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/11/2016 4:09 PM

NAME OF PERSON ALLOWING ENTRY: Andrei — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Two to sewer, one to do	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1100	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 600

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	120
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Two sump pumps to sewer

One sump pump into downspout

One sump pump to unknown

Well inside house near back exit

PHOTO LOG

NOTES: Black thin pipe is from a sump pump

NOTES: 2nd sump pump to sewer

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16 Project 77 High Ridge Ave. Initial JC



2 = ✱ SP Connected to SW clean out.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Richard Jabara	Subarea	2
Address:	87 High Ridge Road	Phone Number	
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/18/2016 3:37 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP		HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3500
YARD DRAIN	Yes	DRAINAGE AREA (sf)	500
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2300
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

No interior inspection, third attempt, owner did not permit us to enter

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 87 High Ridge Ave. Initial NC

3rd Attempt No interior. (house keeper let us walk around Perimeter)



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Peter Jacullo	Subarea	2
Address:	161 High Ridge Road	Phone Number	203 894 8981
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 3:24 PM

NAME OF PERSON ALLOWING ENTRY: Peter — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 2 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown, storm sewe — DRAINAGE AREA (sf): 900

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1200
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

All downspouts, driveway drains and floor drains to storm sewer per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 61 High Ridge Ave. Initial VC/TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Andrei Ganea	Subarea	2
Address:	77 High Ridge Road Pool House	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/11/2016 4:37 PM

NAME OF PERSON ALLOWING ENTRY: Andrei — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown pipe	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	230	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	25

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sump pump connected to pipe in basement that was not the sewer. Possibly a pipe for the pool.
Stairwell drain in back

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16 Project 77 High Ridge Ave. Initial JC



2 = ✱ SP Connected to SW clean out.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Mick bresnan	Subarea	2
Address:	162 Highridge Ave	Phone Number	978 559 9554
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 2:34 PM

NAME OF PERSON ALLOWING ENTRY: Chad shepherd — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	To driveway surfaces	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1200	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 200

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	1200

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Other drain is a French drain in basement.

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 162 High Ridge Ave Initial TP



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Angela Tzamouranis	Subarea	2
Address:	1 Jackson Court	Phone Number	203 403 5252
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. SS	Date/Time	5/12/2016 8:32 AM

NAME OF PERSON ALLOWING ENTRY: Angela — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

4 yard drains

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/12/16 Project 1 Jackson Ct. Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Craig Wilson	Subarea	2
Address:	7 Jackson Court	Phone Number	203 244 5796
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/11/2016 2:13 PM

NAME OF PERSON ALLOWING ENTRY: Craig — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	320	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	Yes	DRAINAGE AREA (sf)	400
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sump pump in garage exits to ground in front

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16. Project 7 Jackson Court. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Bart Patty	Subarea	2
Address:	8 Jackson Court	Phone Number	203 438 7800
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/11/2016 2:25 PM

NAME OF PERSON ALLOWING ENTRY: Bart — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	600	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 2 — FREQUENCY OF USE:

DISCHARGE LOCATION: Sump pump — DRAINAGE AREA (sf): 600

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

1st Sump pump connects to roof gutter, goes under yard and out

2nd sump pump connects to a 2nd roof gutter

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-11-16. Project 8 Jackson Court Initial NC



YD

- Sump pump went to Dan sparks

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Liles Lam LLC	Subarea	2
Address:	11 Jackson Court	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	2
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 2:33 PM

NAME OF PERSON ALLOWING ENTRY: Stephanie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	3000
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5·31 Project 11 Jackson Court Initial MC



YD

No Down Sports.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jesse Lee Memorial Church Carriage House	Subarea	2
Address:	21 King Lane	Phone Number	203 438 8791
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/14/2016 9:25 AM

NAME OF PERSON ALLOWING ENTRY: Dale — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Could not locate clean out

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 2/18/16 Project 21 King Lane Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Betty Demirjian	Subarea	2
Address:	27 King Lane	Phone Number	203 438 6924
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/19/2016 12:57 PM

NAME OF PERSON ALLOWING ENTRY: Betty — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished and cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	2800
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump in basement

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-14-16 Project 27 King Ln Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Joseph	Subarea	2
Address:	44 King Ln	Phone Number	NA
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Reds
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/18/2016 9:51 AM

NAME OF PERSON ALLOWING ENTRY: Marcella — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	250
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 44 King Lane 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY [X] Permitted [ ] Deffered [ ] Refused

GENERAL INFORMATION [ ] 1st Attempt [ ] 2nd Attempt [ ] 3rd Attempt

Owner: Ridgefield Equities LLC
Address: 455 Main
Ridgefield, CT
FM:
Technicians NC TP

Subarea 2
Phone Number 2034315850
# of floors: 2
Building Type: Commercial
Flat Roof: Yes
Date/Time 5/24/2016 12:51 PM

NAME OF PERSON ALLOWING ENTRY Aries
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION Unknown
SUMP PIPE HARD PIPED Yes
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT No
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

PHOTO LOG



NOTES: Both sump pumps lead to the gray pipe and disappear into concret

NOTES:

PHOTOS 3 & 4

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-24-16 Project 455 Main St. Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Annette Obrien
Address: 139 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 2:33 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 139 main St Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Margaret Marconi
Address: 145 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 2:36 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION Left side of the house
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)

HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection
Sump pump discharge pipe coming out of the left side of the house

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 145 main Street Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Annette Obrien
Address: 267 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 3:11 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 3500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 267 Main Street Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Judith Maguire
Address: 305 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 3:19 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 305 main Street Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Michael Butler
Address: 321 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 9:31 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 321 main St Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Pearl Broms
Address: 323 Main St
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 9:28 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 323 main ST Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Brian Sleigh
Address: 325 Main St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 9:20 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/15 Project 325 main Street Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jane Scarborough	Subarea	2
Address:	127 Main Street	Phone Number	203 733 6177
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 3:08 PM

NAME OF PERSON ALLOWING ENTRY: Jane — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	One to sewer, one surfa	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

One sump pump connected to sewer, one drains to ground surface

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 127 Main St Initial CD



*
2 sump pumps hard pvc pipe
1 goes into sewer clean out
1 goes into yard

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Roger Keller	Subarea	2
Address:	149 Main Street	Phone Number	203 894 8393
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 8:47 AM

NAME OF PERSON ALLOWING ENTRY: Roger — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	750	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 4 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 149 Main St Initial CJ



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	265 Main Street LLC	Subarea	2
Address:	265 Main Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 2:28 PM

NAME OF PERSON ALLOWING ENTRY: Josh — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 265 main st Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Glenn Cooper	Subarea	2
Address:	275 Main Street	Phone Number	212 300 3631
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 2:36 PM

NAME OF PERSON ALLOWING ENTRY: Glenn — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/25/16 Project 275 main st Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	St. Stephen's Episcopal	Subarea	2
Address:	353 Main Street	Phone Number	203 438 3789
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Church
		Flat Roof:	Yes
Technicians	TP CD	Date/Time	6/10/2016 5:16 PM

NAME OF PERSON ALLOWING ENTRY: Paul Lyons — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 3 — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf): 90

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: Yes — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2300
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	45

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-9-16 Project 353 mainst Saint stephen Episcopal church Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	385 Main Street LLC	Subarea	2
Address:	385 Main Street	Phone Number	203 438 2661
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	Yes
Technicians	TP SP	Date/Time	6/22/2016 1:55 PM

NAME OF PERSON ALLOWING ENTRY: Gerald Rabin — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Internal roof drain	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	550	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS — FREQUENCY OF USE

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-22-16 Project 385 main ST Initial TP/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Carnall Insurance LLC	Subarea	2
Address:	401 Main Street	Phone Number	
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Commercial
		Flat Roof:	Yes
Technicians	TP NC	Date/Time	6/20/2016 1:58 PM

NAME OF PERSON ALLOWING ENTRY: Catherine Petz — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: Yes — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-20 Project 401 Main Street Initial NC



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	85 Prospect Street LLC	Subarea	2
Address:	409 Main Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/20/2016 2:10 PM

NAME OF PERSON ALLOWING ENTRY: Goia Ingram (Trilliu — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	110	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	22000
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Positive connection sump pump to sewer

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-20 Project 409 Main Street Initial NC



* Sump Pump Goes to SW

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Ridgefield Equities LLC	Subarea	2
Address:	451 Main Street	Phone Number	2034384771
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Commercial
		Flat Roof:	Yes
Technicians	NC TP	Date/Time	5/24/2016 11:40 AM

NAME OF PERSON ALLOWING ENTRY: Jessica — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES: Sump pump, ice machine, walk in cooler, and more not visible

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	3000

EXPERIENCED PONDING ON PROPERTY DURING RAIN?:

ADDITIONAL COMMENTS:

Has a storm drain in parking lot

PHOTO LOG



NOTES:



NOTES:

PHOTOS 1 & 2

PHOTO LOG



NOTES:

NOTES: Sump pump with several outlets dumping into sump pump

PHOTOS 3 & 4

PHOTO LOG



NOTES: Sump pump hard piped to sewer

NOTES: This pipe comes from the ice machine and the walk in cooler. And

PHOTOS 5 & 6

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-24-16 Project 451 Main St. (Ancient Mariner) Restaurant/Bar Initial T.P.



Front

* Positive connection sump pump to sewer

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Ridgefield Equities LLC	Subarea	2
Address:	453 Main Street	Phone Number	2034386308
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	Yes
Technicians	NC TP	Date/Time	5/24/2016 12:40 PM

NAME OF PERSON ALLOWING ENTRY: Grace — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	2000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/24/16 Project 453 Main St. (Aristo Nail Spa) Initial T.P.



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Ridgefield Equities LLC	Subarea	2
Address:	457 Main Street	Phone Number	2034388900
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	Yes
Technicians	NC TP	Date/Time	5/24/2016 1:03 PM

NAME OF PERSON ALLOWING ENTRY: Lily — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-24-16 Project 457 Main St. (Limes Nails Spa) Initial T.P.



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	CVS	Subarea	2
Address:	467 Main Street	Phone Number	203
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Commercial
		Flat Roof:	Yes
Technicians	NC TP	Date/Time	5/24/2016 11:08 AM

NAME OF PERSON ALLOWING ENTRY: Alex — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer pipe	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	5000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES: Yes

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Found a large sump pump connected to SW

PHOTO LOG

NOTES: Hard piped sump pump heading to sewer

NOTES:

PHOTOS 1 & 2

PHOTO LOG

NOTES:

NOTES: This is catching dripping water. Looks connected to SW

PHOTOS 3 & 4

PHOTO LOG

NOTES:

NOTES:

PHOTOS 5 & 6

EST
Associates, Inc.

Environmental Monitorir
Pipeline Service
Operations & Maintenanc

Date 5/24/16 Project 467 Main St. (CVS) Initial T.P.



Front

* Positive connection sump pump to sewer

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	509 Main LLC	Subarea	2
Address:	509 Main Street	Phone Number	215 317 1812 (owner's sister)
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/28/2016 9:17 AM

NAME OF PERSON ALLOWING ENTRY: Katie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	225	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

PHOTO LOG

NOTES: Sump pump inside garbage pail. Could not determine if bottom of

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 509 Main Street Initial MC



Found a EP/SP connected to SW. (Does not seem to be Active But it is connected.)

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Judith McGuire	Subarea	2
Address:	305 B Main Street	Phone Number	2034383995
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/24/2016 2:20 PM

NAME OF PERSON ALLOWING ENTRY: Marry Bigger — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

There was a pit for a sump pump. But no sump pump was inside and active

EST
Associates, Inc.

Environmental Monitori
Pipeline Servic
Operations & Maintenan

Date 5-24-16 Project 305B Main St. Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-822
www.estassoci

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:
Address: 463 Main Street - Steve's Bagels
Ridgefield, CT
FM:
Technicians TP NC

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 6/13/2016 3:17 PM

NAME OF PERSON ALLOWING ENTRY John
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Tile

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 1
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND		DRAINAGE AREA (sf)	
YARD DRAIN		DRAINAGE AREA (sf)	
DRIVEWAY DRAIN		DRAINAGE AREA (sf)	
WINDOW WELL DRAIN		DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:
2 ejector pumps

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-13 Project 463 Main St. (Stans Bagels) Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Alan Lee	Subarea	2
Address:	461 Main Street - Wild Ginger	Phone Number	203 431 4588
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/13/2016 3:31 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN Yes NUMBER OF DRAINS 1 FREQUENCY OF USE

DISCHARGE LOCATION Unknown DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

EST Associates, Inc.

wd. 8: 33- Bally

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-13 Project 461 Main St (with Ginger) Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	GAJ LLC	Subarea	2
Address:	411B Main Street (Planet Pizza)	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/20/2016 2:34 PM

NAME OF PERSON ALLOWING ENTRY: Dominic — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 3 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 300

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 8

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-20 Project 411 Main St. Initial N.C



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jane Scarborough	Subarea	2
Address:	127 Main Street Cottage	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 3:21 PM

NAME OF PERSON ALLOWING ENTRY: Jane — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	30	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	800
YARD DRAIN	Yes	DRAINAGE AREA (sf)	500
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Stairwell drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 127 main st cottage in back Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Pat Crehan	Subarea	2
Address:	181 Main Street Guest House	Phone Number	203 438 0441
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 10:05 AM

NAME OF PERSON ALLOWING ENTRY: Pat — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Cannot locate cleanout

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 181 main st guest house Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jesse Lee Memorial Church	Subarea	2
Address:	207 Main Street main Church building	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/25/2016 1:46 PM

NAME OF PERSON ALLOWING ENTRY: Dale — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Large window drain at front

Possible sump pump (or ejector pump?) in boiler room

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 207 mainst Initial CD



* unable to determine sump pumps discharge end point

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Pat Crehan	Subarea	2
Address:	181 Main Street main house Ridgefield CT	Phone Number	203 438 0441
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 10:47 AM

NAME OF PERSON ALLOWING ENTRY: Pat — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 450

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 181 main st main house Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Pat Crehan	Subarea	2
Address:	181 Main Street Office	Phone Number	203 438 0441
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 10:19 AM

NAME OF PERSON ALLOWING ENTRY: Pat — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 181 main St office Initial CD



* Could not Locate Sewer clean out

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Paul Lyons	Subarea	2
Address:	351 Main Street South Hall	Phone Number	203 297 5781
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 3:03 PM

NAME OF PERSON ALLOWING ENTRY: Paul — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 351 main st Southhall Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jesse Lee Memorial Church	Subarea	2
Address:	207 Main Street Wesley Hall	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 1:52 PM

NAME OF PERSON ALLOWING ENTRY: Dale — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: Yes — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Clean out in sexton's workshop

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 207 main st wessele hall Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X Permitted | Deffered | Refused

GENERAL INFORMATION | 1st Attempt | 2nd Attempt | 3rd Attempt

Owner: John Loehr
Address: 293 MainSt
Ridgefield, CT
FM:
Technicians TP. NC

Subarea 2
Phone Number 203 516 1420
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 5/17/2016 4:09 PM

NAME OF PERSON ALLOWING ENTRY John
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Cement

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION Storm sewer
SUMP PIPE HARD PIPED Yes
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE Yes
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
OTHER INFLOW SOURCES
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 6

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sump pumps drain to storm sewer just off Main Street per owner.

Got town permission to connect his sump pumps and downspouts to storm sewer.

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-17-16 Project 793 Main st Initial N.C.



Per owner All DS Go to Storm Drain by Main st

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner:	Jonathan	Subarea	2
Address:	19 Peacable Street	Phone Number	801 231 8231
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/23/2016 3:14 PM

NAME OF PERSON ALLOWING ENTRY: Jonathan — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer pipe	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1100	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Positive connection sump pump to sewer

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

www.esiassociates.com

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 19 Peacable Street Initial VC



* Sump Pump goes to SW

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner:	Susanne McNelis	Subarea	2
Address:	20 Peacable Street	Phone Number	
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/23/2016 2:58 PM

NAME OF PERSON ALLOWING ENTRY: Diana — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	No visible exit	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	750	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2200
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Patio drains for pool area

PHOTO LOG

NOTES: Hose from sump pump to water pipe

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 20 Pragable Street Initial NC



Floor Drain All around Pool.



Sump pump no visual Exit

DWD

DWD

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Leroy Kling	Subarea	2
Address:	30 Peacable Street	Phone Number	203 438 0782
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 2:46 PM

NAME OF PERSON ALLOWING ENTRY: Leroy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 30 Peacable Street Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner:	Mark Damoth	Subarea	2
Address:	32 Peacable Street	Phone Number	203 438 6729
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 10:05 AM

NAME OF PERSON ALLOWING ENTRY: Mark — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	1500
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 32 Peaceable St Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY [X] Permitted [ ] Deffered [ ] Refused

GENERAL INFORMATION [ ] 1st Attempt [ ] 2nd Attempt [ ] 3rd Attempt

Owner:	Congregation Shearith Israel	Subarea	2
Address:	46 Peacable Street	Phone Number	203 438 6589
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 1:57 PM

NAME OF PERSON ALLOWING ENTRY: Laura — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	250	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 3 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 250

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	900
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Positive connection sump pump to sewer

PHOTO LOG



NOTES:



NOTES:

PHOTOS 1 & 2

PHOTO LOG

NOTES:



NOTES:

PHOTOS 3 & 4

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 46 Peacable Street Initial NC



* Sump pump goes to SW

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: John Benusis Trustee
Address: 2 Peaceable St
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 2
Phone Number
# of floors: 3
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 2:07 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 3500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project Leaseable Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Bruce Ritter
Address: 38 Peaceable St
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 1
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 1:59 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2000
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 38 Peacable Street Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: _____ Subarea 2

Address: 42 Peaceable St Phone Number _____

Ridgefield, CT # of floors: 2

FM: _____ Building Type: Res

Flat Roof: No

Technicians CD/SP Date/Time 7/18/2016 1:54 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2000

YARD DRAIN Yes DRAINAGE AREA (sf) 250

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 42 Peaceable Street Initial CD/SP



D D

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Brian Povinelli	Subarea	2
Address:	44 Peaceable St	Phone Number	203 894 3231
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD	Date/Time	7/18/2016 1:46 PM

NAME OF PERSON ALLOWING ENTRY: Deb Povinelli — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/16 Project 44 Peaceable Street Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Margaret Thompson	Subarea	4
Address:	19 Prospect Ridge Unit 25	Phone Number	203 431 6593
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/13/2016 3:55 PM

NAME OF PERSON ALLOWING ENTRY: Margaret — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	300
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-13 Project 19 Prospect Ridge #25 Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Nancy Mullin	Subarea	2
Address:	47 Shadow Lane	Phone Number	203 438 8686
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians		Date/Time	5/23/2016 4:34 PM

NAME OF PERSON ALLOWING ENTRY: Nancy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2600
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 47 Shadow Lane. Initial MC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Tim Daubenspeck	Subarea	2
Address:	49 Shadow Lane	Phone Number	971 219 3828
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/23/2016 4:27 PM

NAME OF PERSON ALLOWING ENTRY: Kacey — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 49 Shadow Lane. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sean Dowd	Subarea	2
Address:	53 Shadow Lane	Phone Number	203 431 7719
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 4:49 PM

NAME OF PERSON ALLOWING ENTRY: Sean — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

No sewer pipe visible.

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 53 Shaudo Ln Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Sean Dowd	Subarea	2
Address:	57 Shadow Lane	Phone Number	203 431 7719
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 4:39 PM

NAME OF PERSON ALLOWING ENTRY: Sean — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	750	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 57 Shaudo Ln Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Charles Valenzuela
Address: 56 Shadow Ln
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 2
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/18/2016 1:37 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 9/18/16 Project 56 Shadow Lane Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner:	John Samenuk	Subarea	2
Address:	61 Shadow Ln	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/ SP	Date/Time	7/18/2016 1:28 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-18-16 Project 61 Shadow Lane Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Steve Wolfe	Subarea	2
Address:	10 West Lane	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/19/2016 1:12 PM

NAME OF PERSON ALLOWING ENTRY: Steve — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	600	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? Yes

ADDITIONAL COMMENTS:

Sump pump to ground surface, outlet pipe visible

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 10 West Ln Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Bernard Bouissou	Subarea	2
Address:	20 West Lane	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP SP	Date/Time	6/22/2016 10:51 AM

NAME OF PERSON ALLOWING ENTRY: Bernard — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	600	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 4 — FREQUENCY OF USE:

DISCHARGE LOCATION: Ground surface — DRAINAGE AREA (sf): 450

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	125
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-22-16 Project 20 West Lane Initial TP/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Debbie Preiger	Subarea	2
Address:	22 West Lane (Main house)	Phone Number	203 438 7323
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 9:21 AM

NAME OF PERSON ALLOWING ENTRY: Debbie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 3 — FREQUENCY OF USE:

DISCHARGE LOCATION: Ground surface — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

2 sewer clean outs

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-18-16 Project 22 West Ln Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Debbie Prieger	Subarea	2
Address:	22 West Lane Cottage Units 401 to 406	Phone Number	203 438 7323
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Commercial
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 9:30 AM

NAME OF PERSON ALLOWING ENTRY: Debbie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	400	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

3 sump pumps connected to sewer in basement, one soft pipe, two hard pipe

PHOTO LOG

NOTES:



NOTES:

PHOTOS 1 & 2

PHOTO LOG

NOTES:

NOTES:

PHOTOS 3 & 4

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 22 West Ln Cottage on the hill Initial CD
Units 403/406 Brown cellar building



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

2016 RIDGEFIELD

BUILDING INSPECTION REPORT

Prepared for:

AECOM
250 Apollo Drive
Chelmsford, MA 01824

Prepared by:

EST Associates, Inc.
51 Fremont Street
Needham, MA 02494

Subarea 3

TABLE OF CONTENTS

Subarea	No.	Street
3	2	Abbott Ave
3	3	Abbott Ave
3	4	Abbott Ave
3	5	Abbott Ave
3	12	Abbott Ave
3	13	Abbott Ave
3	16	Abbott Ave
3	17	Abbott Ave
3	18	Abbott Ave
3	21	Abbott Ave
3	22	Abbott Ave
3	26	Abbott Ave
3	27	Abbott Ave
3	28	Abbott Ave
3	31	Abbott Ave
3	29A	Abbott Ave
3	29B	Abbott Ave
3	8	Abbott Avenue
3	23	Abbott Avenue
3	24	Abbott Avenue
3	25	Abbott Avenue
3	32	Abbott Avenue
3	35	Abbott Avenue
3	7	Arrowhead Place
3	10	Arrowhead Place
3	24	Arrowhead Place
3	25	Arrowhead Place
3	26	Arrowhead Place
3	28	Arrowhead Place
3	32	Arrowhead Place
3	6	Barry Ave
3	8	Barry Ave
3	10	Barry Ave
3	14	Barry Ave
3	23	Barry Ave
3	25	Barry Ave
3	30	Barry Ave
3	32	Barry Ave
3	33	Barry Ave
3	34	Barry Ave
3	41	Barry Ave
3	44	Barry Ave
3	46	Barry Ave

Subarea	No.	Street
3	48	Barry Ave
3	2	Barry Avenue
3	4	Barry Avenue
3	20	Barry Avenue
3	24	Barry Avenue
3	42	Barry Avenue
3	52	Barry Avenue
3	53	Barry Avenue
3	54	Barry Avenue
3	56	Barry Avenue
3	6	Barry Avenue Ridgefield CT
3	13	Bryon Ave
3	15	Bryon Ave
3	21	Bryon Ave
3	22	Bryon Ave
3	26	Bryon Ave
3	30	Bryon Ave
3	36	Bryon Ave
3	42	Bryon Ave
3	43	Bryon Ave
3	6	Bryon Avenue
3	7	Bryon Avenue
3	9	Bryon Avenue
3	11	Bryon Avenue
3	12	Bryon Avenue
3	17	Bryon Avenue
3	18	Bryon Avenue
3	19	Bryon Avenue
3	20	Bryon Avenue
3	31	Bryon Avenue
3	34	Bryon Avenue
3		Church on corner of Catoonah & High Ridge
3	33	Fairfield Ave
3	7	Fairview Ave
3	9	Fairview Ave
3	14	Fairview Ave
3	15	Fairview Ave
3	20	Fairview Ave
3	25	Fairview Ave
3	28	Fairview Ave
3	32	Fairview Ave
3	36	Fairview Ave
3	5	Fairview Avenue
3	17	Fairview Avenue
3	18	Fairview Avenue
3	22	Fairview Avenue
3	27	Fairview Avenue
3	13	Farm Hill Rd

Subarea	No.	Street
3	34	Farm Hill Rd
3	50	Farm Hill Rd
3	2	Farm Hill Road
3	6	Farm Hill Road
3	16	Farm Hill Road
3	26	Farm Hill Road
3	38	Farm Hill Road
3	44	Farm Hill Road
3	52	Farm Hill Road
3	27	Gilbert Street
3	28	Gilbert Street
3	31	Gilbert Street
3	32	Gilbert Street
3	36	Gilbert Street
3	37	Gilbert Street
3	40	Gilbert Street
3	41	Gilbert Street
3	43	Gilbert Street
3	46	Gilbert Street
3	47	Gilbert Street
3	48	Gilbert Street
3	52	Gilbert Street
3	55	Gilbert Street
3	21	Gilbert Street - Ballard Green
3	3	Gino's Way
3	4	Gino's Way
3	5	Gino's Way
3	7	Greenfield Ave
3	14	Greenfield Ave
3	15	Greenfield Ave
3	6	Greenfield Avenue
3	10	Greenfield Avenue
3	11	Greenfield Avenue
3	17	Greenfield Avenue
3	19	Greenfield Avenue
3	167	High Ridge Ave
3	171	High Ridge Ave
3	173	High Ridge Ave
3	190	High Ridge Ave
3	191	High Ridge Ave
3	192	High Ridge Ave
3	200	High Ridge Ave
3	201	High Ridge Ave
3	218	High Ridge Ave
3	165	High Ridge Avenue
3	183	High Ridge Avenue
3	194	High Ridge Avenue

Subarea	No.	Street
3	196	High Ridge Avenue
3	204	High Ridge Avenue
3	206	High Ridge Avenue
3	208	High Ridge Avenue
3	221	High Ridge Avenue
3	223	High Ridge Avenue
3	215 & 217	High Ridge Avenue
3	202	Higheridge Ave
3	188	Highridge Ave
3	197	Highridge Ave
3	207	Highridge Ave
3	209	Highridge Ave
3	214	Highridge Avenue
3	216	Highridge Avenue
3	165	Homes Rd
3	19	Kellogg Street
3	25	Kellogg Street
3	39	Kellogg Street
3	520	Main Street #4
3	10	Millstone Court
3	30	Mulberry St
3	5	Mulberry Street
3	7	Mulberry Street
3	14	Mulberry Street
3	20	Mulberry Street
3	24	Mulberry Street
3	28	Mulberry Street
3	32	Mulberry Street
3	11	Mulvaney Court
3	12	Mulvaney Court
3	14	Mulvaney Court
3	15	Mulvaney Court
3	16	Mulvaney Court
3	18	Mulvaney Court
3	20	Mulvaney Court
3	7	New Street
3	9	New Street
3	11	New Street
3	17	New Street
3	19	New Street
3	23	New Street
3	2	Nutmeg Court
3	8	Nutmeg Court
3	16	Nutmeg Court
3	19	Nutmeg Court
3	22	Nutmeg Court
3	23	Nutmeg Court
3	30	Nutmeg Court

Subarea	No.	Street
3	42	overlook
3	32	Overlook Dr
3	66	Overlook Dr
3	76	Overlook Dr
3	90	Overlook Dr
3	9	Overlook Drive
3	20	Overlook Drive
3	26	Overlook Drive
3	31	Overlook Drive
3	45	Overlook Drive
3	67	Overlook Drive
3	4	Ramapoo Hill Rd
3	5	Ramapoo Hill Road
3	7	Ramapoo Hill Road
3	14	Ramapoo Hill Road
3	19	Ramapoo Hill Road
3	21	Ramapoo Hill Road
3	2	Ramapoo Rd
3	7	Ramapoo Rd
3	40	Ramapoo Rd
3	64	Ramapoo Rd
3	114	Ramapoo Rd
3	130	Ramapoo Rd
3	162	Ramapoo Rd
3	6	Ramapoo Road
3	8	Ramapoo Road
3	10	Ramapoo Road
3	11	Ramapoo Road
3	15	Ramapoo Road
3	21	Ramapoo Road
3	29	Ramapoo Road
3	34	Ramapoo Road
3	35	Ramapoo Road
3	50	Ramapoo Road
3	55	Ramapoo Road
3	67	Ramapoo Road
3	70	Ramapoo Road
3	72	Ramapoo Road
3	79	Ramapoo Road
3	80	Ramapoo Road
3	82	Ramapoo Road
3	85	Ramapoo Road
3	86	Ramapoo Road
3	87	Ramapoo Road
3	91	Ramapoo Road
3	99	Ramapoo Road
3	102	Ramapoo Road

Subarea	No.	Street
3	105	Ramapoo Road
3	110	Ramapoo Road
3	112	Ramapoo Road
3	115	Ramapoo Road
3	116	Ramapoo Road
3	126	Ramapoo Road
3	131	Ramapoo Road
3	136	Ramapoo Road
3	138	Ramapoo Road
3	144	Ramapoo Road
3	2	Victor Drive
3	3	Victor Drive
3	5	Victor Drive
3	7	Victor Drive
3	8	Victor Drive
3	9	Victor Drive
3	11	Victor Drive
3	15	Victor Drive
3	17	Victor Drive

LEGEND

DWD	Driveway Drain
SWD	Stairwell Drain
YD	Yard Drain
WWD	Window Well Drain
SP	Sump Pump
FD	Floor Drain
SW	Sewer Cleanout
X	Downspout goes to surface
O	Downspout goes to ground
⊗	Downspout goes into foundation

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Elizabeth Zieman	Subarea	3
Address:	2 Abbott Avenue	Phone Number	203 733 2149
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/30/2016 11:52 AM

NAME OF PERSON ALLOWING ENTRY: Elizabeth — CONFIRM OVER 18 YRS: No

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 160

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-30-16 Project 2 Abbott Ave, Initial NC



EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Todd Meier
Address: 3 Abbott Ave
Ridgefield, CT
FM:
Technicians CD /SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 1:49 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1400
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 3abbott ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Robert Freeman	Subarea	3
Address:	4 Abbott Ave	Phone Number	203 244 5719
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/ SP	Date/Time	7/19/2016 1:42 PM

NAME OF PERSON ALLOWING ENTRY: Mara freeman — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Tile — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Left side yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 4 abbott ave Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Corey Londoner	Subarea	3
Address:	5 Abbott Ave	Phone Number	203 403 3042
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/ SP	Date/Time	7/12/2016 11:03 AM

NAME OF PERSON ALLOWING ENTRY: Drew beman — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project Abbott Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Adele Annisi	Subarea	3
Address:	12 Abbott Ave	Phone Number	203 894 1908
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 10:01 AM

NAME OF PERSON ALLOWING ENTRY: Adele — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 750

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: No — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? — LOCATION

DRAINAGE AREA (sf) — ELEVATION (ft)

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Clean out not visible

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-3-16 Project 12 Abbott Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Francine Carmody
Address: 13 Abbott Ave
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 1:52 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 13 abbott ave Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	3rd Attempt

Owner: John West
Address: 16 Abbott Ave
Ridgefield, CT
FM:
Technicians TP CD

Subarea 3
Phone Number 203 438 7154
# of floors: 2
Building Type: Res
Flat Roof: Yes
Date/Time 5/19/2016 9:53 AM

NAME OF PERSON ALLOWING ENTRY John
CONFIRM OVER 18 YRS Yes
BASEMENT No
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR
No

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 2
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 16 Abbott Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	George Mulvaney	Subarea	3
Address:	17 Abbott Ave	Phone Number	203 665 0054
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 11:31 AM

NAME OF PERSON ALLOWING ENTRY: Jack hugas — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	150	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Positive connection to sewer

PHOTO LOG

NOTES: Positive connection to the sewer

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 17 abbott Initial SP/CD



positive connection

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jacquelyn Rostow	Subarea	3
Address:	18 Abbott Ave	Phone Number	203 733 1733
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/20/2016 12:45 PM

NAME OF PERSON ALLOWING ENTRY: Jacquelyn — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-20-16 Project 18 Abbott Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Mona Thorpe
Address: 21 Abbott Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 1:57 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 21 abbott ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY [X] Permitted [ ] Deffered [ ] Refused

GENERAL INFORMATION [ ] 1st Attempt [ ] 2nd Attempt [ ] 3rd Attempt

Owner: Kendra Latauska
Address: 22 Abbott Avenue
Ridgefield, CT
FM:
Technicians TP. cD

Subarea 3
Phone Number 203 240 5244
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 6/1/2016 10:13 AM

NAME OF PERSON ALLOWING ENTRY Kendra
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE
DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE
DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 6
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 8-1-16 Project 22 Abbott St Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Rebecca Liebe
Address: 22 Abbott Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea
Phone Number 203 240 5244
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 2:06 PM

NAME OF PERSON ALLOWING ENTRY Kendra
CONFIRM OVER 18 YRS Yes
BASEMENT No
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR No

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 7
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 22 abbott ave Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Justin Oppelaar	Subarea	3
Address:	26 Abbott Ave	Phone Number	914 216 1087
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/ SP	Date/Time	7/19/2016 2:02 PM

NAME OF PERSON ALLOWING ENTRY: Suzanne — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 26 Abbott Initial CD/SP

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: George Pilla
Address: 27 Abbott Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: Yes
Date/Time 7/19/2016 2:08 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 27 abbott ave Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Christopher Mcintosh	Subarea	3
Address:	28 Abbott Ave	Phone Number	203 295 5131
	Ridgefield, CT	# of floors:	
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/19/2016 2:12 PM

NAME OF PERSON ALLOWING ENTRY: Tammy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 28 abbott ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Dan Rossini
Address: 31 Abbott Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 2:21 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 31 abbott ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Rossini Enterprises
Address: 29 A Abbott Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 2:19 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1200
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/14/16 Project 29 Abbott ave A Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner:	Rossini Enterprises	Subarea	3
Address:	29 B Abbott Ave	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/ SP	Date/Time	7/19/2016 2:17 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/17/16 Project 29 abbott ave B4C Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jacquelyn Rostow	Subarea	3
Address:	8 Abbott Avenue	Phone Number	203 733 1733
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/20/2016 12:26 PM

NAME OF PERSON ALLOWING ENTRY: Jacquelyn — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	No	LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sewer clean out likely behind wall,could not locate it.

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-20-16 Project 8 Abbot Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Gregory Symon	Subarea	3.
Address:	23 Abbott Avenue	Phone Number	203 470 7001
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/31/2016 3:29 PM

NAME OF PERSON ALLOWING ENTRY: Mary Henwood — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface,	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1200	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1100
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Herwood.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31 Project 23 Abbott road. Initial MC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Barbara Jones	Subarea	3
Address:	24 Abbott Avenue	Phone Number	203 438 8425
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/20/2016 10:56 AM

NAME OF PERSON ALLOWING ENTRY: Barbara — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Date 5-20-16 Project 24 Abbott Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	25 Abbott Avenue LLC	Subarea	3
Address:	25 Abbott Avenue	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/31/2016 1:36 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Positive connection sump pump to sewer

Difficult landlord insisted sump pump drained to culvert, connection to sewer was clear

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31 Project 25 Abbott Avenue Initial NC



* Simp pump Goes into SW.

* Difficult Guy. Said it i wants Down it goes to SW he would fight it!

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Laura Castelluccio	Subarea	3
Address:	32 Abbott Avenue	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 10:20 AM

NAME OF PERSON ALLOWING ENTRY: Laura — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 32 ABBOTT AVE Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Nancy Bradbury	Subarea	3
Address:	35 Abbott Avenue	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 9:50 AM

NAME OF PERSON ALLOWING ENTRY: Linda — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 35 Abbott st Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Dean Miller	Subarea	3
Address:	7 Arrowhead Place	Phone Number	203 947 6820
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/20/2016 1:31 PM

NAME OF PERSON ALLOWING ENTRY: Dean — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-20 Project 7- Arrowhead Place. Initial



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Carolee Olkoski	Subarea	3
Address:	10 Arrowhead Place	Phone Number	203 856 3596
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/31/2016 3:58 PM

NAME OF PERSON ALLOWING ENTRY: Carolee — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	900
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31-16. Project 10 Arrow Head. - Place. Initial MC.



Front

628 3413

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Peter Vanderminden	Subarea	3
Address:	24 Arrowhead Place	Phone Number	203 313 4800
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 11:16 AM

NAME OF PERSON ALLOWING ENTRY: Peter — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished & cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1600
YARD DRAIN	Yes	DRAINAGE AREA (sf)	800
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Yard drain to dry well per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 24 Arrowhead RD Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Mark Spallone	Subarea	3
Address:	25 Arrowhead Place	Phone Number	203 244 5856
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 10:46 AM

NAME OF PERSON ALLOWING ENTRY: Mark — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	Yes	DRAINAGE AREA (sf)	250
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Yard drain and two rear gutters to back outlet drain

Two gutters on left side go to outlet in back

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 25 Arrowhead Place Initial JC/TP



ARROW Head PL

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jenna Gasparrini	Subarea	3
Address:	26 Arrowhead Place	Phone Number	203 438 8802
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 9:02 AM

NAME OF PERSON ALLOWING ENTRY: Jenna — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1400
YARD DRAIN	Yes	DRAINAGE AREA (sf)	50
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	20
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/14 Project 26 ARROWHead PL Initial JC/TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Marc Lunn	Subarea	3
Address:	28 Arrowhead Place	Phone Number	773 914 1800
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 11:10 AM

NAME OF PERSON ALLOWING ENTRY: Marc — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Downspouts to wetlands in back per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/31 Project 28 Arrow head Place. Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Philip Ländler	Subarea	3
Address:	32 Arrowhead Place	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 10:30 AM

NAME OF PERSON ALLOWING ENTRY: Bev — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Date 5/31 Project 32 Arrow Road, Ploer Initial MC



Front.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Scavenge Lawrence Trustee
Address: 6 Barry Ave
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:05 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 6 Barry ave Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Joseph Byrne
Address: 8 Barry Ave
Ridgefield, CT
FM:
Technicians CD/Sp

Subarea 3
Phone Number
# of floors: 3
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:09 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1200
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 8 Barry ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Robert Baker	Subarea	3
Address:	10 Barry Ave	Phone Number	203 788 8774
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 3:21 PM

NAME OF PERSON ALLOWING ENTRY: Bob Baker — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Tile — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	50
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 10 Barry Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	David Phillips	Subarea	3
Address:	14 Barry Avenue	Phone Number	646 261 9265
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/30/2016 12:54 PM

NAME OF PERSON ALLOWING ENTRY: David — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	700
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-30-16 Project 14 Barry Ave. Initial NC



EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: _____ Subarea 3

Address: 23 Barry Ave Phone Number _____

Ridgefield, CT # of floors: 2

FM: _____ Building Type: Res

Flat Roof: No

Technicians CD/ SP Date/Time 7/19/2016 3:16 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1400

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 23 Barry ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Ames
Address: 25 Barry Ave
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 3
Phone Number
# of floors: 3
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:19 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 25 Barry Ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Eric Knachel	Subarea	3
Address:	30 Barry Ave	Phone Number	908 342 1391
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	Yes
Technicians	TP NC	Date/Time	5/31/2016 9:48 AM

NAME OF PERSON ALLOWING ENTRY: Eric — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	600	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2200
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump connected to sewer

Sump pump through basement wall but couldn't see where it exited outside

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31-16 Project 30 Barry Ave. Initial MC



EP connected to SW

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Obert
Address: 32 Barry Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:37 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 3200
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 500
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/9/10 Project 32 Barry ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Calving
Address: 33 Barry Ave
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 3
Phone Number
# of floors: 3
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:21 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Date 7/19/16 Project 33 Barry Ave Initial CD/SP

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Joes
Address: 34 Barry Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:35 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500
YARD DRAIN Yes DRAINAGE AREA (sf) 250
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 250
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 34 Barry ave Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Wayne
Address: 41 Barry Ave
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:24 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 2/19/16 Project 41 Barry ave Initial CD/SD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Tom Hawk	Subarea	3
Address:	44 Barry Ave	Phone Number	203 994 3103
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 10:29 AM

NAME OF PERSON ALLOWING ENTRY: Tom — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump in basement

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 44 Barry Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Jennifer Ki
Address: 46 Barry Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:28 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2300
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 46 Barry ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Lily Stephen	Subarea	3
Address:	48 Barry Ave	Phone Number	2034709391
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/24/2016 4:49 PM

NAME OF PERSON ALLOWING ENTRY: Lily — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement / Finished — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	5000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-24-16 Project 48 Barry Avenue Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Paul Murdock	Subarea	3
Address:	2 Barry Avenue	Phone Number	203 517 7789
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 2:21 PM

NAME OF PERSON ALLOWING ENTRY: Paul — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31 Project 2 Barry Ave. Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Antonio Dimeglio	Subarea	3
Address:	4 Barry Avenue	Phone Number	203 438 3711
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/28/2016 9:40 AM

NAME OF PERSON ALLOWING ENTRY: Richard — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	740	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6- Project 4 Barry Avenue. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Stefano Zandri	Subarea	3
Address:	20 Barry Avenue	Phone Number	203 733 4720
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 2:39 PM

NAME OF PERSON ALLOWING ENTRY: Laura Zandri — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 20 Berry Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jennifer St. Victor De Pinhot	Subarea	3
Address:	24 Barry Avenue	Phone Number	914 263 4458
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 2:26 PM

NAME OF PERSON ALLOWING ENTRY: Jennifer — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1800	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

2 sump pumps, both to ground surface

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 24 Barry Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Mary Reinertsen	Subarea	3
Address:	42 Barry Avenue	Phone Number	203 438 8212
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/20/2016 10:26 AM

NAME OF PERSON ALLOWING ENTRY: Hakkon — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1100
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Downspouts to catch basin in driveway draining to stream in back, per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-20-16 Project 42 barry Initial CP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Cristina Corona	Subarea	3
Address:	52 Barry Avenue	Phone Number	203 300 9085
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 3:34 PM

NAME OF PERSON ALLOWING ENTRY: Cristina — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	700	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Three sump pumps, all exit to ground per owner but no visible outlets for any of them

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 52 Barry Ave Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Andrew McClellan	Subarea	3
Address:	53 Barry Avenue	Phone Number	203 894 3214
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 2:05 PM

NAME OF PERSON ALLOWING ENTRY: Andrew — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS — FREQUENCY OF USE

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	750
YARD DRAIN	Yes	DRAINAGE AREA (sf)	300
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	40

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

2 sump pumps to ground surface

Stairwell drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 53 Berry Ave Initial GD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Mark Krys	Subarea	3
Address:	54 Barry Avenue	Phone Number	203 403 5341.
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 3:23 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3200
YARD DRAIN	Yes	DRAINAGE AREA (sf)	60
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/12-16 Project 54 Barry Ave. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Cantrece Keidel	Subarea	3
Address:	56 Barry Avenue	Phone Number	203 470 2694
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 1:52 PM

NAME OF PERSON ALLOWING ENTRY: Cantrece — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 56 Berry Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Scavenge Lawrence Trustee
Address: 6 Barry Ave
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:05 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 6 Barry ave Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Steve Wagnblas	Subarea	3
Address:	13 Bryon Ave	Phone Number	203 894 5667
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 9:55 AM

NAME OF PERSON ALLOWING ENTRY: Ann wagnblas — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	50
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	50

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Other drain is a stairway drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 13 Bryon Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Nicholas Gambardella	Subarea	3
Address:	15 Bryon Ave	Phone Number	203 403 5071
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 10:06 AM

NAME OF PERSON ALLOWING ENTRY: Tina — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1600
YARD DRAIN	Yes	DRAINAGE AREA (sf)	100
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	50
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 5 Bryon Initial CO/SP



EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Jennifer Kubick
Address: 21 Bryon Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 4:36 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 3200
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN Yes DRAINAGE AREA (sf) 50
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 21 Bryon Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Allyson Lowe
Address: 22 Bryon Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 4:39 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 22 Bryon Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Anthony Pandrini
Address: 26 Bryon Ave
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 4:21 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 800
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 26 Bryon Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner: Philip Murphy
Address: 30 Bryon Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 4:17 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1800
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 30 Bryon Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Soche Rollins	Subarea	3
Address:	36 Bryon Ave	Phone Number	203 438 3679
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/12/2016 9:36 AM

NAME OF PERSON ALLOWING ENTRY: Soche Picared — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Tile — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Left side yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	200	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 36 Bryon Initial CD/SF



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	John Apinis	Subarea	3
Address:	42 Bryon Ave	Phone Number	203 438 1008
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/20/2016 11:39 AM

NAME OF PERSON ALLOWING ENTRY: John — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-20-16 Project 42 Brayn Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Christina Jenova	Subarea	3
Address:	43 Bryon Ave	Phone Number	203 438 4533
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 2:52 PM

NAME OF PERSON ALLOWING ENTRY: Christina — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 43 Byron Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Lisa Whelan	Subarea	3
Address:	6 Bryon Avenue	Phone Number	203 438 2624
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians		Date/Time	5/31/2016 5:21 PM

NAME OF PERSON ALLOWING ENTRY: Lisa — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1600	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31-16. Project 6 Bryon Ave. Initial UC



Front.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	ilsa Britz	Subarea	3
Address:	7 Bryon Avenue	Phone Number	203 241 5628
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/19/2016 1:47 PM

NAME OF PERSON ALLOWING ENTRY ilsa CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	One to sewer, one to gr	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN Yes NUMBER OF DRAINS 1 FREQUENCY OF USE

DISCHARGE LOCATION Unknown DRAINAGE AREA (sf) 1200

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	1200
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

One sump pump to sewer. One sump pump to ground surface.

Owner states sump pumps do not run.

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-19-16 Project 7 Bryon Ave. Initial CD



Front

*
2 sump pumps
Both hard PVC pipes
1 goes into sewer clean out
1 goes out to yard

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Clive Standish	Subarea	3
Address:	9 Bryon Avenue	Phone Number	203 894 5634
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 3:23 PM

NAME OF PERSON ALLOWING ENTRY: Clive — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	3100
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	24
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump in basement

Clean out in front lawn

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 9 Bryon Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Michael Rosenblatt	Subarea	3
Address:	11 Bryon Avenue	Phone Number	203 403 5140
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 3:10 PM

NAME OF PERSON ALLOWING ENTRY: Amy Rosenblatt — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	30
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	200

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Ejector pump connected to sewer

Stairwell drain

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 11 Bryon Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	St. Mary Catholic School	Subarea	3
Address:	12 Bryon Avenue	Phone Number	203 948 8796
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/26/2016 2:21 PM

NAME OF PERSON ALLOWING ENTRY: Seth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	900	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

2 sump pumps to sewer, both had water in them

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 12 Bryon Ave Initial CD



* two sump pump connected to sewer clean out hard PVC pipe

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Patrice Lordi	Subarea	3
Address:	17 Bryon Avenue	Phone Number	203 438 7495
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 3:49 PM

NAME OF PERSON ALLOWING ENTRY: Patrice Lordi — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	48
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 11 Bryon AV Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	St. Mary's Catholic School	Subarea	3
Address:	18 Bryon Avenue	Phone Number	203 948 8796
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 11:45 AM

NAME OF PERSON ALLOWING ENTRY: Seth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 18 Bryon Ave Initial CD



* Sump pump discharges into Down spout

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Tracy Warren	Subarea	3
Address:	19 Bryon Avenue	Phone Number	203 448 6420
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 3:38 PM

NAME OF PERSON ALLOWING ENTRY: Tracy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	24
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump in basement

PHOTO LOG



NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 19 Bryan AVE Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Angela McCluskey	Subarea	3
Address:	20 Bryon Avenue	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 5:08 PM

NAME OF PERSON ALLOWING ENTRY: Rebecca — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	2400	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	300
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sump pump hose placed into slop sink that is connected to sewer

Positive connection sump pump to sewer; tenant Rebecca said water collects in basement whenever it r

PHOTO LOG

NOTES:

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31-16 Project 20 Bryon Ave Initial MC



* SP Goes to slop sink. wich goes to SW.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	St. Mary Catholic Scool	Subarea	3
Address:	31 Bryon Avenue	Phone Number	203 948 8796
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 2:34 PM

NAME OF PERSON ALLOWING ENTRY: Seth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1800	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2300
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 31 Bryon Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Francis Sileo	Subarea	3
Address:	34 Bryon Avenue	Phone Number	203 438 0218
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	6/1/2016 12:20 PM

NAME OF PERSON ALLOWING ENTRY: Mary Sileo — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1200	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 34 Bryon Initial CN



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner: St. Mary Catholic School
Address: Church on corner of Catoonah & High Ridge
Ridgefield, CT
FM:
Technicians TP. CD

Subarea 3
Phone Number
# of floors: 2
Building Type: Commercial
Flat Roof: No
Date/Time 5/25/2016 11:27 AM

NAME OF PERSON ALLOWING ENTRY Seth
CONFIRM OVER 18 YRS Yes
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT? No
TYPE OF BASEMENT FLOOR Dirt

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 2
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND — DRAINAGE AREA (sf)
YARD DRAIN — DRAINAGE AREA (sf)
DRIVEWAY DRAIN — DRAINAGE AREA (sf)
WINDOW WELL DRAIN — DRAINAGE AREA (sf)
OTHER DRAINS — DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project Church Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Scott Baird	Subarea	3
Address:	33 Fairfield Ave	Phone Number	203 493 3347
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/	Date/Time	7/19/2016 3:55 PM

NAME OF PERSON ALLOWING ENTRY: Jain — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Til — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	250
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 33 Fairview ave Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: William Harrison
Address: 7 Fairview Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 4:13 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1800
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19 Project 7 fairview Initial SP/CD

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sandra Mosiello	Subarea	3
Address:	9 Fairview Ave	Phone Number	203 438 3255
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/20/2016 11:27 AM

NAME OF PERSON ALLOWING ENTRY: Sandra — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-20-16 Project 9 Fairview Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Helen Brandis	Subarea	3
Address:	14 Fairview Ave	Phone Number	203 438 0679
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/20/2016 11:32 AM

NAME OF PERSON ALLOWING ENTRY: Helen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-20-16 Project 14 Fairview Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	David Reiner	Subarea	3
Address:	15 Fairview Ave	Phone Number	978 886 1348
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 11:45 AM

NAME OF PERSON ALLOWING ENTRY: Ashley Heller — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31 Project 15 Fairview Avenue Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** X **3rd Attempt**

Owner:	Frank Dellicarpini	Subarea	3
Address:	20 Fairview Ave	Phone Number	203 431 5852
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/ SP	Date/Time	7/19/2016 4:05 PM

NAME OF PERSON ALLOWING ENTRY: Dorothy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/A/16 Project 20 Fairview Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Michael Rettger	Subarea	3
Address:	25 Fairview Ave	Phone Number	2034381654
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/24/2016 4:30 PM

NAME OF PERSON ALLOWING ENTRY: Michael — CONFIRM OVER 18 YRS:

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	4000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Owner states that down spouts lead to a curtain drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-24-16 Project 25 Fairview Ave. Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Vincit Giordano	Subarea	3
Address:	28 Fairview Ave	Phone Number	203 894 5908
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 5:11 PM

NAME OF PERSON ALLOWING ENTRY: Vincit — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 28 Fairview Ave Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: A Better Change in Ridgefield INC
Address: 32 Fairview Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 3
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 4:01 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP Yes
DISCHARGE LOCATION Front drain line
SUMP PIPE HARD PIPED Yes
DRAINAGE AREA (sf)

HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
IS THE CLEANOUT SEALED?
DRAINAGE AREA (sf)

ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION
ELEVATION (ft)

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes — DRAINAGE AREA (sf) 1000
YARD DRAIN No — DRAINAGE AREA (sf)
DRIVEWAY DRAIN No — DRAINAGE AREA (sf)
WINDOW WELL DRAIN No — DRAINAGE AREA (sf)
OTHER DRAINS Yes — DRAINAGE AREA (sf)

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection

Can see sump pump discharge pipe coming out from the front of the house

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 32 Fairview ave Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Patricia Bailey
Address: 36 Fairview Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 1
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:52 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/14/16 Project 36 fairview Initial cr/sp



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Mark Lacey	Subarea	3
Address:	5 Fairview Avenue	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/6/2016 4:40 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Finished No

SUMP PUMP

SUMP PUMP No HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT No ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2000

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Cleanout not visible

Finished basement

EST
Associates, Inc.

Date 6-6- Project 5 Fairview Ave. Initial NC.



Front.

Follow the (SW) to be hind a wall. (Finished Basement)

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Mary Jaehnig	Subarea	3
Address:	17 Fairview Avenue	Phone Number	203 431 8113
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 1:26 PM

NAME OF PERSON ALLOWING ENTRY: Mary — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 17 Fairview Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Kevin Briody	Subarea	3
Address:	18 Fairview Avenue	Phone Number	203 438 7600
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/26/2016 1:30 PM

NAME OF PERSON ALLOWING ENTRY: Kevin — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1300	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	900
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Stairwell drain to dry well

Downspouts to dry well (retaining chamber) or to surface

Sump pump outside house in retaining chamber drains to surface, connected to stairwell drain and poss

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 18 Fairview Ave Initial CD



*

Has an Abandoned sump pump in basement
Has a drian retaining well in back yard which has a sump pump that discharges in back yard

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Patricia Ligos	Subarea	3
Address:	22 Fairview Avenue	Phone Number	203 438 8390
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/26/2016 1:09 PM

NAME OF PERSON ALLOWING ENTRY: Patricia — CONFIRM OVER 18 YRS: No

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 22 Fairview Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Bill Nance	Subarea	3
Address:	27 Fairview Avenue	Phone Number	203 894 8211
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/14/2016 2:28 PM

NAME OF PERSON ALLOWING ENTRY: Bill — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

17

Date 7/14/16 Project 27 Fairview Ave Initial JC/TP



Fairview Ave

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Carmine Marallo	Subarea	3
Address:	13 Farm Hill Rd	Phone Number	203 438 2429
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/26/2016 12:05 PM

NAME OF PERSON ALLOWING ENTRY: Carmine — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump for toilet on lower level

No visible cleanout

Drain in driveway connected to culvert

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 13 Farm hill RD Initial CD



* Could not locate sewer clean out Most likely In wall behind laundry machine

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jeffrey Menoher	Subarea	3
Address:	34 Farm Hill Rd	Phone Number	917 328 4471
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 8:57 AM

NAME OF PERSON ALLOWING ENTRY: Jeffrey — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	750
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Propane system collects water vapor that is piped to sewer, but...
Runs infrequently, owner states very minimal amount
Downspouts to outlet pipe in yard

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 34 Farmhill RD Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Michael Capozzolo	Subarea	3
Address:	50 Farm Hill Rd	Phone Number	203 894 9008
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/26/2016 9:19 AM

NAME OF PERSON ALLOWING ENTRY: Michael — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 50 Farm hill RD Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Riecker, Warren	Subarea	3
Address:	2 Farm Hill Road	Phone Number	203 438 3278
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 11:47 AM

NAME OF PERSON ALLOWING ENTRY: Warren — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 2 Farm hill RD Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Fred Lenz	Subarea	3
Address:	6 Farm Hill Road	Phone Number	203 438 4806
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/26/2016 11:57 AM

NAME OF PERSON ALLOWING ENTRY: Fred — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Downspouts to brook per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 6 Farm hill RD Initial CO



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Elizabeth Castle	Subarea	3
Address:	16 Farm Hill Road	Phone Number	203 894 1675
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 1:06 PM

NAME OF PERSON ALLOWING ENTRY: Elizabeth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet and cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	200	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1600
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 16 Farm Hill Rd Initial JC/TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Peter Authier	Subarea	3
Address:	26 Farm Hill Road	Phone Number	203 431 6439
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 9:41 AM

NAME OF PERSON ALLOWING ENTRY: Peter — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1200	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Positive connection sump pump to sewer

Downspouts to dry well per owner

PHOTO LOG



NOTES:



NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 26 Farmhill RD Initial CD



* Sump pump connected to sewer clean out with hard PVC pipe

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Meg Beutel	Subarea	3
Address:	38 Farm Hill Road	Phone Number	203 431 8622
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 8:58 AM

NAME OF PERSON ALLOWING ENTRY: Meg — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

All water drains to storm sewer per owner

Stairwell drain

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 38 Farm Hill Road Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Walter Kichler	Subarea	3
Address:	44 Farm Hill Road	Phone Number	203 438 8392
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/31/2016 2:02 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN Yes NUMBER OF DRAINS 1 FREQUENCY OF USE

DISCHARGE LOCATION Unknown DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	700

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31 Project 44 Farm Hill Road. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Patricia Barlow	Subarea	3
Address:	52 Farm Hill Road	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 9:28 AM

NAME OF PERSON ALLOWING ENTRY: Pat — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 52 Farmhill RD Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Ridgefield Housing Authority
Address: 27 Gilbert Street
Ridgefield, CT
FM:
Technicians TP TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:14 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 600
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/Lv Project 27 Gilbert St 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	DPA LLC	Subarea	3
Address:	28 Gilbert Street	Phone Number	203 733 0932
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 2:46 PM

NAME OF PERSON ALLOWING ENTRY: Danny LeTourneau — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	Yes	DRAINAGE AREA (sf)	450
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Could not like locate clean out

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/14 Project 28 Gilbert St. Initial JC/TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jim Trado	Subarea	3
Address:	31 Gilbert Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 1:09 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31 Project 31 Gilbert St. Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: New Street Realty Inc.
Address: 32 Gilbert Street
Ridgefield, CT
FM:
Technicians TP TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:21 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 52 Gilmont 57 3rd Ave. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	**Permitted**	**Deffered**	**Refused**
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Mary Ellen Miller	Subarea	3
Address:	36 Gilbert St	Phone Number	2034386612
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/NC	Date/Time	5/2/2016 2:30 PM

NAME OF PERSON ALLOWING ENTRY: Mary Ellen Miller — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/2 Project 36 Gilbert. St Initial



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Irene Falcinelli	Subarea	3
Address:	37 Gilbert Street	Phone Number	203 438 8441
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/13/2016 7:58 AM

NAME OF PERSON ALLOWING ENTRY: Irene — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	900
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-13 Project 37 Gilbert St. Initial NC



Front.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Patti Knibbe	Subarea	3
Address:	40 Gilbert Street	Phone Number	203 244 5848
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 2:23 PM

NAME OF PERSON ALLOWING ENTRY: Patti — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	400	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Positive connection sp to sewer

PHOTO LOG



NOTES: White pipe coming from the right is from a sump pump in another r

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/10 Project 40 Gilbert ST Initial JC/TP



Gilbert St.

* Positive connection SP to SW

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	MichaelAnderson	Subarea	3
Address:	41 Gilbert Street	Phone Number	817 648 4547
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/30/2016 10:09 AM

NAME OF PERSON ALLOWING ENTRY: Michael — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf): 400

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	100
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-30-16 Project 41 Gilbert Street Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Gary Velez
Address: 43 Gilbert Street
Ridgefield, CT
FM:
Technicians TP TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:32 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 43 Gilbert St 3rd Flr. Initial TP/MA



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Maureen Lutz	Subarea	3
Address:	46 Gilbert Street	Phone Number	203 438 0248
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 3:43 PM

NAME OF PERSON ALLOWING ENTRY: Maureen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-3-16 Project 46 Gilbert Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Joseph Kolf	Subarea	3
Address:	47 Gilbert Street	Phone Number	203 438 6404
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 3:12 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31 Project 47 Gilbert Street Initial NC

Back



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Deborah Strauss	Subarea	3
Address:	48 Gilbert Street	Phone Number	203 244 5208
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/26/2016 7:54 AM

NAME OF PERSON ALLOWING ENTRY: Deborah — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 48 Gilbert st Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Cathy Perry	Subarea	3
Address:	52 Gilbert Street	Phone Number	203 403 5322
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 11:26 AM

NAME OF PERSON ALLOWING ENTRY: Cathy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 52 Gilbert St Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Michael McNeill
Address: 55 Gilbert Street
Ridgefield, CT
FM:
Technicians TP TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 3:36 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1400
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN Yes DRAINAGE AREA (sf) 6
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 55 Gilbert St 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Ridgefield Housing Authority	Subarea	3
Address:	21 Gilbert Street - Ballard Green	Phone Number	203 240 5323
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP SP	Date/Time	6/23/2016 7:54 AM

NAME OF PERSON ALLOWING ENTRY: Doug — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-23-16 Project 21 Gilbert Street Initial TP/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Susan Fama	Subarea	3
Address:	3 Gino's Way	Phone Number	508 317 7931
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/6/2016 4:19 PM

NAME OF PERSON ALLOWING ENTRY: Susan — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	600
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-6. Project 3 Gino's Way Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Donna Reed	Subarea	3
Address:	4 Gino's Way	Phone Number	203 438 8453
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/15/2016 8:57 AM

NAME OF PERSON ALLOWING ENTRY: Donna — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2100
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1400
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/15/16 Project 4 GILOS WAY Initial TC / TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Kete Long	Subarea	3
Address:	5 Gino's Way	Phone Number	518 393 0859
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	
Technicians	TP NC	Date/Time	5/23/2016 8:38 AM

NAME OF PERSON ALLOWING ENTRY: Kete — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 5 Gino's Way Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Charles Knoche	Subarea	3
Address:	7 Greenfield Ave	Phone Number	2037317770
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/SS	Date/Time	4/29/2016 8:26 AM

NAME OF PERSON ALLOWING ENTRY: Charles Knoche — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Na
DISCHARGE LOCATION	Yard	PUMP CAPACITY(gpm)	Na
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Na
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS — FREQUENCY OF USE

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Below Baseme
DRAINAGE AREA (sf)	400	ELEVATION (ft)	0

OTHER INFLOW SOURCES: Na

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	450
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4/29/14 Project 7 Green Field Ave Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Michele Barricelli
Address: 14 Greenfield Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 4:25 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 19 Green field ave Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Eric Hoerdemann
Address: 15 Greenfield Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 4:30 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1800
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 15 Greenfield ave Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Charles Konche	Subarea	3
Address:	6 Greenfield Avenue	Phone Number	2037317770
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Residential
		Flat Roof:	No
Technicians	TP/SS	Date/Time	4/29/2016 8:04 AM

NAME OF PERSON ALLOWING ENTRY: Charles — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	Na
DISCHARGE LOCATION	Yard	PUMP CAPACITY(gpm)	Na
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	Na
DRAINAGE AREA (sf)	400	IS PUMP ALWAYS ADEQUATE	Yes

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4/29/16 Project 6 Green Field Ave Initial S.S.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Donald Kager	Subarea	3
Address:	10 Greenfield Avenue	Phone Number	203 438 8661
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 10:14 AM

NAME OF PERSON ALLOWING ENTRY: Donald — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 10 Greenfield Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Wendy Boscia	Subarea	3
Address:	11 Greenfield Avenue	Phone Number	203 438 2357
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/25/2016 9:59 AM

NAME OF PERSON ALLOWING ENTRY: Wendy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 11 Greenfield Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Julie Yorty	Subarea	3
Address:	17 Greenfield Avenue	Phone Number	516 606 3805
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/25/2016 9:42 AM

NAME OF PERSON ALLOWING ENTRY: Ian — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sump pump outlet in yard

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 17 Greenfield Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Josephine Mallucci	Subarea	3
Address:	19 Greenfield Avenue	Phone Number	203 438 3084
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 12:31 PM

NAME OF PERSON ALLOWING ENTRY: Josephine — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	850
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 19 Greenfeild Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Saint Mary Catholic School	Subarea	3
Address:	167 High Ridge Ave	Phone Number	203 948 8796
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 11:17 AM

NAME OF PERSON ALLOWING ENTRY: Seth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

No visible clean out

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 167 Ridgefield Ave Initial CD



* Can not locate sewer clean out

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	St. Mary Catholic School	Subarea	3
Address:	171 High Ridge Ave	Phone Number	203 948 8796
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/25/2016 11:04 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 171 Highridge Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	St. Mary Catholic School	Subarea	3
Address:	173 High Ridge Ave	Phone Number	203 948 8796
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 11:07 AM

NAME OF PERSON ALLOWING ENTRY: Peter/Seth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 173 High Ridge Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Christopher Adams
Address: 190 High Ridge Ave
Ridgefield, CT
FM:
Technicians CD/ SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 2:25 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1000
YARD DRAIN Yes DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? Yes

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 190 high Ridge Road Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Dimgelio Antonio Trustee	Subarea	3
Address:	191 High Ridge Ave	Phone Number	203 733 2704
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/19/2016 2:34 PM

NAME OF PERSON ALLOWING ENTRY: Sara patafio — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Front yard	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 191 High Ridge Rd Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Besnik Hasanaj
Address: 192 High Ridge Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 2:29 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 192 High Ridge Rd Initial CO/SO



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Brigid Rice	Subarea	3
Address:	200 High Ridge Ave	Phone Number	203 403 5036
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/28/2016 1:59 PM

NAME OF PERSON ALLOWING ENTRY: Brigid — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 200 High Ridge Ave. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Giselda Torcellini	Subarea	3
Address:	201 High Ridge Ave	Phone Number	
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/SP	Date/Time	7/19/2016 2:40 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 201 High Ridge Rd Initial CD/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Ruth Choplinski
Address: 218 High Ridge Ave
Ridgefield, CT
FM:
Technicians CD/SP

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 1:31 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1400
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:
3rd attempt just did external house inspection

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 218 high Ridge Rd Initial CO/SP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jerry Zimring	Subarea	3
Address:	165 High Ridge Avenue	Phone Number	203 403 5093
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 12:05 PM

NAME OF PERSON ALLOWING ENTRY: Steven Zimiring — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1100
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	3000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Clean out not visible

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-3-16 Project 165 Highridge Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	St. Mary's School	Subarea	3
Address:	183 High Ridge Avenue	Phone Number	203 948 8796
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 10:41 AM

NAME OF PERSON ALLOWING ENTRY: Seth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	To drainage outlet pipe i	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: Yes — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

One sump pump in data room, one s.p. in electrical room, appeared to drain into proper discharge line,
Sewer clean out in Room 112
Internal roof drain in teacher's lounge room 113

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 183 Highridge Initial CD



* Internal drain lines in dataroom
Both sump pumps discharge there

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Joseph Coffey	Subarea	3
Address:	194 High Ridge Avenue	Phone Number	203 438 3711
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/28/2016 9:32 AM

NAME OF PERSON ALLOWING ENTRY: Richard Walter — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	860
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-28-16 Project 194 High Ridge Avenue Initial



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Harry Gill	Subarea	3
Address:	196 High Ridge Avenue	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 3:52 PM

NAME OF PERSON ALLOWING ENTRY: Harry — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: Yes — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23 Project 196 High Ridge Ave. Initial NC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	William LaRosa	Subarea	3
Address:	204 High Ridge Avenue	Phone Number	203 942 8545
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 2:01 PM

NAME OF PERSON ALLOWING ENTRY: Trish — CONFIRM OVER 18 YRS: No

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	900
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 304 High Ridge Ave Initial UC

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	John Flannery	Subarea	3
Address:	206 High Ridge Avenue	Phone Number	203 438 5129
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/26/2016 11:27 AM

NAME OF PERSON ALLOWING ENTRY: John — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 206 High ridge Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Joyce Baum	Subarea	3
Address:	208 High Ridge Avenue	Phone Number	203 894 8056
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 2:09 PM

NAME OF PERSON ALLOWING ENTRY: Joyce — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 208 High Ridge. Ave. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Kenneth Polverani	Subarea	3
Address:	221 High Ridge Avenue	Phone Number	475 289 3393
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 8:16 AM

NAME OF PERSON ALLOWING ENTRY: Bruce Smith — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Owner(s) deceased according to caretaker

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 221 Highridge Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Alda Carboni	Subarea	3
Address:	223 High Ridge Avenue	Phone Number	203 403 3470
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 11:55 AM

NAME OF PERSON ALLOWING ENTRY: Anna — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-3-16 Project 223 Highridge Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Kenneth Polverari	Subarea	3
Address:	215 & 217 High Ridge Avenue	Phone Number	475 289 3393
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/25/2016 8:51 AM

NAME OF PERSON ALLOWING ENTRY: Bruce Smith — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 217/215 High ridge Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Paul Beaulac	Subarea	3
Address:	202 Higheridge Ave	Phone Number	203 894 1027
	Ridgefield, CT	# of floors:	
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 4:17 PM

NAME OF PERSON ALLOWING ENTRY: Chandra Beaulac — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	250
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Some water collects in the basement during rain events

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 202 High Ridge Ave Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Lawrence Owczarzak	Subarea	3
Address:	188 Highridge Ave	Phone Number	203 431 9012
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 3:17 PM

NAME OF PERSON ALLOWING ENTRY: Lawrence — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Dirt — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? Yes

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 188 High Ridge Ave Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Henri Carbonneau	Subarea	3
Address:	197 Highridge Ave	Phone Number	203 717 5005
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 3:51 PM

NAME OF PERSON ALLOWING ENTRY Maryanne Ehrlinspie CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Finished carpet No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Back yard driveway surf	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1200	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND		DRAINAGE AREA (sf)	
YARD DRAIN		DRAINAGE AREA (sf)	
DRIVEWAY DRAIN		DRAINAGE AREA (sf)	
WINDOW WELL DRAIN		DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Finished basement can not locate sewer clean out.

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 197 High Ridge Ave Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Eileen Hahenkratt	Subarea	3
Address:	207 Highridge Ave	Phone Number	203 431 8805
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 4:36 PM

NAME OF PERSON ALLOWING ENTRY: Eileen Hahenkratt — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 207 High Ridge Ave Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Eric Forsyth	Subarea	3
Address:	209 Highridge Ave	Phone Number	203 244 0652
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 4:51 PM

NAME OF PERSON ALLOWING ENTRY: Angela Forsyth — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 209 High Ridge Ave Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Mike Byrne	Subarea	3
Address:	214 Highridge Avenue	Phone Number	203-496-8963
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Residential
		Flat Roof:	No
Technicians	SS/TP	Date/Time	4/28/2016 1:39 PM

NAME OF PERSON ALLOWING ENTRY: Mike — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Dirt — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4-28-16 Project 214 Highridge Rd. Initial T. Purcell



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Mike Byrne	Subarea	3
Address:	216 Highridge Avenue	Phone Number	203-496-8963
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Residential
		Flat Roof:	No
Technicians	SS/TP	Date/Time	4/28/2016 1:48 PM

NAME OF PERSON ALLOWING ENTRY: Mike — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Concrete — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 4-28-16 Project 216 High ridge Rd. Initial T. Purcell



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jerry Zimring	Subarea	3
Address:	165 High Ridge Avenue	Phone Number	203 403 5093
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 12:05 PM

NAME OF PERSON ALLOWING ENTRY: Steven Zimiring — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1100
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	3000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Clean out not visible

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-3-16 Project 165 Highridge Ave Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Carol Solinger	Subarea	3
Address:	19 Kellogg Street	Phone Number	203 403 3645
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	5/26/2016 2:44 PM

NAME OF PERSON ALLOWING ENTRY: Carol — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Unknown — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2300
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-26-16 Project 19 Kellogg St Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Stephen Norcross
Address: 25 Kellogg Street
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 1:06 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 5000

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS _____ DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 25 Kellogg St. 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Tim Frosch	Subarea	3
Address:	39 Kellogg Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 10:19 AM

NAME OF PERSON ALLOWING ENTRY: Tim — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/18/14 Project 39 Kilby St Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Brian Stevenson	Subarea	4
Address:	520 Main Street #4	Phone Number	2034381046
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	6/14/2016 5:41 PM

NAME OF PERSON ALLOWING ENTRY: Brian — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-14-16 Project 520 Main St, Unit 4 Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Rachel Belden	Subarea	3
Address:	10 Millstone Court	Phone Number	203 431 5774
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 11:16 AM

NAME OF PERSON ALLOWING ENTRY: Rachel — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-3-16 Project 10 millston Court Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Evan Keefer	Subarea	3
Address:	30 Mulberry St	Phone Number	2034388965
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/NC	Date/Time	5/3/2016 8:50 AM

NAME OF PERSON ALLOWING ENTRY: Evan — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: Yes — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Clean out underground according to owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/1 Project 30 Mulberry st Initial MC



SW underGround, under a Rock. Not visable.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Thomas Lyons
Address: 5 Mulberry Street
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 1:16 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 5 Mulberry St. 3rd Flr. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Alysa Wakin
Address: 7 Mulberry Street
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 1:22 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 5000

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS _____ DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 7 Mulberry St. 3rd Att. Initial TP / TH



EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner:	Kenneth MacKenzie	Subarea	3
Address:	14 Mulberry Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 1:28 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	4500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 14 Mulberry St. 3rd Aff. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Marjorie Goral	Subarea	3
Address:	20 Mulberry Street	Phone Number	203 438 8950
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 4:45 PM

NAME OF PERSON ALLOWING ENTRY: Marjorie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31-16 Project 20 Mulberry Street Initial N.C.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sarah Berkley	Subarea	3
Address:	24 Mulberry Street	Phone Number	203 894 5651
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/27/2016 3:26 PM

NAME OF PERSON ALLOWING ENTRY: Sarah — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	0.5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-27-16. Project 24 Mulberry St. Initial NC



SW clean out was out side back of house.

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Martin Nadel
Address: 28 Mulberry Street
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 1:36 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN DRAINAGE AREA (sf)
DRIVEWAY DRAIN DRAINAGE AREA (sf)
WINDOW WELL DRAIN DRAINAGE AREA (sf)
OTHER DRAINS DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 28 Mulberry St. 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	X 1st Attempt	2nd Attempt	3rd Attempt

Owner:	Evan Keefer	Subarea	3
Address:	32 Mulberry Street	Phone Number	203 438 8
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP / NC	Date/Time	5/3/2016 9:09 AM

NAME OF PERSON ALLOWING ENTRY: Evan — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Second Clean out outside is under ground not visible.

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/3 Project 32 Melbourne St Initial AC



Unable to enter
SW
Not visible

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	John Eppolito	Subarea	3
Address:	11 Mulvaney Court	Phone Number	2034380632
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	5/24/2016 3:54 PM

NAME OF PERSON ALLOWING ENTRY: John — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-24-16 Project 11 Mulvaney Court Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Lisa Shriver	Subarea	3
Address:	12 Mulvaney Court	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	6/1/2016 9:36 AM

NAME OF PERSON ALLOWING ENTRY: Lisa — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 12 Mulvaney Court Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Arpita Sankaran	Subarea	3
Address:	14 Mulvaney Court	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	
Technicians	TP JC	Date/Time	7/14/2016 10:14 AM

NAME OF PERSON ALLOWING ENTRY: Arpita — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/14/16 Project 14 MDLVaney ST Initial JC/JTP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Joanna Maxham	Subarea	3
Address:	15 Mulvaney Court	Phone Number	203 810 9266
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 2:26 PM

NAME OF PERSON ALLOWING ENTRY: Joanna — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16. Project 15 Molvany. Court Initial AC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Robert Colen	Subarea	3
Address:	16 Mulvaney Court	Phone Number	203 438 0664
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 11:33 AM

NAME OF PERSON ALLOWING ENTRY: Robert Colen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-3-16 Project 16 Mulvaney Court Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Michael Atkins	Subarea	3
Address:	18 Mulvaney Court	Phone Number	203 244 5322
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 8:23 AM

NAME OF PERSON ALLOWING ENTRY: Andrea — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 18 mulvaney court Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Amy Nash	Subarea	3
Address:	20 Mulvaney Court	Phone Number	203 403 5225
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 2:42 PM

NAME OF PERSON ALLOWING ENTRY: Amy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Could not locate clean out, finished basement.

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 20 Mulberry Court Initial LK



* No Usable clean out located * Finished Basement

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Robert Wengel	Subarea	3
Address:	7 New Street	Phone Number	203 403 3262
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/7/2016 1:38 PM

NAME OF PERSON ALLOWING ENTRY: Mary Formichelli — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES: 5

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	550
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-7 Project 7 New Street Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Patricia Jones	Subarea	3
Address:	9 New Street	Phone Number	203 894 1078
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/7/2016 1:56 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-7 Project 9 Van Street Initial NC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Deborah Atkins	Subarea	3
Address:	11 New Street	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians		Date/Time	6/7/2016 1:45 PM

NAME OF PERSON ALLOWING ENTRY: Deborah — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6.7 Project 11 New St. Initial JC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Poole Kevin
Address: 17 New Street
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 2:43 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 17 New St. 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Cynthia Mullins	Subarea	3
Address:	19 New Street	Phone Number	Refused
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 4:06 PM

NAME OF PERSON ALLOWING ENTRY: Cynthia — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	200
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	300
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 19 New Stud Initial AC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Cynthia Mullins	Subarea	3
Address:	19 New Street	Phone Number	Refused
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/12/2016 4:06 PM

NAME OF PERSON ALLOWING ENTRY: Cynthia — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	200
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	300
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-12-16 Project 19 New Stud Initial AC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Kevin Perhamus
Address: 23 New Street
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 2:52 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 23 New St. 3rd Flr. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Patricia King	Subarea	3
Address:	2 Nutmeg Court	Phone Number	203 438 3089
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/9/2016 5:34 PM

NAME OF PERSON ALLOWING ENTRY: Patricia — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-9-16 Project 2 Nutmag Court Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner: Joseph Kovacs
Address: 8 Nutmeg Court
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 1
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 2:08 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN _____ DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN _____ DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN _____ DRAINAGE AREA (sf) _____

OTHER DRAINS _____ DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 8 Nutmeg Court 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Paul Rossini
Address: 16 Nutmeg Court
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 2:14 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN DRAINAGE AREA (sf)
DRIVEWAY DRAIN DRAINAGE AREA (sf)
WINDOW WELL DRAIN DRAINAGE AREA (sf)
OTHER DRAINS DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 16 Nutmeg Court 3rd Aff. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Steven Westington
Address: 19 Nutmeg Court
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 2:21 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 5000

YARD DRAIN Yes DRAINAGE AREA (sf) 500

DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 2000

WINDOW WELL DRAIN No DRAINAGE AREA (sf)

OTHER DRAINS _____ DRAINAGE AREA (sf)

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 19 Nutmeg Court 3rd Att Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	John Laber	Subarea	3
Address:	22 Nutmeg Court	Phone Number	203 438 9394
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/8/2016 12:21 PM

NAME OF PERSON ALLOWING ENTRY: John Laber — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-8-16 Project 22 Nutmeg Court Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Carol Hamilton	Subarea	3
Address:	23 Nutmeg Court	Phone Number	203 438 3491
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/16/2016 12:56 PM

NAME OF PERSON ALLOWING ENTRY: Carol — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1800
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-16-16 Project 23 Nutmeg Court Initial CD



EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Laura cabrera	Subarea	3
Address:	30 Nutmeg Court	Phone Number	305 542 2233
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD	Date/Time	6/8/2016 12:52 PM

NAME OF PERSON ALLOWING ENTRY: Karen serrao — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet / Finished basement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	225
YARD DRAIN	Yes	DRAINAGE AREA (sf)	500
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Could not locate sewer clean out, finished basement

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-8-16 Project 30 Nutmeg Court Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner: William short
Address: 42 overlook
Ridgefield, CT
FM:
Technicians NC TP

Subarea 3
Phone Number 2034388281
# of floors: 3
Building Type: Res
Flat Roof: No
Date/Time 5/24/2016 10:49 AM

NAME OF PERSON ALLOWING ENTRY William
CONFIRM OVER 18 YRS
BASEMENT Yes
WATER IN BASEMENT No
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR Cement
No

SUMP PUMP

SUMP PUMP No
DISCHARGE LOCATION
SUMP PIPE HARD PIPED
DRAINAGE AREA (sf)
HORSEPOWER OF PUMP
PUMP CAPACITY(gpm)
FREQUENCY OF CYCLING
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes
IS THE CLEANOUT SEALED? Yes
DRAINAGE AREA (sf)
ELEVATION OF SEWER CONNECTION CLEANOUT
LOCATION Above Basem
ELEVATION (ft) 2
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2000
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitorir
Pipeline Service
Operations & Maintenanc

Date 5-24-16 Project 42 Overlook Drive Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Vjollca Dalipi	Subarea	3
Address:	32 Overlook Dr	Phone Number	NA
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 12:35 PM

NAME OF PERSON ALLOWING ENTRY: Spemdi — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	2000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

No home phone

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 32 Overlook Drive Initial TP



Discharge location for SP unknown but not connected to sewer pipe according to what we could see

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	David Tullis	Subarea	3
Address:	66 Overlook Dr	Phone Number	203 403 2150
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 11:52 AM

NAME OF PERSON ALLOWING ENTRY: Miriam Tullis — CONFIRM OVER 18 YRS: No

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Old sewer clean out going out the back of the house. Not sealed

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 66 Overlook Drive Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Harold Havl	Subarea	3
Address:	76 Overlook Dr	Phone Number	203 438 2547
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 11:25 AM

NAME OF PERSON ALLOWING ENTRY: Robert — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 76 Overlook Drive Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Michael Cali	Subarea	3
Address:	90 Overlook Dr	Phone Number	203 438 2534
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 11:36 AM

NAME OF PERSON ALLOWING ENTRY: Michael Cali — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Drive way surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	60	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	Yes	DRAINAGE AREA (sf)	400
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 90 Overlook Drive Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Walter Seibert	Subarea	3
Address:	9 Overlook Drive	Phone Number	203 438 2199
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. NC	Date/Time	5/23/2016 9:16 AM

NAME OF PERSON ALLOWING ENTRY: Walter — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	7

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

Clean out not located. House is converted barn, c.o. probably behind wall.

I'm

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5/23. Project 9 Overlook Drive Initial NC



YD

DWD

No visable. SW clean out.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner:	Schluetter Jen-Uwe	Subarea	3
Address:	20 Overlook Drive	Phone Number	
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 1:57 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 20 Overlook Drive 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sarah Gontijo	Subarea	3
Address:	26 Overlook Drive	Phone Number	914 536 8379
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/7/2016 9:18 AM

NAME OF PERSON ALLOWING ENTRY: Sarah — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2100
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	Yes	DRAINAGE AREA (sf)	4
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

Clean out not located

Finished basement

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-7 Project 26 Overlook Drive Initial AC



SW clean out is behind a wall Not visable.

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jessica Aframe	Subarea	3
Address:	31 Overlook Drive	Phone Number	203-403-3343
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 1:45 PM

NAME OF PERSON ALLOWING ENTRY: Jessica — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ext	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	10000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	5000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 31 Overlook Drive Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jessica Aframe	Subarea	3
Address:	31 Overlook Drive	Phone Number	203-403-3343
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 1:45 PM

NAME OF PERSON ALLOWING ENTRY: Jessica — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ext	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	10000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	5000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 31 Overlook Drive Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	James Tarsi	Subarea	3
Address:	45 Overlook Drive	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/10/2016 9:23 AM

NAME OF PERSON ALLOWING ENTRY: Jim — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-10-16 Project 45 Overlook DR Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Gregory Gorski	Subarea	3
Address:	67 Overlook Drive	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	5/25/2016 8:42 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP No HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT Yes ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? Yes LOCATION Above Basem

DRAINAGE AREA (sf) _____ ELEVATION (ft) 4

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) _____

YARD DRAIN Yes DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-25-16 Project 67 Overlook Dr Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Steven Christofor	Subarea	3
Address:	4 Ramapoo Hill Rd	Phone Number	646?643 0394
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 11:20 AM

NAME OF PERSON ALLOWING ENTRY: Steven — CONFIRM OVER 18 YRS: No

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 4 Ramapoo Hill Rd Initial TC/TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	David Palmer	Subarea	3
Address:	5 Ramapoo Hill Road	Phone Number	203-438-0563
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 3:50 PM

NAME OF PERSON ALLOWING ENTRY: Carla Palmer — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 5 Ramapoo Hill Rd. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	1st Attempt	2nd Attempt	X 3rd Attempt

Owner: Charles Vasoll
Address: 7 Ramapoo Hill Road
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 3:58 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 2500

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN Yes DRAINAGE AREA (sf) 1500

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS _____ DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 7 Ramapoo Hill Rd. - 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Maria Louise Getz	Subarea	3
Address:	14 Ramapoo Hill Road	Phone Number	203 438 8258
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/7/2016 9:40 AM

NAME OF PERSON ALLOWING ENTRY: Maria Louise — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-7 Project 14 Ramapoo Hill rd. Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Richard Norwitt	Subarea	3
Address:	19 Ramapoo Hill Road	Phone Number	203-438-0579
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 4:04 PM

NAME OF PERSON ALLOWING ENTRY: Pam — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Outside	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	450	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Outside — DRAINAGE AREA (sf): 500

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	Yes	DRAINAGE AREA (sf)	500
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?: No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 19 Ramapoo Hill Rd. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Catherine Berry	Subarea	3
Address:	21 Ramapoo Hill Road	Phone Number	203-438-3253
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 4:18 PM

NAME OF PERSON ALLOWING ENTRY: Mrs. Berry — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

4240

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 21 Ramapoo Hill Rd Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Bob Walker	Subarea	3
Address:	2 Ramapoo Rd	Phone Number	203 994 5390
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/30/2016 9:30 AM

NAME OF PERSON ALLOWING ENTRY: Bob — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Downspouts to stream in back per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-30-16 Project 2 Ramapoo Rd Initial CD



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Charles Vasoll	Subarea	3
Address:	7 Ramapoo Rd	Phone Number	203 438 7284
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 5:56 PM

NAME OF PERSON ALLOWING ENTRY: Leslie millington — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished carpet — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 7 Ramapoo Rd Initial T.P.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Lanie colao	Subarea	3
Address:	40 Ramapoo Rd	Phone Number	203 438 0572
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/8/2016 10:50 AM

NAME OF PERSON ALLOWING ENTRY: Lanie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement and carpet — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	1000	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1700
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	Yes	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? Yes

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-8-16 Project 40 Ramapoo Rd. Initial T.P



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Clint Stanford	Subarea	3
Address:	64 Ramapoo Rd	Phone Number	203 438 3556
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 5:44 PM

NAME OF PERSON ALLOWING ENTRY: Clint Stanford — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Wood — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN		DRAINAGE AREA (sf)	
DRIVEWAY DRAIN		DRAINAGE AREA (sf)	
WINDOW WELL DRAIN		DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 64 Ramapoo Road Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Alice Hayes	Subarea	3
Address:	114 Ramapoo Rd	Phone Number	203 240 2790
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 10:52 AM

NAME OF PERSON ALLOWING ENTRY: Alice — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: Yes — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — Yes

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION: Back yard — DRAINAGE AREA (sf): 60

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 3

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	750
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Some downspout to surface have visible outlets

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 114 Ramapoo Rd Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Chris Delaurentis	Subarea	3
Address:	130 Ramapoo Rd	Phone Number	203 325 8415
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 10:29 AM

NAME OF PERSON ALLOWING ENTRY: Chris — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	800
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 130 Ramapoo Rd Initial JC/TA



Ramapoo Rd

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Christopher Couri	Subarea	3
Address:	162 Ramapoo Rd	Phone Number	203 438 7739
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	CD/TP	Date/Time	6/2/2016 10:00 AM

NAME OF PERSON ALLOWING ENTRY: Couri — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Front of house surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	400	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	750
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN		DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN?

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 162 Ramapoo Rd. Initial TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Mark Waring
Address: 6 Ramapoo Road
Ridgefield, CT
FM:
Technicians TP TH

Subarea
Phone Number
# of floors:
Building Type:
Flat Roof:
Date/Time 7/19/2016 3:56 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN? No
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/14 Project 6 RAMAPOO Rd 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Lindsey Ferguson	Subarea	3
Address:	8 Ramapoo Road	Phone Number	203 244 5306
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	7/30/2016 9:06 AM

NAME OF PERSON ALLOWING ENTRY: Lindsey — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2300
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-30-16 Project 8 Ramapo Road Initial AC



- Front -

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Steven Silvestri	Subarea	3
Address:	10 Ramapoo Road	Phone Number	203 894 9432
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 8:06 AM

NAME OF PERSON ALLOWING ENTRY: Steven — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2000
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 10 Ramapoo Rd Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Sherri Anandappa	Subarea	3
Address:	11 Ramapoo Road	Phone Number	203 438 7847
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 12:30 PM

NAME OF PERSON ALLOWING ENTRY: Sherri — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	250
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 11 Ramapoo Rd Initial JC/TP



Ramapoo

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Julie Rossettie	Subarea	3
Address:	15 Ramapoo Road	Phone Number	203 984 6676
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 4:07 PM

NAME OF PERSON ALLOWING ENTRY: Julie — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Unknown, no outlet on o	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	900	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1800
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 15 Ramapoo Rd Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	David Gengo	Subarea	3
Address:	21 Ramapoo Road	Phone Number	
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 4:15 PM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN No DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN No DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN No DRAINAGE AREA (sf) _____

OTHER DRAINS No DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 21 RAMAPOO Rd - 3rd Attempt Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Charley Popp	Subarea	3
Address:	29 Ramapoo Road	Phone Number	203 438 3459
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 9:17 AM

NAME OF PERSON ALLOWING ENTRY: Charley — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 29 Ramapoo Rd Initial VC/TP



Ramapoo Rd

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**X 3rd Attempt**

Owner: Dean Miller
Address: 34 Ramapoo Road
Ridgefield, CT
FM:
Technicians TP TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/19/2016 4:29 PM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND Yes DRAINAGE AREA (sf) 1500
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS No DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 84 Ramapoo Rd 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Rolf Almgren	Subarea	3
Address:	35 Ramapoo Road	Phone Number	203 438 8663
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 8:25 AM

NAME OF PERSON ALLOWING ENTRY: Rolf — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Dirt — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	850
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-3-16 Project 35 Ramapoo Rd Initial CD



Front

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Donna Hall	Subarea	3
Address:	50 Ramapoo Road	Phone Number	203 438 3994
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 9:32 AM

NAME OF PERSON ALLOWING ENTRY: Donna — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1850
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EP to sewer

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/14 Project 50 Ramapoo Rd. Initial JC/TD



Ramapoo Rd

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Elizabeth White	Subarea	3
Address:	55 Ramapoo Road	Phone Number	203 438 1828
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP TH	Date/Time	7/19/2016 4:41 PM

NAME OF PERSON ALLOWING ENTRY: Pauline — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet, concrete — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	500	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/19/16 Project 55 Ramapo Rd Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Dale Wooten	Subarea	3
Address:	67 Ramapoo Road	Phone Number	203 961 8000
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/6/2016 12:49 PM

NAME OF PERSON ALLOWING ENTRY: Dale Wooten — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	8

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-6 Project 67 Rampoo Road Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Thomas Frossell	Subarea	3
Address:	70 Ramapoo Road	Phone Number	
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 10:38 AM

NAME OF PERSON ALLOWING ENTRY: Thomas — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	1500
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 70 Ramapoo Rd. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Richard Luck	Subarea	3
Address:	72 Ramapoo Road	Phone Number	203 438 6232
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 9:46 AM

NAME OF PERSON ALLOWING ENTRY: Richard — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 72 Ramapoo Rd Initial JC/TP



Ramapoo Rd

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Nicholas Poletto	Subarea	3
Address:	79 Ramapoo Road	Phone Number	917 589 9686
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/9/2016 2:39 PM

NAME OF PERSON ALLOWING ENTRY: Karen — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-9-16 Project 79 Ramapoo Rd Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Mary Phelps	Subarea	3
Address:	80 Ramapoo Road	Phone Number	203 546 0315
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/9/2016 2:57 PM

NAME OF PERSON ALLOWING ENTRY: Mary — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Wood — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	400	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

2 sump pumps, one in garage, one in closet

Sump pump in garage exits through exterior stone wall at front steps

SP in closet exits to ground surface of front yard

Could not locate cleanout, likely behind wall.

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-9-16 Project 80 Ramapoo Rd. Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Joseph Sullivan	Subarea	3
Address:	82 Ramapoo Road	Phone Number	203 438 6218
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/9/2016 2:52 PM

NAME OF PERSON ALLOWING ENTRY: Rachel — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	400
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-9-16 Project 82 Ramapoo Rd Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sean Archambault	Subarea	3
Address:	85 Ramapoo Road	Phone Number	203 438 0181
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/7/2016 3:29 PM

NAME OF PERSON ALLOWING ENTRY: Sean — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump to sewer

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-7 Project 85 Ramapoo Road. Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sarah Blosat	Subarea	3
Address:	86 Ramapoo Road	Phone Number	339 223 0229
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/7/2016 2:58 PM

NAME OF PERSON ALLOWING ENTRY: Sarah Blosat — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet,wood,some cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Sewer	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	300	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	650
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Positive connection sump pump to sewer
Owner has never heard sump pump going in 4 years
Said no water gets in basement

PHOTO LOG



NOTES: SP to sewer

NOTES:

PHOTOS 1 & 2

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6 7 Project 86 Ramapo Road Initial NC



Front.

* SP Goes to SW / (Positive Connection)

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Wendy Richardson	Subarea	3
Address:	87 Ramapoo Road	Phone Number	203 244 5605
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 3:45 PM

NAME OF PERSON ALLOWING ENTRY: Wendy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	2200
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

All outside drains go to back drainage creek per owner

Ejector pump for laundry area

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 5-31 Project 87 Ramapo Rd Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	X **3rd Attempt**

Owner:	Evan McGerald	Subarea	3
Address:	91 Ramapoo Road	Phone Number	
	Ridgefield, CT	# of floors:	1
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 10:57 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT Yes

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP		HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT		ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 91 Ramapoo Rd. 3rd Attempt Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Edna Weber
Address: 99 Ramapoo Road
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 11:54 AM

NAME OF PERSON ALLOWING ENTRY
CONFIRM OVER 18 YRS
BASEMENT
WATER IN BASEMENT
EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?
TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP
HORSEPOWER OF PUMP
DISCHARGE LOCATION
PUMP CAPACITY(gpm)
SUMP PIPE HARD PIPED
FREQUENCY OF CYCLING
DRAINAGE AREA (sf)
IS PUMP ALWAYS ADEQUATE
** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN
NUMBER OF DRAINS
FREQUENCY OF USE
DISCHARGE LOCATION
DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN
FREQUENCY OF USE
DISCHARGE LOCATION
DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT
ELEVATION OF SEWER CONNECTION CLEANOUT
IS THE CLEANOUT SEALED?
LOCATION
DRAINAGE AREA (sf)
ELEVATION (ft)
OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes
DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf)
YARD DRAIN No DRAINAGE AREA (sf)
DRIVEWAY DRAIN No DRAINAGE AREA (sf)
WINDOW WELL DRAIN No DRAINAGE AREA (sf)
OTHER DRAINS DRAINAGE AREA (sf)
EXPERIENCED PONDING ON PROPERTY DURING RAIN?
ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 99 Ramapoo Rd. 3rd Attempt Initial TP/TH

X



Front Ramapoo Rd.

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	X Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt**

Owner:	Michael Colletto	Subarea	3
Address:	102 Ramapoo Road	Phone Number	2034314265
	Ridgefield, CT	# of floors:	3
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	NC TP	Date/Time	6/14/2016 6:02 PM

NAME OF PERSON ALLOWING ENTRY: Michael — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Finished — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6/14/16 Project 102 Ramapoo Rd Initial DC TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Barclay Griffiths	Subarea	3
Address:	105 Ramapoo Road	Phone Number	914 261 7948
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 9:33 AM

NAME OF PERSON ALLOWING ENTRY Barclay CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Carpet No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Sewer clean out not visible behind wall, finished basement

All but 2 downspouts to ground surface

EST
Associates, Inc.

Date 6-2-16 Project 105 Ramapoo Rd Initial CD



*
Can not locate sewe cleanout
Finished basement pipes are
in the walls

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Laura Stucki	Subarea	3
Address:	110 Ramapoo Road	Phone Number	203 244 5061
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	5/31/2016 10:55 AM

NAME OF PERSON ALLOWING ENTRY: Laura — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2300
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Date 5/31 Project 110 Bampos Road Initial NC



* Slop Sink Discharges into Floor Drain

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Cesar Casas	Subarea	3
Address:	112 Ramapoo Road	Phone Number	203 300 0137
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/20/2016 8:02 AM

NAME OF PERSON ALLOWING ENTRY: Cesar — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Dirt — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Date 6-20 Project 112 Ramapo Road Initial NE



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Alex Vorozhbitskiy	Subarea	3
Address:	115 Ramapoo Road	Phone Number	203 550 4690
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/7/2016 2:36 PM

NAME OF PERSON ALLOWING ENTRY: Alex — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	4

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-7 Project 115 Dumpco Road Initial NC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | X **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Raymond Ford	Subarea	3
Address:	116 Ramapoo Road	Phone Number	203 451 4774
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/7/2016 2:05 PM

NAME OF PERSON ALLOWING ENTRY: Michelle Ford — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	6

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-7 Project 116 Ramapoo Road. Initial N.C.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Christopher Morrissey	Subarea	3
Address:	126 Ramapoo Road	Phone Number	203 417 3505
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/10/2016 9:10 AM

NAME OF PERSON ALLOWING ENTRY: Christopher — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	125	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	200
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-10-16 Project 126 Ramapoo Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Jonathan Garand	Subarea	3
Address:	131 Ramapoo Road	Phone Number	413 627 6789
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/15/2016 8:46 AM

NAME OF PERSON ALLOWING ENTRY: Kate — CONFIRM OVER 18 YRS: Yes

BASEMENT: No

WATER IN BASEMENT: — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Finished basement could not locate clean out

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/15/16 Project 131 Ramapoo Rd Initial JC/TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Alexandra Lehman	Subarea	3
Address:	136 Ramapoo Road	Phone Number	914 450 9598
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/7/2016 11:32 AM

NAME OF PERSON ALLOWING ENTRY: Dan Griswold — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	2

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	450
YARD DRAIN	Yes	DRAINAGE AREA (sf)	350
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-7 Project 136 Damage Roof. Initial MC



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Maryellen Comer	Subarea	3
Address:	138 Ramapoo Road	Phone Number	203-363-7181
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 12:02 PM

NAME OF PERSON ALLOWING ENTRY: Tracy — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: 1 — FREQUENCY OF USE: Unk

DISCHARGE LOCATION: Rear — DRAINAGE AREA (sf): 2000

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 6

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	1000
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 138 Ramapoo Rd. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Kevin Quinn	Subarea	3
Address:	144 Ramapoo Road	Phone Number	203 431 6512
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP NC	Date/Time	6/7/2016 11:41 AM

NAME OF PERSON ALLOWING ENTRY: Kevin Quinn — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: Yes — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT: Yes — ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED?: Yes — LOCATION: Above Basem

DRAINAGE AREA (sf): — ELEVATION (ft): 1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-7 Project 144 Ramapoo Road. Initial NC.



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Sharon Scott	Subarea	3
Address:	2 Victor Drive	Phone Number	203 438 3079
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 1:55 PM

NAME OF PERSON ALLOWING ENTRY: Sharon — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	No	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	300	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Could not locate clean out, finished basement

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7/13/16 Project 2 VICTOR Dr. Initial VC/TP



VICTOR

51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Maryann Flynn	Subarea	3
Address:	3 Victor Drive	Phone Number	203 438 3209
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP. CD	Date/Time	6/3/2016 9:24 AM

NAME OF PERSON ALLOWING ENTRY Maryann CONFIRM OVER 18 YRS Yes

BASEMENT Yes

WATER IN BASEMENT No EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR Cement No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	170	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN No NUMBER OF DRAINS FREQUENCY OF USE

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN No FREQUENCY OF USE

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	No	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?		LOCATION	
DRAINAGE AREA (sf)		ELEVATION (ft)	

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Clean out not visible, behind wall, owner states it exits back left corner of house

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 3 Victor DR Initial CO



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Marlene Evans	Subarea	3
Address:	5 Victor Drive	Phone Number	203-438-2935
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP/TH	Date/Time	7/20/2016 11:04 AM

NAME OF PERSON ALLOWING ENTRY: Marlene — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	2400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS		DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 5 Victor Drive Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST
Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY	Permitted	Deffered	Refused
GENERAL INFORMATION	**1st Attempt**	**2nd Attempt**	**3rd Attempt** X

Owner: Robert Reitknecht
Address: 7 Victor Drive
Ridgefield, CT
FM:
Technicians TP/TH

Subarea 3
Phone Number
# of floors: 2
Building Type: Res
Flat Roof: No
Date/Time 7/20/2016 11:13 AM

NAME OF PERSON ALLOWING ENTRY _____ CONFIRM OVER 18 YRS _____

BASEMENT _____

WATER IN BASEMENT _____ EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR

SUMP PUMP

SUMP PUMP _____ HORSEPOWER OF PUMP _____

DISCHARGE LOCATION _____ PUMP CAPACITY(gpm) _____

SUMP PIPE HARD PIPED _____ FREQUENCY OF CYCLING _____

DRAINAGE AREA (sf) _____ IS PUMP ALWAYS ADEQUATE _____

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN _____ NUMBER OF DRAINS _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN _____ FREQUENCY OF USE _____

DISCHARGE LOCATION DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT _____ ELEVATION OF SEWER CONNECTION CLEANOUT

IS THE CLEANOUT SEALED? _____ LOCATION _____

DRAINAGE AREA (sf) _____ ELEVATION (ft) _____

OTHER INFLOW SOURCES _____

EXTERNAL HOUSE INSPECTION Yes

DOWNSPOUTS ENTER GROUND No DRAINAGE AREA (sf) _____

YARD DRAIN _____ DRAINAGE AREA (sf) _____

DRIVEWAY DRAIN _____ DRAINAGE AREA (sf) _____

WINDOW WELL DRAIN _____ DRAINAGE AREA (sf) _____

OTHER DRAINS _____ DRAINAGE AREA (sf) _____

EXPERIENCED PONDING ON PROPERTY DURING RAIN? _____

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 7-20-16 Project 7 Victor Drive 3rd Att. Initial TP/TH



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	William Berg	Subarea	3
Address:	8 Victor Drive	Phone Number	203 438 0104
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP JC	Date/Time	7/13/2016 10:07 AM

NAME OF PERSON ALLOWING ENTRY: William — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN | NUMBER OF DRAINS | FREQUENCY OF USE

DISCHARGE LOCATION | DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	600
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	300
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Date 7/13/16 Project 8 VICTOR Dr Initial JC/TP



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Mary Larubbio	Subarea	3
Address:	9 Victor Drive	Phone Number	203 470 7267
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/16/2016 7:57 AM

NAME OF PERSON ALLOWING ENTRY: Mary — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground outside	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	900	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	5

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION	Yes		
DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	550
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

2 sump pumps; SP in garage drains to outlet next to road, SP in basement drains to outlet in side yard

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-16-16 Project 9 Victor Drive Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	Robin Prokopczyk	Subarea	3
Address:	11 Victor Drive	Phone Number	203 788 5607
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/1/2016 1:09 PM

NAME OF PERSON ALLOWING ENTRY: Robin — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Cement — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	No	DRAINAGE AREA (sf)	
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	600
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-1-16 Project 11 Victor Drive Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY | X **Permitted** | **Deffered** | **Refused**

GENERAL INFORMATION | **1st Attempt** | **2nd Attempt** | **3rd Attempt**

Owner:	Gary Frulla	Subarea	3
Address:	15 Victor Drive	Phone Number	203 438 7530
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 10:39 AM

NAME OF PERSON ALLOWING ENTRY: Gary — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	Yes	HORSEPOWER OF PUMP	
DISCHARGE LOCATION	Ground surface	PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED	Yes	FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)	60	IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION: — DRAINAGE AREA (sf):

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION: — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE: (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	1

OTHER INFLOW SOURCES:

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	400
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	Yes	DRAINAGE AREA (sf)	700
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Driveway drain and roof leaders to catch basin per owner

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-2-16 Project 15 Victor Drive Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com

EST Associates, Inc.

51 FREMONT STREET
NEEDHAM, MA 02494
T: (781) 455-0003
F: (781) 455-8336
www.estassociates.com

HOUSE INSPECTION

ENTRY X **Permitted** **Deffered** **Refused**

GENERAL INFORMATION **1st Attempt** **2nd Attempt** **3rd Attempt**

Owner:	William Jerome	Subarea	3
Address:	17 Victor Drive	Phone Number	203 438 6774
	Ridgefield, CT	# of floors:	2
FM:		Building Type:	Res
		Flat Roof:	No
Technicians	TP CD	Date/Time	6/3/2016 10:29 AM

NAME OF PERSON ALLOWING ENTRY: William — CONFIRM OVER 18 YRS: Yes

BASEMENT: Yes

WATER IN BASEMENT: No — EXPERIENCED SEWER BACKUP/FLOODING IN BASEMENT?

TYPE OF BASEMENT FLOOR: Carpet — No

SUMP PUMP

SUMP PUMP	No	HORSEPOWER OF PUMP	
DISCHARGE LOCATION		PUMP CAPACITY(gpm)	
SUMP PIPE HARD PIPED		FREQUENCY OF CYCLING	
DRAINAGE AREA (sf)		IS PUMP ALWAYS ADEQUATE	

** IF ILLEGAL SUMP PUMP FOUND** HOW OFTEN DOES IT RUN?

FLOOR DRAIN INFO

FLOOR DRAIN: No — NUMBER OF DRAINS: — FREQUENCY OF USE:

DISCHARGE LOCATION — DRAINAGE AREA (sf)

FOUNDATION DRAIN INFORMATION

INTERNAL ROOF DRAIN: No — FREQUENCY OF USE:

DISCHARGE LOCATION — DISTANCE FROM SILL (top of concrete) TO INVERT OF PIPE (feet)

SEWER CONNECTION CLEANOUT

IS THERE A SEWER CLEANOUT	Yes	ELEVATION OF SEWER CONNECTION CLEANOUT	
IS THE CLEANOUT SEALED?	Yes	LOCATION	Above Basem
DRAINAGE AREA (sf)		ELEVATION (ft)	3

OTHER INFLOW SOURCES

EXTERNAL HOUSE INSPECTION: Yes

DOWNSPOUTS ENTER GROUND	Yes	DRAINAGE AREA (sf)	500
YARD DRAIN	No	DRAINAGE AREA (sf)	
DRIVEWAY DRAIN	No	DRAINAGE AREA (sf)	
WINDOW WELL DRAIN	No	DRAINAGE AREA (sf)	
OTHER DRAINS	No	DRAINAGE AREA (sf)	

EXPERIENCED PONDING ON PROPERTY DURING RAIN? No

ADDITIONAL COMMENTS:

Ejector pump

Finished basement

EST
Associates, Inc.

Environmental Monitoring
Pipeline Services
Operations & Maintenance

Date 6-3-16 Project 17 Victor Initial CD



51 Fremont Street, Needham, MA 02494 • Tel: (781) 455-0003 Fax: (781) 455-8336
www.estassociates.com