

## **LIST OF APPENDICES**

### **APPENDIX A – TECHNICAL MEMORANDUM NO. 1: DYED WATER TESTING AND TRACING (OCTOBER 27, 2016)**

Attachment A – Stacey DePasquale Engineering, Inc. - Dye Testing Report CD (February 29, 2016)  
Attachment B – EST Associates, Inc. - Dye Flooding Report  
Disc 1 – EST Associates, Inc. - Dye Flooding Report (July 2016)  
Disc 2 – EST Associates, Inc. - Dye Flooding with CCTV Inspections (July 14, 2016)  
Disc 3 – EST Associates, Inc. - Dye Flooding with CCTV Inspections (July 15, 2016)  
Disc 4 – EST Associates, Inc. - Dye Flooding with CCTV Inspections (July 18, 2016)

### **APPENDIX B – TECHNICAL MEMORANDUM NO. 2: INTERNAL CCTV INSPECTION OF SELECTED MAINLINE SEWERS AND LATERAL SERVICE CONNECTIONS (NOVEMBER 17, 2016)**

Attachment A – National Water Main Cleaning Company, Mainline and Lateral CCTV Inspection  
Report  
Disc 1 – NWMCC CCTV Inspections – Rev. 1  
Disc 2 – NWMCC CCTV Inspections – Rev. 2

### **APPENDIX C – TECHNICAL MEMORANDUM NO. 3: MANHOLE INSPECTIONS (DECEMBER 21, 2016)**

Attachment A – Dye Flooding Data  
EST Associates, Inc. – Dye Flooding Report (November 16, 2016)  
EST Associates, Inc. – Manhole Inspection Report – Book 1  
EST Associates, Inc. – Manhole Inspection Report – Book 2  
EST Associates, Inc. – Manhole Inspection Report – Book 3  
EST Associates, Inc. – Manhole Inspection Report – Book 4  
EST Associates, Inc. – Manhole Inspection Report – Book 5  
EST Associates, Inc. – Manhole Inspection Report – Book 6

### **APPENDIX D – TECHNICAL MEMORANDUM NO. 4: HOUSE TO HOUSE INSPECTIONS (DECEMBER 21, 2016)**

Attachment A – Building Inspection Reports  
EST Associates, Inc. – Subarea 1 Building Inspection Report  
EST Associates, Inc. – Subarea 2 Building Inspection Report  
EST Associates, Inc. – Subarea 3 Building Inspection Report  
EST Associates, Inc. – Subarea 4 Building Inspection Report  
EST Associates, Inc. – Subarea 5 Building Inspection Report  
EST Associates, Inc. – Subarea 6 Building Inspection Report  
EST Associates, Inc. – Subarea NA Building Inspection Report

### **APPENDIX E – DRAFT INFLOW CONTROL PLAN (JANUARY 26, 2016)**

### **APPENDIX F – ROUTE 7 WWTF NPDES PERMIT (SEPTEMBER 17, 2014)**

### **APPENDIX G – SOUTH STREET WWTF NPDES PERMIT (SEPTEMBER 29, 2015)**

### **APPENDIX H – PHASE 2 WASTEWATER FACILITIES PLAN – WWTF CONDITION ASSESSMENTS (MARCH 2, 2016)**

Highlighted items in yellow have not been included in the posted website material due to either large file sizes or PDF incompatibility. These materials can be reviewed at the office of the WPCA upon request.